

## Facility Summary in Garfield County in the City of Jordan

**Location:** FARMERS UNION OIL CO JORDAN  
201 Jordan Ave  
Jordan, MT 59337 Garfield

System Facility ID:17-05702

**Facility Code:** 21878  
**Last Inspected On:** 02/17/2023  
**Operating Permit Renewal Date:** 08/19/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Farmers Union Oil Co Jordan (406) 557-2215 cenexjor@midrivers.com

---

**Operator Contact:** Robert Wilson (406) 557-2218 cenexjor@midrivers.com

---

**Owner/Operator:** Farmers Union Oil Co Jordan (406) 557-2215 cenexjor@midrivers.com

Loren Edwards, UST Class B Global Operator      edwards\_loren@yahoo.com  
Robert Wilson, UST Class A Operator      cenexjor@midrivers.com

<b>Tank Code</b>	06	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	941	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>	09/18/2024	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/23/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/18/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>	Franklin Fueling Systems/				
<b>Tank Code</b>	07	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	942	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>	10/02/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/11/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4100	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>					
<b>Tank Code</b>	08	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve

<b>Tag Number</b>	943	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/11/2022	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Not Listed	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4100	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>					
<b>Tank Code</b>	09	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	944	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>	10/02/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/11/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	3760	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>					
<b>Tank Code</b>	10	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	945	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>	06/03/2011	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/11/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7900	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>					
<b>Tank Code</b>	11	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	946	<b>Spill Test Date</b>	02/17/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/11/2022	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Not Listed	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/30/2008	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4100	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/17/2023			<b>ATG Type</b>					

### Facility Summary in Garfield County in the City of Jordan

**Location:** FARMERS UNION OIL CO JORDAN 2  
40 Brusett Rd  
Jordan, MT 59337 Garfield

System Facility ID:60-15243

**Facility Code:** 30960  
**Last Inspected On:** 02/17/2023  
**Operating Permit Renewal Date:** 07/05/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Farmers Union Oil Co Jordan (406) 557-2215 cenexjor@midrivers.com

---

**Operator Contact:** Robert Wilson (406) 557-2218 cenexjor@midrivers.com

---

**Owner/Operator:** Farmers Union Oil Co Jordan (406) 557-2215 cenexjor@midrivers.com

Loren Edwards, UST Class B Global Operator      edwards\_loren@yahoo.com  
Robert Wilson, UST Class A Operator      cenexjor@midrivers.com

<b>Tank Code</b>	S1	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	10/28/2014	<b>Tank Material</b>	Aboveground Tank	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5498	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/28/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/02/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S2	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	10/28/2014	<b>Tank Material</b>	Aboveground Tank	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5499	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/28/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/02/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S3	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	10/28/2014	<b>Tank Material</b>	Aboveground Tank	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	

<b>Tag Number</b>	5500	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/28/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/02/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/26/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Garfield County in the City of Jordan**

**Location:** JAKES PLACE  
618 Jordan Ave  
Jordan, MT 59337 Garfield

System Facility ID:17-10707

**Facility Code:** 21895  
**Last Inspected On:** 08/07/2023  
**Operating Permit Renewal Date:** 11/16/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jakes Property Investments LLC (406) 853-1732 skylarharbaugh@hotmail.com

**Operator Contact:** Kenneth Ellington;Rex Phipps;Skylar Harbaugh (406) 557-2201;(406) 853-1732 kellington@midrivers.com;rex@garfieldcountybank.com;skylarharbaugh@hotmail.com

**Owner/Operator:** Jakes Property Investments LLC (406) 853-1732 skylarharbaugh@hotmail.com

- |  |                            |
|--|----------------------------|
| Kenneth Ellington, UST Class A Operator      | kellington@midrivers.com   |
| Kenneth Ellington, UST Class A Operator      | kellington@midrivers.com   |
| Kenneth Ellington, UST Class B Operator      | kellington@midrivers.com   |
| Kenneth Ellington, UST Class B Operator      | kellington@midrivers.com   |
| Rex Phipps, UST Class A Operator             | rex@garfieldcountybank.com |
| Rex Phipps, UST Class A Operator             | rex@garfieldcountybank.com |
| Rex Phipps, UST Class B Operator             | rex@garfieldcountybank.com |
| Rex Phipps, UST Class B Operator             | rex@garfieldcountybank.com |
| Skylar Harbaugh, UST Class A Operator        | skylarharbaugh@hotmail.com |
| Skylar Harbaugh, UST Class A Operator        | skylarharbaugh@hotmail.com |
| Skylar Harbaugh, UST Class B Global Operator | skylarharbaugh@hotmail.com |
| Skylar Harbaugh, UST Class B Global Operator | skylarharbaugh@hotmail.com |

<b>Tank Code</b>	05	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4311	<b>Spill Test Date</b>	08/07/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/17/2013	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	08/07/2023	<b>Line Tightness Test Date</b>	08/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/07/2023			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	06	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm

<b>Tag Number</b>	4312	<b>Spill Test Date</b>	08/07/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/17/2013	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	08/07/2023	<b>Line Tightness Test Date</b>	08/27/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/07/2023			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	07	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4313	<b>Spill Test Date</b>	08/07/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/17/2013	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	08/07/2023	<b>Line Tightness Test Date</b>	08/23/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/07/2023			<b>ATG Type</b>	Incon/TS-550 EVO				