

**Facility Summary in Missoula County in the City of Bonner**

**Location:** POTOMAC BAR AND COUNTRY STORE  
29344 MT Hwy 200 E  
Bonner, MT 59823-9526 Missoula

System Facility ID:32-12400

**Facility Code:** 25677  
**Last Inspected On:** 03/04/2023  
**Operating Permit Renewal Date:** 04/19/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Kenney Brown;Potomac Bar and Country Store, Inc;Potomac Bar and Country Store, Inc (406) 240-3863;(406) 240-3863;(406) 240-3863 kennybrown@blackfoot.net;kennybrown@blackfoot.net;kennybrown@blackfoot.net

**Operator Contact:** Christine Yednick potomacbar@outlook.com

**Owner/Operator:** Kenney Brown,Potomac Bar and Country Store, Inc (406) 240-3863 kennybrown@blackfoot.net

**Owner/Operator:** Potomac Bar and Country Store, Inc (406) 240-3863 kennybrown@blackfoot.net  
Christine Yednick, UST Class A Operator potomacbar@outlook.com  
Christine Yednick, UST Class B Operator potomacbar@outlook.com

<b>Tank Code</b>	01	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	05/28/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3488	<b>Spill Test Date</b>	06/10/2020	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/09/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	03/04/2023	<b>Line Tightness Test Date</b>	11/06/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/10/2020			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	02	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	05/28/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3489	<b>Spill Test Date</b>	06/10/2020	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/09/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	03/04/2023	<b>Line Tightness Test Date</b>	11/06/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/10/2020			<b>ATG Type</b>	Gilbarco/EMC Basic				

<b>Tank Code</b>	03	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	05/28/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3490	<b>Spill Test Date</b>	06/10/2020	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/09/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	03/04/2023	<b>Line Tightness Test Date</b>	11/06/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/10/2020			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	04	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	05/28/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve; Flapper Valve
<b>Tag Number</b>	3491	<b>Spill Test Date</b>	06/10/2020	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/09/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	3000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/20/2010	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/10/2020			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Clinton**

**Location:** BEARMOUTH EXPRESS  
16595 US Hwy 10 E  
Clinton, MT 59825-9678 Missoula

System Facility ID:32-01572

**Facility Code:** 25223  
**Last Inspected On:** 07/20/2022  
**Operating Permit Renewal Date:** 11/12/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Gene Tripp (406) 825-4000

**Operator Contact:** Bryan Tripp;Jeff Tripp (406) 825-4000 bearmouth66@blackfoot.net;bryan.tripp44@gmail.com

**Owner/Operator:** Gene Tripp (406) 825-4000

Bryan Tripp, UST Class A Operator  
Bryan Tripp, UST Class B Operator  
Jeff Tripp, UST Class A Operator  
Jeff Tripp, UST Class B Operator

bryan.tripp44@gmail.com  
bryan.tripp44@gmail.com  
bearmouth66@blackfoot.net  
bearmouth66@blackfoot.net

<b>Tank Code</b>	01	<b>Tank Age</b>	46	<b>Tank Installed Date</b>	04/29/1979	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1205	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>					

## Facility Summary in Missoula County in the City of Clinton

**Location:** CLINTON MARKET  
20500 Hwy 10 E  
Clinton, MT 59825 Missoula

System Facility ID:56-14040

**Facility Code:** 30695  
**Last Inspected On:** 11/19/2024  
**Operating Permit Renewal Date:** 04/09/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** RR Investments of Montana (406) 546-4940 roy.handley6543@gmail.com

---

**Operator Contact:** Roy Handley (406) 546-4940 roy.handley6543@gmail.com

---

**Owner/Operator:** RR Investments of Montana (406) 546-4940 roy.handley6543@gmail.com

Roy Handley, UST Class A Operator roy.handley6543@gmail.com  
Roy Handley, UST Class B Global Operator roy.handley6543@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	05/16/2002	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4651	<b>Spill Test Date</b>	05/17/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/17/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/19/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/19/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/17/2024			<b>ATG Type</b>	Gilbarco/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	05/16/2002	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4652	<b>Spill Test Date</b>	05/17/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/17/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/19/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/19/2024	<b>Line Tightness Test Date</b>	02/26/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/17/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	03	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	05/16/2002	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4653	<b>Spill Test Date</b>	05/17/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/17/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/19/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	11/19/2024	<b>Line Tightness Test Date</b>	02/28/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/17/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	04	<b>Tank Age</b>	16	<b>Tank Installed Date</b>	10/29/2009	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5223	<b>Spill Test Date</b>	05/17/2024	<b>Piping Installed Date</b>	10/14/2009	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/17/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/19/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/19/2024	<b>Line Tightness Test Date</b>	02/26/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/17/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	05	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	08/28/2018	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5851	<b>Spill Test Date</b>	05/17/2024	<b>Piping Installed Date</b>	08/28/2018	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/17/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/19/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/19/2024	<b>Line Tightness Test Date</b>	02/26/2019	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	05/17/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Clinton**

**Location:** ROCK CREEK LODGE  
7 Rock Creek Rd  
Clinton, MT 59825 Missoula

System Facility ID:32-11093

**Facility Code:** 25616  
**Last Inspected On:** 01/05/2024  
**Operating Permit Renewal Date:** 01/08/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Nicholas Caras;SEVEN ROCK LLC (406) 203-4467;(406) 203-4467 nickcaras@gmail.com;sjw@cararealestate.com

**Operator Contact:**

**Owner/Operator:** Nicholas Caras,SEVEN ROCK LLC (406) 203-4467 nickcaras@gmail.com

<b>Tank Code</b>	03	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	05/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4572	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.1;Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-300				
<b>Tank Code</b>	04	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	05/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4573	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/20/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Condon**

**Location:** MISSION MOUNTAINS MERCANTILE  
7217 MT Hwy 83  
Condon, MT 59826 Missoula

System Facility ID:32-01619

**Facility Code:** 25226  
**Last Inspected On:** 04/12/2023  
**Operating Permit Renewal Date:** 06/10/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Leonard Kobylenski (406) 754-2387 len@swanvalley.com

---

**Operator Contact:** Leonard Kobylenski (406) 754-2387 len@swanvalley.com

---

**Owner/Operator:** Len Kobylenski (406) 754-2387 len@swanvalley.com  
 Len Kobylenski, UST Class A Operator len@swanvalley.com  
 Len Kobylenski, UST Class A Operator len@swanvalley.com  
 Len Kobylenski, UST Class B Operator len@swanvalley.com  
 Len Kobylenski, UST Class B Operator len@swanvalley.com

<b>Tank Code</b>	04	<b>Tank Age</b>	33	<b>Tank Installed Date</b>	05/20/1992	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1495	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/12/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	04/12/2023	<b>Line Tightness Test Date</b>	04/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	05	<b>Tank Age</b>	33	<b>Tank Installed Date</b>	05/20/1992	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1496	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/12/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/12/2023	<b>Line Tightness Test Date</b>	04/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

<b>Tank Code</b>	06	<b>Tank Age</b>	33	<b>Tank Installed Date</b>	05/20/1992	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1497	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/12/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/12/2023	<b>Line Tightness Test Date</b>	04/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				



**Facility Summary in Missoula County in the City of Frenchtown**

**Location:** BRONCS GROCERIES INC  
16640 Beckwith St  
Frenchtown, MT 59834-9747 Missoula

System Facility ID:32-05767

**Facility Code:** 25384  
**Last Inspected On:** 11/28/2023  
**Operating Permit Renewal Date:** 03/03/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jeremy Louvar (406) 546-3656 jeremylouvar@yahoo.com

**Operator Contact:**

**Owner/Operator:** Jeremy Louvar (406) 546-3656 jeremylouvar@yahoo.com

Jeremy Louvar, UST Class B Operator jeremylouvar@yahoo.com

<b>Tank Code</b>	04	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	05/01/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	2702	<b>Spill Test Date</b>	05/30/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	05/06/2024	<b>Line Tightness Test Date</b>	05/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/06/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	05/01/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	2703	<b>Spill Test Date</b>	05/30/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	05/06/2024	<b>Line Tightness Test Date</b>	05/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/06/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Frenchtown**

**Location:** FRENCHIES  
16875 Beckwith St  
Frenchtown, MT 59834-9646 Missoula

System Facility ID:32-11177

**Facility Code:** 25623  
**Last Inspected On:** 05/22/2024  
**Operating Permit Renewal Date:** 11/01/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

**Operator Contact:** Alivia Moseman;Joe Heuchert;Karly Shafer (406) 396-2206 amoseman19@gmail.com;dahoyk@yahoo.com;karly@gwpetrol.com

**Owner/Operator:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

Alivia Moseman, UST Class A Operator amoseman19@gmail.com  
Alivia Moseman, UST Class B Global Operator amoseman19@gmail.com  
Joe Heuchert, UST Class A Operator dahoyk@yahoo.com  
Karly Shafer, UST Class A Operator karly@gwpetrol.com  
Karly Shafer, UST Class B Global Operator karly@gwpetrol.com

<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	06/25/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4372	<b>Spill Test Date</b>	11/09/2023	<b>Piping Installed Date</b>	11/20/2023	<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/18/2022	<b>Sump Tightness Test Date</b>	11/13/2023	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/09/2023	<b>Line Tightness Test Date</b>	12/30/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/09/2023			<b>ATG Type</b>	Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	06	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	06/25/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4373	<b>Spill Test Date</b>	11/09/2023	<b>Piping Installed Date</b>	11/20/2023	<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/18/2022	<b>Sump Tightness Test Date</b>	11/13/2023	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/09/2023	<b>Line Tightness Test Date</b>	12/30/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	11/09/2023			<b>ATG Type</b>	Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	07	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	06/25/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4374	<b>Spill Test Date</b>	11/09/2023	<b>Piping Installed Date</b>	11/20/2023	<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/18/2022	<b>Sump Tightness Test Date</b>	11/13/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/09/2023	<b>Line Tightness Test Date</b>	12/30/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/18/2022			<b>ATG Type</b>	Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	08	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	06/25/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4375	<b>Spill Test Date</b>	11/09/2023	<b>Piping Installed Date</b>	11/20/2023	<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/18/2022	<b>Sump Tightness Test Date</b>	11/13/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/09/2023	<b>Line Tightness Test Date</b>	12/30/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/18/2022			<b>ATG Type</b>	Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	09	<b>Tank Age</b>	2	<b>Tank Installed Date</b>	11/16/2023	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	6209	<b>Spill Test Date</b>	11/09/2023	<b>Piping Installed Date</b>	11/20/2023	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	11/13/2023	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/09/2023	<b>Line Tightness Test Date</b>	12/30/2023	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	11/09/2023			<b>ATG Type</b>					

### Facility Summary in Missoula County in the City of Greenough

**Location:** CLEARWATER STOP N GO  
44676 MT Hwy 200 E  
Greenough, MT 59823-9557 Missoula

System Facility ID:32-07114

**Facility Code:** 25422  
**Last Inspected On:** 03/27/2025  
**Operating Permit Renewal Date:** 06/24/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** The Cow Group (406) 396-8431 jjross9185@msn.com

---

**Operator Contact:** Jeff Stavish;Sherri Housley (406) 244-5598 clearwaterstopngo@gmail.com;jjross9185@msn.com

---

**Owner/Operator:** The Cow Group (406) 396-8431 jjross9185@msn.com

Jeff Stavish, UST Class A Operator clearwaterstopngo@gmail.com  
 Jeff Stavish, UST Class B Global Operator clearwaterstopngo@gmail.com  
 Sherri Housley, UST Class A Operator jjross9185@msn.com  
 Sherri Housley, UST Class B Operator jjross9185@msn.com

<b>Tank Code</b>	04	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	04/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4474	<b>Spill Test Date</b>	10/12/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	03/18/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/18/2022	<b>Line Tightness Test Date</b>	03/18/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/12/2021			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	04/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4475	<b>Spill Test Date</b>	10/12/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	03/18/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	03/18/2022	<b>Line Tightness Test Date</b>	03/18/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/12/2021			<b>ATG Type</b>	Gilbarco/EMC Basic				

<b>Tank Code</b>	06	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	04/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4476	<b>Spill Test Date</b>	10/12/2021	<b>Piping Installed Date</b>	03/19/2018	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	03/18/2022	<b>Sump Tightness Test Date</b>	08/12/2022	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/18/2022	<b>Line Tightness Test Date</b>	03/18/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/12/2021			<b>ATG Type</b>	Gilbarco/EMC Basic				

### Facility Summary in Missoula County in the City of Lolo

**Location:** LOLO SUPERSTOP  
12011 US Hwy 93 S  
Lolo, MT 59847-9666 Missoula

System Facility ID:56-13795

**Facility Code:** 30482  
**Last Inspected On:** 06/30/2022  
**Operating Permit Renewal Date:** 10/03/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

---

**Operator Contact:** Bri Mader;Karly Shafer (406) 396-2206 karly@gwpetrol.com;knotts.brianna@yahoo.com

---

**Owner/Operator:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

Bri Mader, UST Class A Operator knotts.brianna@yahoo.com  
Bri Mader, UST Class B Operator knotts.brianna@yahoo.com  
Karly Shafer, UST Class A Operator karly@gwpetrol.com  
Karly Shafer, UST Class B Global Operator karly@gwpetrol.com

<b>Tank Code</b>	05	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	01/15/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2086	<b>Spill Test Date</b>	06/30/2022	<b>Piping Installed Date</b>	12/01/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/30/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/15/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	06/15/2022	<b>Line Tightness Test Date</b>	04/27/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	06	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	01/15/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2087	<b>Spill Test Date</b>	06/30/2022	<b>Piping Installed Date</b>	12/01/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/30/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/15/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	06/15/2022	<b>Line Tightness Test Date</b>	05/01/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	07	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	01/15/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2088	<b>Spill Test Date</b>	06/30/2022	<b>Piping Installed Date</b>	12/01/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/30/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>	06/15/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	06/15/2022	<b>Line Tightness Test Date</b>	05/07/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	08	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	01/15/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2089	<b>Spill Test Date</b>	06/30/2022	<b>Piping Installed Date</b>	12/01/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/30/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/15/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/15/2022	<b>Line Tightness Test Date</b>	05/07/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	09	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	01/15/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2090	<b>Spill Test Date</b>	06/30/2022	<b>Piping Installed Date</b>	12/01/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/30/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/15/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/15/2022	<b>Line Tightness Test Date</b>	05/01/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Lolo**

**Location:** TOWN PUMP INC LOLO 1  
10955 US Hwy 93 S  
Lolo, MT 59847 Missoula

System Facility ID:32-09414

**Facility Code:** 25493  
**Last Inspected On:** 03/31/2023  
**Operating Permit Renewal Date:** 11/01/2024

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Lolo 1 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

**Operator Contact:** Trent Biggers

**Trentb@townpump.com**

**Owner/Operator:** Lolo 1 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

Trent Biggers, UST Class A Operator  
Trent Biggers, UST Class A Operator  
Trent Biggers, UST Class B Global Operator  
Trent Biggers, UST Class B Global Operator

Trentb@townpump.com  
Trentb@townpump.com  
Trentb@townpump.com  
Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	07/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2555	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	12/06/2018	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	24000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	02	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	07/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2556	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	12/06/2018	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	24000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					



<b>Tank Code</b>	03	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	07/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2557	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	12/06/2018	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	24000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	04	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	07/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2558	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	12/06/2018	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	24000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	05	<b>Tank Age</b>	4	<b>Tank Installed Date</b>	04/20/2021	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6029	<b>Spill Test Date</b>	07/19/2022	<b>Piping Installed Date</b>	04/20/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/19/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/24/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	20000	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>	05/04/2021	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/19/2022			<b>ATG Type</b>					
<b>Tank Code</b>	06	<b>Tank Age</b>	4	<b>Tank Installed Date</b>	04/20/2021	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6030	<b>Spill Test Date</b>	07/19/2022	<b>Piping Installed Date</b>	04/20/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/19/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/24/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes

<b>Capacity</b>	15000	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>	05/04/2021	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/19/2022			<b>ATG Type</b>					
<b>Tank Code</b>	07	<b>Tank Age</b>	4	<b>Tank Installed Date</b>	04/20/2021	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6031	<b>Spill Test Date</b>	07/19/2022	<b>Piping Installed Date</b>	04/20/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/19/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/24/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	7000	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>	05/04/2021	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/19/2022			<b>ATG Type</b>					
<b>Tank Code</b>	08	<b>Tank Age</b>	4	<b>Tank Installed Date</b>	04/20/2021	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6032	<b>Spill Test Date</b>	07/19/2022	<b>Piping Installed Date</b>	04/20/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/19/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/24/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>	05/04/2021	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/19/2022			<b>ATG Type</b>					
<b>Tank Code</b>	09	<b>Tank Age</b>	4	<b>Tank Installed Date</b>	04/20/2021	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6033	<b>Spill Test Date</b>	03/10/2021	<b>Piping Installed Date</b>	04/20/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/10/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	05/04/2021	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/02/2021			<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Lolo**

**Location:** TOWN PUMP INC LOLO 2  
11880 US HWY 93 S, STE 1  
Lolo, MT 59847 Missoula

System Facility ID:32-01639

**Facility Code:** 25228  
**Last Inspected On:** 03/31/2023  
**Operating Permit Renewal Date:** 10/22/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Lolo 2 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

**Operator Contact:** Trent Biggers

**Trentb@townpump.com**

**Owner/Operator:** Lolo 2 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

Trent Biggers, UST Class A Operator  
Trent Biggers, UST Class A Operator  
Trent Biggers, UST Class B Global Operator  
Trent Biggers, UST Class B Global Operator

Trentb@townpump.com  
Trentb@townpump.com  
Trentb@townpump.com  
Trentb@townpump.com

<b>Tank Code</b>	13	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2545	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	14	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2546	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	17	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2549	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>	08/11/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	18	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2550	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	15	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4289	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	16	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve

<b>Tag Number</b>	4290	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>	08/11/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>	12/05/2012	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	20	<b>Tank Age</b>	21	<b>Tank Installed Date</b>	09/15/2004	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4942	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	21	<b>Tank Age</b>	21	<b>Tank Installed Date</b>	09/15/2004	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4943	<b>Spill Test Date</b>	07/20/2022	<b>Piping Installed Date</b>	08/11/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/03/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	03/23/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Lolo**

**Location:** TRAVELERS REST  
10565 Lolo Creek Rd  
Lolo, MT 59847-9471 Missoula

System Facility ID:32-11303

**Facility Code:** 25632  
**Last Inspected On:** 09/26/2024  
**Operating Permit Renewal Date:** 12/12/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Manpreet Singh (509) 994-6599 sbsm065@gmail.com

**Operator Contact:** Emily Day;Jeffrey Toole histar.jeff@gmail.com;Travelersrestlolo@gmail.com

**Owner/Operator:** Manpreet Singh (509) 994-6599 sbsm065@gmail.com  
 Emily Day, UST Class A Operator Travelersrestlolo@gmail.com  
 Jeffrey Toole, UST Class A Operator histar.jeff@gmail.com  
 Jeffrey Toole, UST Class B Operator histar.jeff@gmail.com

<b>Tank Code</b>	S4	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	08/13/2003	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4854	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	09/26/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	09/26/2024	<b>Line Tightness Test Date</b>	09/26/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	S5	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	08/13/2003	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4855	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	09/26/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	09/26/2024	<b>Line Tightness Test Date</b>	09/26/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	S6	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	06/23/2003	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4856	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	09/26/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	09/26/2024	<b>Line Tightness Test Date</b>	09/26/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	S7	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	06/23/2003	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4857	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	09/26/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	09/26/2024	<b>Line Tightness Test Date</b>	09/26/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	S8	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	06/23/2003	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4858	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	09/26/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	09/26/2024	<b>Line Tightness Test Date</b>	09/26/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Milltown**

**Location:** TOWN PUMP INC BONNER-MILLTOWN  
7985 MT Hwy 200 E  
Milltown, MT 59851 Missoula

System Facility ID:32-13629

**Facility Code:** 25772  
**Last Inspected On:** 03/30/2023  
**Operating Permit Renewal Date:** 11/03/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Bonner Town Pump and Casino Inc

**(406) 497-6700**

**environmental@townpump.com**

**Operator Contact:** Trent Biggers

**Trentb@townpump.com**

**Owner/Operator:** Bonner Town Pump and Casino Inc

**(406) 497-6700**

**environmental@townpump.com**

Trent Biggers, UST Class A Operator

Trentb@townpump.com

Trent Biggers, UST Class B Global Operator

Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2564	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	05	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2568	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				



<b>Tank Code</b>	07	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2570	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	08	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2571	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	09	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2572	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	11	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2574	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	02	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4260	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	03	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4261	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	04	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4262	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/13/2006	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/17/2023	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No

<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	06	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4263	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	12	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	12/03/2003	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4871	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	13	<b>Tank Age</b>	22	<b>Tank Installed Date</b>	12/03/2003	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4872	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

<b>Tank Code</b>	10	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	09/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4889	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	10/17/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	14	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	06/01/2013	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5363	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	07/12/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Other	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring;Deferred	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring;Deferred	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	15	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	01/01/2018	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Positive Shutoff
<b>Tag Number</b>	5802	<b>Spill Test Date</b>	06/06/2022	<b>Piping Installed Date</b>	12/22/2017	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/07/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/09/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	30000	<b>ATG Test Date</b>	03/17/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	06/06/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** 3RD STREET MART  
2340 S 3rd St W  
Missoula, MT 59801 Missoula

System Facility ID:32-02179

**Facility Code:** 25246  
**Last Inspected On:** 06/22/2022  
**Operating Permit Renewal Date:** 08/28/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jays Corporation

polsonbay@yahoo.com

**Operator Contact:** Jagpreet Ghuman;Jaspal Sandhu;Jays Corporation

(406) 880-7677

jas\_sandhu75@hotmail.com;polsonbay@yahoo.com;jaysfood08@outlook.com

**Owner/Operator:** Jays Corporation

polsonbay@yahoo.com

Jagpreet Ghuman, UST Class A Operator  
Jagpreet Ghuman, UST Class B Operator  
Jaspal Sandhu, UST Class A Operator  
Jaspal Sandhu, UST Class B Operator

jaysfood08@outlook.com  
jays1stop21@outlook.com  
polsonbay@yahoo.com  
polsonbay@yahoo.com

<b>Tank Code</b>	01	<b>Tank Age</b>	49	<b>Tank Installed Date</b>	04/23/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3624	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/17/2022	<b>Tank/Piping CP Test Date</b>	04/13/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	01/17/2022	<b>Line Tightness Test Date</b>	04/01/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/17/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	49	<b>Tank Installed Date</b>	04/23/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3625	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/17/2022	<b>Tank/Piping CP Test Date</b>	04/13/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	01/17/2022	<b>Line Tightness Test Date</b>	04/07/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	01/17/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	03	<b>Tank Age</b>	49	<b>Tank Installed Date</b>	04/23/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3626	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	01/17/2022	<b>Tank/Piping CP Test Date</b>	04/13/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	01/17/2022	<b>Line Tightness Test Date</b>	10/11/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/17/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** 70 Mile Super Stop 2  
930 N Russell St  
Missoula, MT 59808 Missoula

System Facility ID:32-13472

**Facility Code:** 25751  
**Last Inspected On:** 01/04/2024  
**Operating Permit Renewal Date:** 01/06/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Hi-Star Properties LLC

histarms3@yahoo.com

**Operator Contact:**

**Owner/Operator:** Hi-Star Properties LLC

histarms3@yahoo.com

<b>Tank Code</b>	01	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	06/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1450	<b>Spill Test Date</b>	10/23/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	10/23/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/04/2011	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	10/23/2023	<b>Line Tightness Test Date</b>	10/23/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/28/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	06/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1451	<b>Spill Test Date</b>	02/28/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	10/23/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/04/2011	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/23/2023	<b>Line Tightness Test Date</b>	10/23/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	06/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve

<b>Tag Number</b>	1452	<b>Spill Test Date</b>	02/28/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	10/23/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/04/2011	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	10/23/2023	<b>Line Tightness Test Date</b>	10/23/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/28/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				



**Facility Summary in Missoula County in the City of Missoula**

**Location:** AIRWAY FLEET FUEL  
5355 W Harrier  
Missoula, MT 59808 Missoula

System Facility ID:56-14133

**Facility Code:** 30771  
**Last Inspected On:** 01/17/2023  
**Operating Permit Renewal Date:** 02/18/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Finest Oil Co (406) 543-6969

**Operator Contact:** Christopher Glasser;James Brady;John Stordahl;Justin Gaudot;Stephen Hanson (406) 218-1563;(406) 543-6969;(406) 544-1005;(714) 333-8926  
chrisglasser@hotmail.com;finestoil@finest-oil.com;fireman2201@msn.com;jeepin247.jb@gmail.com;justgaudot@yahoo.com

**Owner/Operator:** Finest Oil Co (406) 543-6969

Christopher Glasser, UST Class A Operator	chrisglasser@hotmail.com
James Brady, UST Class A Operator	jeepin247.jb@gmail.com
John Stordahl, UST Class A Operator	fireman2201@msn.com
Joseph McClain, UST Class B Operator	jgmcclain25@gmail.com
Justin Gaudot, UST Class A Operator	justgaudot@yahoo.com
Justin Gaudot, UST Class B Global Operator	justgaudot@yahoo.com
Stephen Hanson, UST Class A Operator	finestoil@finest-oil.com
Stephen Hanson, UST Class B Operator	finestoil@finest-oil.com

<b>Tank Code</b>	01	<b>Tank Age</b>	20	<b>Tank Installed Date</b>	04/05/2005	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4904	<b>Spill Test Date</b>	01/16/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/19/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	12/20/2022	<b>Line Tightness Test Date</b>	06/12/2013	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/19/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	20	<b>Tank Installed Date</b>	04/05/2005	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4905	<b>Spill Test Date</b>	12/19/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/19/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	12/20/2022	<b>Line Tightness Test Date</b>	06/12/2013	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/19/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	20	<b>Tank Installed Date</b>	04/05/2005	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4906	<b>Spill Test Date</b>	12/19/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>	12/19/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	12/20/2022	<b>Line Tightness Test Date</b>	06/12/2013	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/19/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	04	<b>Tank Age</b>	20	<b>Tank Installed Date</b>	04/05/2005	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	4907	<b>Spill Test Date</b>	12/19/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/19/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	25000	<b>ATG Test Date</b>	12/20/2022	<b>Line Tightness Test Date</b>	06/12/2013	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/19/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	05	<b>Tank Age</b>	20	<b>Tank Installed Date</b>	04/05/2005	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5038	<b>Spill Test Date</b>	12/19/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/19/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	12/20/2022	<b>Line Tightness Test Date</b>	06/12/2013	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	12/19/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
--	--	---------------------------	------------	--	--	-----------------	--	--	--	--	--

**Facility Summary in Missoula County in the City of Missoula**

**Location:** ALLIED WASTE SERVICES OF NORTH AMERICA LLC  
1501 Rodgers St  
Missoula, MT 59802-1735 Missoula

System Facility ID:32-09872

**Facility Code:** 25524  
**Last Inspected On:** 07/15/2020  
**Operating Permit Renewal Date:** 08/30/2023

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Allied Waste Services of North America LLC (406) 543-3157

**Operator Contact:** David Seeberger (406) 543-3157 dseeberger@republicservices.com

David Seeberger, UST Class A Operator

dseeberger@republicservices.com

David Seeberger, UST Class B Global Operator

dseeberger@republicservices.com

<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	01/24/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	500	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/15/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/15/2020	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	01/24/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	501	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/15/2020	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/15/2020	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	07/18/2006	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
--	--	---------------------------	--	--	-----------------	--	--	--	--	--

**Facility Summary in Missoula County in the City of Missoula**

**Location:** BEACH TRANSPORTATION CO  
825 Mount Ave  
Missoula, MT 59801-5607 Missoula

System Facility ID:32-11904

**Facility Code:** 25660  
**Last Inspected On:** 04/01/2025  
**Operating Permit Renewal Date:** 05/20/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Beach Transportation (406) 549-6121

**Operator Contact:** Carlin Cavill;Shawnae Stanton;Beach Transportation (406) 549-6121 ccavill@beachtrans.com;sstanton@beachtrans.com

**Owner/Operator:** Beach Transportation (406) 549-6121

Carlin Cavill, UST Class A Operator  
Carlin Cavill, UST Class A Operator  
Carlin Cavill, UST Class B Operator  
Carlin Cavill, UST Class B Operator  
Shawnae Stanton, UST Class A Operator  
Shawnae Stanton, UST Class B Operator

ccavill@beachtrans.com  
ccavill@beachtrans.com  
ccavill@beachtrans.com  
ccavill@beachtrans.com  
sstanton@beachtrans.com  
sstanton@beachtrans.com

<b>Tank Code</b>	03	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2361	<b>Spill Test Date</b>	04/01/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/01/2025	<b>Sump Tightness Test Date</b>	03/31/2025	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer;Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	04/01/2025	<b>Line Tightness Test Date</b>	03/03/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/01/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** BNSF MISSOULA YARD  
101 International Dr  
Missoula, MT 59808-1549 Missoula

System Facility ID:32-11226

**Facility Code:** 25626  
**Last Inspected On:** 12/04/2023  
**Operating Permit Renewal Date:** 03/27/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** BNSF Railway Helena (406) 256-4040 yueh.chuang@bnsf.com

**Operator Contact:** Devin Clary;Montana Rail Link Inc Missoula;Michael DeLozier;BNSF Railway Helena;Robert Mantle;BNSF Railway Helena (406) 256-4040;(406) 523-1500 bobmantle@hotmail.com;yueh.chuang@bnsf.com;michael.delozier@bnsf.com;yueh.chuang@bnsf.com;rshelley@mtrail.com

**Owner/Operator:** BNSF Railway Helena (406) 256-4040 yueh.chuang@bnsf.com  
 Devin Clary, UST Class A Operator rshelley@mtrail.com  
 Devin Clary, UST Class A Operator rshelley@mtrail.com  
 Devin Clary, UST Class B Operator yueh.chuang@bnsf.com  
 Michael DeLozier, UST Class A Operator yueh.chuang@bnsf.com  
 Robert Mantle, UST Class A Operator yueh.chuang@bnsf.com

<b>Tank Code</b>	S5	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	11/01/1990	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	
<b>Tag Number</b>	3872	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/01/2023	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	11/17/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** CHS MISSOULA PETROLEUM TERMINAL  
3576 Grant Creek Rd  
Missoula, MT 59808 Missoula

System Facility ID:60-15296

**Facility Code:** 31000  
**Last Inspected On:** 09/20/2022  
**Operating Permit Renewal Date:** 01/17/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** CHS Inc Laurel (406) 628-5200

**Operator Contact:** Matthew Mill (406) 721-3207 Matt.Mill@chsinc.com

**Owner/Operator:** CHS Inc Laurel (406) 628-5200

Matthew Mill, UST Class A Operator  
Matthew Mill, UST Class B Operator

Matt.Mill@chsinc.com  
Matt.Mill@chsinc.com

<b>Tank Code</b>	01	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	02/01/2008	<b>Tank Material</b>	Not Listed	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	5708	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Mixture	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/03/2022	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7750	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/22/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					



**Facility Summary in Missoula County in the City of Missoula**

**Location:** CIRCLE K STORE 2746282  
605 S Higgins Ave  
Missoula, MT 59801-2733 Missoula

System Facility ID:32-09733

**Facility Code:** 25517  
**Last Inspected On:** 05/03/2023  
**Operating Permit Renewal Date:** 08/17/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Rocky Mountain Oil LLC (602) 728-8000 NT-ESS@Circlek.com

**Operator Contact:** Veronica Rivera ESS-WestCoast@circlek.com

**Owner/Operator:** Rocky Mountain Oil LLC (602) 728-8000 NT-ESS@Circlek.com

Brad Lee, UST Class B Global Operator	brad.lee@holidaycompanies.com
Brad Lee, UST Class B Global Operator	brad.lee@holidaycompanies.com
Jeff Reed, UST Class B Global Operator	jeff.reed@holidaycompanies.com
Jeff Reed, UST Class B Global Operator	jeff.reed@holidaycompanies.com
Veronica Rivera, UST Class A Operator	ESS-WestCoast@circlek.com
Veronica Rivera, UST Class A Operator	ESS-WestCoast@circlek.com

<b>Tank Code</b>	01	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	08/01/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3028	<b>Spill Test Date</b>	05/03/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/27/2022	<b>Line Tightness Test Date</b>	06/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	08/01/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3029	<b>Spill Test Date</b>	05/03/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/27/2022	<b>Line Tightness Test Date</b>	06/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	06/27/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	08/01/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3030	<b>Spill Test Date</b>	05/03/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/27/2022	<b>Line Tightness Test Date</b>	06/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

### Facility Summary in Missoula County in the City of Missoula

**Location:** CIRCLE K STORE 2746283  
2325 S Reserve St  
Missoula, MT 59801-6446 Missoula

System Facility ID:32-09694

**Facility Code:** 25512  
**Last Inspected On:** 10/17/2023  
**Operating Permit Renewal Date:** 02/13/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Rocky Mountain Oil LLC

**(602) 728-8000**

**NT-ESS@Circlek.com**

**Operator Contact:** Veronica Rivera

**ESS-WestCoast@circlek.com**

**Owner/Operator:** Rocky Mountain Oil LLC

**(602) 728-8000**

**NT-ESS@Circlek.com**

Brad Lee, UST Class B Global Operator  
Brad Lee, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Veronica Rivera, UST Class A Operator  
Veronica Rivera, UST Class A Operator  
Veronica Rivera, UST Class A Operator

brad.lee@holidaycompanies.com  
brad.lee@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
ESS-WestCoast@circlek.com  
ESS-WestCoast@circlek.com  
ESS-WestCoast@circlek.com

<b>Tank Code</b>	01	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	08/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3706	<b>Spill Test Date</b>	11/21/2024	<b>Piping Installed Date</b>	04/10/2019	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/03/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/07/2023	<b>Tank/Piping CP Test Date</b>	06/07/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/07/2023	<b>Line Tightness Test Date</b>	07/06/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/07/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	08/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3707	<b>Spill Test Date</b>	11/21/2024	<b>Piping Installed Date</b>	04/10/2019	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/03/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/07/2023	<b>Tank/Piping CP Test Date</b>	06/07/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/07/2023	<b>Line Tightness Test Date</b>	06/14/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/07/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	08/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3708	<b>Spill Test Date</b>	04/11/2022	<b>Piping Installed Date</b>	04/10/2019	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/03/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/07/2023	<b>Tank/Piping CP Test Date</b>	06/07/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/07/2023	<b>Line Tightness Test Date</b>	06/17/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/07/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	04	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	08/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3709	<b>Spill Test Date</b>	06/22/2021	<b>Piping Installed Date</b>	04/10/2019	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/03/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/07/2023	<b>Tank/Piping CP Test Date</b>	06/07/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/07/2023	<b>Line Tightness Test Date</b>	06/13/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/07/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

### Facility Summary in Missoula County in the City of Missoula

**Location:** CIRCLE K STORE2746278  
403 S Russell St  
Missoula, MT 59801-2311 Missoula

System Facility ID:32-08072

**Facility Code:** 25460  
**Last Inspected On:** 03/25/2025  
**Operating Permit Renewal Date:** 04/23/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Rocky Mountain Oil LLC **(602) 728-8000** **NT-ESS@Circlek.com**

---

**Operator Contact:** Veronica Rivera **ESS-WestCoast@circlek.com**

---

**Owner/Operator:** Rocky Mountain Oil LLC (602) 728-8000 NT-ESS@Circlek.com

Brad Lee, UST Class B Global Operator  
Brad Lee, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Jeff Reed, UST Class B Global Operator  
Veronica Rivera, UST Class A Operator  
Veronica Rivera, UST Class A Operator

brad.lee@holidaycompanies.com  
brad.lee@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
jeff.reed@holidaycompanies.com  
ESS-WestCoast@circlek.com  
ESS-WestCoast@circlek.com

<b>Tank Code</b>	06	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	07/31/1995	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3024	<b>Spill Test Date</b>	01/06/2025	<b>Piping Installed Date</b>	06/10/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/25/2025	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	01/06/2025	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	01/06/2025	<b>Line Tightness Test Date</b>	07/25/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	07	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	07/31/1995	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3025	<b>Spill Test Date</b>	01/06/2025	<b>Piping Installed Date</b>	06/10/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/25/2025	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/06/2025	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes

<b>Capacity</b>	8000	<b>ATG Test Date</b>	01/06/2025	<b>Line Tightness Test Date</b>	07/27/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	08	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	07/31/1995	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3026	<b>Spill Test Date</b>	01/06/2025	<b>Piping Installed Date</b>	06/10/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/25/2025	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/06/2025	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	8000	<b>ATG Test Date</b>	01/06/2025	<b>Line Tightness Test Date</b>	08/02/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	09	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	07/31/1995	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4700	<b>Spill Test Date</b>	01/06/2025	<b>Piping Installed Date</b>	06/10/2021	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/25/2025	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/06/2025	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	01/06/2025	<b>Line Tightness Test Date</b>	10/13/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** COMMUNITY MEDICAL CENTER  
2827 Fort Missoula Rd  
Missoula, MT 59804 Missoula

System Facility ID:32-11740

**Facility Code:** 25652  
**Last Inspected On:** 11/29/2023  
**Operating Permit Renewal Date:** 03/08/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** RCHP Billings - Missoula LLC

cclark@communitymed.org

**Operator Contact:** Randy Allen;Community Medical Center

rallen6261@gmail.com

**Owner/Operator:** RCHP Billings - Missoula LLC

cclark@communitymed.org

Randy Allen, UST Class A Operator

rallen6261@gmail.com

Randy Allen, UST Class B Operator

rallen6261@gmail.com

<b>Tank Code</b>	04	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	07/01/1994	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2353	<b>Spill Test Date</b>	11/28/2023	<b>Piping Installed Date</b>	06/03/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/11/2024	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/05/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	11/28/2023	<b>Line Tightness Test Date</b>	11/28/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	3-Year Line Tightness Test	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/28/2023			<b>ATG Type</b>	Franklin Fueling Systems/S940				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** CORNER QWIK STOP  
2480 39th St  
Missoula, MT 59803-1123 Missoula

System Facility ID:32-09690

**Facility Code:** 25511  
**Last Inspected On:** 03/01/2023  
**Operating Permit Renewal Date:** 08/02/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Hi-Star Properties LLC

histarms3@yahoo.com

**Operator Contact:** Jagpreet Ghuman;Manpreet Singh

(406) 880-7677;(509) 994-6599

jaysfood08@outlook.com;sbsm065@gmail.com

**Owner/Operator:** Hi-Star Properties LLC

histarms3@yahoo.com

Jagpreet Ghuman, UST Class A Operator  
Jagpreet Ghuman, UST Class A Operator  
Jaspal Sandhu, UST Class B Global Operator  
Manpreet Singh, UST Class A Operator

jaysfood08@outlook.com  
jaysfood08@outlook.com  
jas\_sandhu75@hotmail.com  
sbsm065@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	43	<b>Tank Installed Date</b>	11/03/1982	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1360	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>	04/27/2018	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/08/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/22/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	43	<b>Tank Installed Date</b>	11/03/1982	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1361	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>	04/27/2018	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	12/03/2019	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes



<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/22/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	43	<b>Tank Installed Date</b>	11/03/1982	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1362	<b>Spill Test Date</b>	04/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2018	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/08/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/22/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** COSTCO WHOLESALE FUELING FACILITY  
3220 N Reserve St  
Missoula, MT 59808-1556 Missoula

System Facility ID:56-13977

**Facility Code:** 30639  
**Last Inspected On:** 07/11/2024  
**Operating Permit Renewal Date:** 07/11/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Costco Wholesale (425) 251-6222 gaslicenses@costco.com

**Operator Contact:** Brandon Krause;Sean Davis;Costco Wholesale Corporation Missoula;Shawn Willis w067gas@costco.com;w067ops@costco.com

**Owner/Operator:** Costco Wholesale (425) 251-6222 gaslicenses@costco.com

Brandon Krause, UST Class A Operator w067gas@costco.com  
Sean Davis, UST Class A Operator w067ops@costco.com  
Sean Davis, UST Class B Operator w067ops@costco.com  
Shawn Willis, UST Class A Operator w067gas@costco.com  
Shawn Willis, UST Class B Global Operator w067gas@costco.com  
Shawn Willis, UST Class B Operator w067gas@costco.com

<b>Tank Code</b>	01	<b>Tank Age</b>	25	<b>Tank Installed Date</b>	05/15/2000	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4189	<b>Spill Test Date</b>	07/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/01/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/11/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	07/10/2024	<b>Line Tightness Test Date</b>	07/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/10/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	25	<b>Tank Installed Date</b>	05/15/2000	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4190	<b>Spill Test Date</b>	07/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/01/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/11/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	20000	<b>ATG Test Date</b>	07/10/2024	<b>Line Tightness Test Date</b>	07/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/10/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	03	<b>Tank Age</b>	25	<b>Tank Installed Date</b>	05/15/2000	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4191	<b>Spill Test Date</b>	07/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/01/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/11/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	07/10/2024	<b>Line Tightness Test Date</b>	07/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/10/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	04	<b>Tank Age</b>	14	<b>Tank Installed Date</b>	08/01/2011	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5283	<b>Spill Test Date</b>	07/10/2024	<b>Piping Installed Date</b>	10/25/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/11/2024	<b>Sump Tightness Test Date</b>	06/01/2022	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Hazardous Substance	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	1500	<b>ATG Test Date</b>	07/10/2024	<b>Line Tightness Test Date</b>	07/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/10/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** DEANOS TRAVEL PLAZA 14  
5055 N Reserve St  
Missoula, MT 59808-1401 Missoula

System Facility ID:32-03610

**Facility Code:** 25301  
**Last Inspected On:** 10/24/2022  
**Operating Permit Renewal Date:** 12/21/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** DC Petroleum Inc (406) 728-6052 office.dcp@bresnan.net

**Operator Contact:** Sheri Taylor (406) 543-8885 office.dcp@gmail.com

**Owner/Operator:** DC Petroleum Inc (406) 728-6052 office.dcp@bresnan.net  
 Sheri Taylor, UST Class A Operator office.dcp@gmail.com  
 Sheri Taylor, UST Class A Operator office.dcp@gmail.com  
 Sheri Taylor, UST Class B Operator office.dcp@gmail.com  
 Sheri Taylor, UST Class B Operator office.dcp@gmail.com

<b>Tank Code</b>	06	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	04/02/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	795	<b>Spill Test Date</b>	01/06/2023	<b>Piping Installed Date</b>	06/22/2007	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	10/24/2022	<b>Tank/Piping CP Test Date</b>	10/24/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/24/2022	<b>Line Tightness Test Date</b>	07/22/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	07	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	04/02/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	796	<b>Spill Test Date</b>	01/06/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	10/24/2022	<b>Tank/Piping CP Test Date</b>	10/24/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/24/2022	<b>Line Tightness Test Date</b>	07/23/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

<b>Tank Code</b>	08	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	04/02/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	797	<b>Spill Test Date</b>	01/06/2023	<b>Piping Installed Date</b>	06/22/2007	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	10/24/2022	<b>Tank/Piping CP Test Date</b>	10/24/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/24/2022	<b>Line Tightness Test Date</b>	07/23/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	09	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	04/02/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	798	<b>Spill Test Date</b>	01/06/2023	<b>Piping Installed Date</b>	06/22/2007	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	10/24/2022	<b>Tank/Piping CP Test Date</b>	10/24/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/24/2022	<b>Line Tightness Test Date</b>	07/25/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	10	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	04/02/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	799	<b>Spill Test Date</b>	01/06/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	10/24/2022	<b>Tank/Piping CP Test Date</b>	10/24/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/24/2022	<b>Line Tightness Test Date</b>	08/22/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** DEANOS TRAVEL PLAZA II  
5318 W Harrier  
Missoula, MT 59801 Missoula

System Facility ID:60-15010

**Facility Code:** 30800  
**Last Inspected On:** 02/07/2024  
**Operating Permit Renewal Date:** 04/27/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** DC Petroleum Inc (406) 728-6052 office.dcp@bresnan.net

**Operator Contact:** Dean Clinkenbeard;Sheri Taylor (406) 543-8885 office.dcp@bresnan.net;office.dcp@gmail.com

**Owner/Operator:** DC Petroleum Inc (406) 728-6052 office.dcp@bresnan.net  
 Dean Clinkenbeard, UST Class A Operator office.dcp@bresnan.net  
 Dean Clinkenbeard, UST Class B Global Operator office.dcp@bresnan.net  
 Sheri Taylor, UST Class A Operator office.dcp@gmail.com  
 Sheri Taylor, UST Class B Operator office.dcp@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	19	<b>Tank Installed Date</b>	01/17/2006	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5027	<b>Spill Test Date</b>	01/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/17/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/17/2023	<b>Line Tightness Test Date</b>	09/10/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/10/2024			<b>ATG Type</b>	Gilbarco/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	19	<b>Tank Installed Date</b>	01/17/2006	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5028	<b>Spill Test Date</b>	01/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/17/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/17/2023	<b>Line Tightness Test Date</b>	02/07/2018	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/10/2024			<b>ATG Type</b>	Gilbarco/TLS-350				

<b>Tank Code</b>	03	<b>Tank Age</b>	19	<b>Tank Installed Date</b>	01/17/2006	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5029	<b>Spill Test Date</b>	01/10/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/17/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/17/2023	<b>Line Tightness Test Date</b>	02/07/2018	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/10/2024			<b>ATG Type</b>	Gilbarco/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** DECKER TRUCK LINE INC  
8350 Old Hwy 10  
Missoula, MT 59808 Missoula

System Facility ID:60-15231

**Facility Code:** 30948  
**Last Inspected On:** 05/23/2023  
**Operating Permit Renewal Date:** 09/01/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Decker Truck Line Inc (515) 574-4338 glawman@deckermail.com

**Operator Contact:** Liam Lederer (406) 274-7987 llederer@dtlinc.com

**Owner/Operator:** Decker Truck Line Inc (515) 574-4338 glawman@deckermail.com

Cory Jelletich, UST Class B Global Operator dagumit13@hotmail.com  
Liam Lederer, UST Class A Operator llederer@dtlinc.com  
Liam Lederer, UST Class B Global Operator llederer@dtlinc.com

<b>Tank Code</b>	01	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5438	<b>Spill Test Date</b>	11/16/2021	<b>Piping Installed Date</b>	08/30/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/12/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/16/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/16/2021	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	11/16/2021			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5439	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/25/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Other	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/09/2013	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.1;Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.1;ELLD 0.2	<b>Vapor Recovery</b>	No



<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Not Listed	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** DEMAROIS, INC  
3115 W Broadway St  
Missoula, MT 59808-1613 Missoula

System Facility ID:32-10552

**Facility Code:** 25588  
**Last Inspected On:** 11/06/2024  
**Operating Permit Renewal Date:** 01/08/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** DeMarois Inc

**Operator Contact:** Jack DeMarois

**(406) 721-4000**

**jack@demarois.com**

**Owner/Operator:** DeMarois Inc

Jack DeMarois, UST Class A Operator

jack@demarois.com

Jack DeMarois, UST Class B Operator

jack@demarois.com

<b>Tank Code</b>	03	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	11/01/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2188	<b>Spill Test Date</b>	11/08/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	12/13/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/13/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** FAST TRIP CONOCO  
2730 S Reserve St  
Missoula, MT 59801-7641 Missoula

System Facility ID:56-13914

**Facility Code:** 30584  
**Last Inspected On:** 03/28/2025  
**Operating Permit Renewal Date:** 07/02/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Scott Worster

scottoej@gmail.com

**Operator Contact:** Deb Privett

(406) 529-7771

fasttripinc@gmail.com

**Owner/Operator:** Scott Worster

scottoej@gmail.com

Deb Privett, UST Class A Operator

fasttripinc@gmail.com

Deb Privett, UST Class B Operator

fasttripinc@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	08/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4913	<b>Spill Test Date</b>	06/07/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/03/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/22/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	06/07/2022	<b>Line Tightness Test Date</b>	12/02/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/16/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	08/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4914	<b>Spill Test Date</b>	06/07/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/03/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	03/16/2023	<b>Line Tightness Test Date</b>	11/14/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	03/16/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	08/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4915	<b>Spill Test Date</b>	06/07/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/03/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	03/16/2023	<b>Line Tightness Test Date</b>	10/25/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/16/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

## Facility Summary in Missoula County in the City of Missoula

**Location:** FINEST OIL CO MISSOULA NORTHGATE  
3665 Grant Creek Rd  
Missoula, MT 59808-1431 Missoula

System Facility ID:32-02295

**Facility Code:** 25257  
**Last Inspected On:** 06/14/2023  
**Operating Permit Renewal Date:** 08/09/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Finest Oil Co (406) 543-6969

**Operator Contact:** Christopher Glasser;David Peyton;James Brady;James DeWaters;Justin Gaudot;Stephen Hanson (406) 218-1563;(406) 360-6327;(406) 543-6969;(406) 544-1005;(714) 333-8926 chrisglasser@hotmail.com;finestoil@finest-oil.com;jeepin247.jb@gmail.com;justgaudot@yahoo.com;rivban22@gmail.com

**Owner/Operator:** Finest Oil Co (406) 543-6969

Christopher Glasser, UST Class A Operator	chrisglasser@hotmail.com
David Peyton, UST Class A Operator	
David Peyton, UST Class B Global Operator	
James Brady, UST Class A Operator	jeepin247.jb@gmail.com
James DeWaters, UST Class A Operator	rivban22@gmail.com
Joseph McClain, UST Class B Operator	jgmccclain25@gmail.com
Justin Gaudot, UST Class A Operator	justgaudot@yahoo.com
Justin Gaudot, UST Class B Global Operator	justgaudot@yahoo.com
Stephen Hanson, UST Class A Operator	finestoil@finest-oil.com
Stephen Hanson, UST Class B Operator	finestoil@finest-oil.com

<b>Tank Code</b>	06	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	07/01/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1066	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/21/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	07	<b>Tank Age</b>	34	<b>Tank Installed Date</b>	07/01/1991	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1067	<b>Spill Test Date</b>	06/14/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	06/14/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	08	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1068	<b>Spill Test Date</b>	06/14/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	06/14/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	09	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1069	<b>Spill Test Date</b>	06/14/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	06/14/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	10	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1070	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	04/21/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No

<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	11	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1071	<b>Spill Test Date</b>	08/04/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	04/21/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	12	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	05/01/1994	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1072	<b>Spill Test Date</b>	08/04/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	04/21/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	13	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	05/01/1994	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1073	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/14/2023	<b>Tank/Piping CP Test Date</b>	04/21/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/18/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** FINEST OIL EASTGATE  
940 E Broadway St  
Missoula, MT 59802-4915 Missoula

System Facility ID:32-10284

**Facility Code:** 25565  
**Last Inspected On:** 05/04/2022  
**Operating Permit Renewal Date:** 09/17/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Finest Oil Co (406) 543-6969

**Operator Contact:** Christopher Glasser;David Peyton;James Brady;James DeWaters;Justin Gaudot;Stephen Hanson (406) 218-1563;(406) 360-6327;(406) 543-6969;(406) 544-1005;(714) 333-8926 chrisglasser@hotmail.com;finestoil@finest-oil.com;jeepin247.jb@gmail.com;justgaudot@yahoo.com;rivban22@gmail.com

**Owner/Operator:** Finest Oil Co (406) 543-6969

- |  |                          |
|--|--------------------------|
| Christopher Glasser, UST Class A Operator  | chrisglasser@hotmail.com |
| Christopher Glasser, UST Class A Operator  | chrisglasser@hotmail.com |
| David Peyton, UST Class A Operator         |                          |
| David Peyton, UST Class B Global Operator  |                          |
| James Brady, UST Class A Operator          | jeepin247.jb@gmail.com   |
| James Brady, UST Class A Operator          | jeepin247.jb@gmail.com   |
| James DeWaters, UST Class A Operator       | rivban22@gmail.com       |
| James DeWaters, UST Class A Operator       | rivban22@gmail.com       |
| John Stordahl, UST Class B Global Operator | fireman2201@msn.com      |
| John Stordahl, UST Class B Global Operator | fireman2201@msn.com      |
| Joseph McClain, UST Class B Operator       | jgmcclain25@gmail.com    |
| Joseph McClain, UST Class B Operator       | jgmcclain25@gmail.com    |
| Justin Gaudot, UST Class A Operator        | justgaudot@yahoo.com     |
| Justin Gaudot, UST Class A Operator        | justgaudot@yahoo.com     |
| Justin Gaudot, UST Class B Global Operator | justgaudot@yahoo.com     |
| Justin Gaudot, UST Class B Global Operator | justgaudot@yahoo.com     |
| Stephen Hanson, UST Class A Operator       | finestoil@finest-oil.com |
| Stephen Hanson, UST Class A Operator       | finestoil@finest-oil.com |
| Stephen Hanson, UST Class B Operator       | finestoil@finest-oil.com |
| Stephen Hanson, UST Class B Operator       | finestoil@finest-oil.com |

<b>Tank Code</b>	07	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	10/27/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1074	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible



<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	08	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	10/27/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1075	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	09	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	10/27/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1076	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/04/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** GREAT WESTERN PETROLEUM  
1002 E Broadway St  
Missoula, MT 59802-4930 Missoula

System Facility ID:32-07431

**Facility Code:** 25437  
**Last Inspected On:** 05/01/2024  
**Operating Permit Renewal Date:** 10/30/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Tabish Brothers Distributors Inc

**(406) 543-7621**

**lss@gwpetrol.com**

**Operator Contact:** Heather Stiles

**hstiles@gwpetrol.com**

**Owner/Operator:** Tabish Brothers Distributors Inc

**(406) 543-7621**

**lss@gwpetrol.com**

Heather Stiles, UST Class A Operator

**hstiles@gwpetrol.com**

Heather Stiles, UST Class A Operator

**hstiles@gwpetrol.com**

Heather Stiles, UST Class B Global Operator

**hstiles@gwpetrol.com**

Heather Stiles, UST Class B Global Operator

**hstiles@gwpetrol.com**

<b>Tank Code</b>	10	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	06/01/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1432	<b>Spill Test Date</b>	10/17/2024	<b>Piping Installed Date</b>	08/26/2006	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/01/2024	<b>Sump Tightness Test Date</b>	07/27/2018	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	05/01/2024	<b>Line Tightness Test Date</b>	05/01/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/01/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	S11	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	06/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	1433	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/01/2024	<b>Sump Tightness Test Date</b>	07/27/2018	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No

<b>Capacity</b>	17000	<b>ATG Test Date</b>	10/07/2021	<b>Line Tightness Test Date</b>	05/01/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S12	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	06/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	1434	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/01/2024	<b>Sump Tightness Test Date</b>	07/27/2018	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	11000	<b>ATG Test Date</b>	10/07/2021	<b>Line Tightness Test Date</b>	05/01/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S13	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	06/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	1435	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/01/2024	<b>Sump Tightness Test Date</b>	07/27/2018	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	14600	<b>ATG Test Date</b>	10/07/2021	<b>Line Tightness Test Date</b>	05/01/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S14	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	06/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	1436	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/01/2024	<b>Sump Tightness Test Date</b>	07/27/2018	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	11000	<b>ATG Test Date</b>	10/07/2021	<b>Line Tightness Test Date</b>	05/01/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

	Overfill Test Date		ATG Type		
--	--------------------	--	----------	--	--

**Facility Summary in Missoula County in the City of Missoula**

**Location:** HEATING PLANT  
Physical Plant Bldg #32  
Missoula, MT 59812 Missoula

System Facility ID:32-00505

**Facility Code:** 25184  
**Last Inspected On:** 01/28/2023  
**Operating Permit Renewal Date:** 02/22/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** University of Montana (406) 243-2190

**Operator Contact:** Anthony Ey anthony.ey@mso.umt.edu

**Owner/Operator:** University of Montana (406) 243-2190

Anthony Ey, UST Class A Operator  
Anthony Ey, UST Class B Operator

anthony.ey@mso.umt.edu  
anthony.ey@mso.umt.edu

<b>Tank Code</b>	09	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	11/01/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4221	<b>Spill Test Date</b>	01/27/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	01/27/2023	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	01/27/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/27/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300;Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** HELLGATE CONOCO SERVICE CENTER  
711 E Broadway St  
Missoula, MT 59802-4609 Missoula

System Facility ID:32-00144

**Facility Code:** 25156  
**Last Inspected On:** 06/12/2023  
**Operating Permit Renewal Date:** 06/14/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Hellgate Conoco Service Center;Ross Grenfell;Hellgate Conoco Service Center      **(406) 728-9966;(406) 728-9966;(406) 728-9966**      **hellgateconoco@gmail.com**

**Operator Contact:** Ross Grenfell;Hellgate Conoco Service Center      **(406) 728-9966;(406) 728-9966**      **hellgateconoco@gmail.com**

**Owner/Operator:** Hellgate Conoco Service Center      (406) 728-9966

**Owner/Operator:** Ross Grenfell,Hellgate Conoco Service Center      (406) 728-9966

Ross Grenfell, UST Class A Operator

hellgateconoco@gmail.com

Ross Grenfell, UST Class B Global Operator

hellgateconoco@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	59	<b>Tank Installed Date</b>	03/31/1966	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3765	<b>Spill Test Date</b>	06/12/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/12/2023	<b>Sump Tightness Test Date</b>	06/12/2023	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/12/2023	<b>Line Tightness Test Date</b>	06/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	59	<b>Tank Installed Date</b>	03/31/1966	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3766	<b>Spill Test Date</b>	06/12/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/12/2023	<b>Sump Tightness Test Date</b>	06/12/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/12/2023	<b>Line Tightness Test Date</b>	06/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	06/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				
<b>Tank Code</b>	03	<b>Tank Age</b>	59	<b>Tank Installed Date</b>	03/31/1966	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3767	<b>Spill Test Date</b>	06/12/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/12/2023	<b>Sump Tightness Test Date</b>	06/12/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/12/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/12/2023	<b>Line Tightness Test Date</b>	06/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				
<b>Tank Code</b>	08	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	12/16/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5279	<b>Spill Test Date</b>	06/12/2023	<b>Piping Installed Date</b>	12/16/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/12/2023	<b>Sump Tightness Test Date</b>	06/12/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	03/15/2017	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/12/2023	<b>Line Tightness Test Date</b>	06/12/2023	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	06/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

### Facility Summary in Missoula County in the City of Missoula

**Location:** HELLGATE TRADING POST INC  
6265 Mullan Rd  
Missoula, MT 59808-5650 Missoula

System Facility ID:32-00211

**Facility Code:** 25173  
**Last Inspected On:** 03/12/2025  
**Operating Permit Renewal Date:** 06/03/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

---

**Operator Contact:** Karly Shafer;Malinda Davis (406) 396-2206;(406) 728-8644 htp@gwpetrol.com;karly@gwpetrol.com

---

**Owner/Operator:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

Heather Stiles, UST Class B Global Operator	hstiles@gwpetrol.com
Karly Shafer, UST Class A Operator	karly@gwpetrol.com
Karly Shafer, UST Class B Global Operator	karly@gwpetrol.com
Malinda Davis, UST Class A Operator	htp@gwpetrol.com
Malinda Davis, UST Class B Global Operator	htp@gwpetrol.com

<b>Tank Code</b>	03	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	09/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1425	<b>Spill Test Date</b>	04/24/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/18/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/29/2022	<b>Line Tightness Test Date</b>	02/18/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/24/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	04	<b>Tank Age</b>	31	<b>Tank Installed Date</b>	09/01/1994	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1426	<b>Spill Test Date</b>	04/24/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/18/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	02/18/2022	<b>Line Tightness Test Date</b>	02/18/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/24/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				



**Facility Summary in Missoula County in the City of Missoula**

**Location:** JACKSON FOOD STORE 400  
540 E Broadway St  
Missoula, MT 59802-4614 Missoula

System Facility ID:32-03614

**Facility Code:** 25304  
**Last Inspected On:** 04/09/2024  
**Operating Permit Renewal Date:** 08/26/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** JACKSONS FOOD STORE INC (208) 888-6061 compliance@jacksons.com

**Operator Contact:** Earl Allen;John Monahan (406) 396-7578 jmonahan@hi-noon.com

**Owner/Operator:** JACKSONS FOOD STORE INC (208) 888-6061 compliance@jacksons.com

Earl Allen, UST Class A Operator

Earl Allen, UST Class A Operator

Earl Allen, UST Class B Operator

Earl Allen, UST Class B Operator

John Monahan, UST Class A Operator

John Monahan, UST Class A Operator

John Monahan, UST Class B Global Operator

John Monahan, UST Class B Global Operator

Lisa Millspaugh, UST Class B Operator

Lisa Millspaugh, UST Class B Operator

Willy Baker, UST Class B Global Operator

Willy Baker, UST Class B Global Operator

jmonahan@hi-noon.com

jmonahan@hi-noon.com

jmonahan@hi-noon.com

jmonahan@hi-noon.com

lisamillspaugh@yahoo.com

lisamillspaugh@yahoo.com

silly-willy-69@hotmail.com

silly-willy-69@hotmail.com

<b>Tank Code</b>	05	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	04/28/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5573	<b>Spill Test Date</b>	04/09/2024	<b>Piping Installed Date</b>	04/28/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/30/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/03/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	18000	<b>ATG Test Date</b>	05/03/2023	<b>Line Tightness Test Date</b>	02/13/2021	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/31/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

<b>Tank Code</b>	06	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	04/28/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5574	<b>Spill Test Date</b>	04/09/2024	<b>Piping Installed Date</b>	04/28/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/09/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/03/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	05/03/2023	<b>Line Tightness Test Date</b>	02/13/2021	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/31/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	07	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	04/28/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5575	<b>Spill Test Date</b>	05/18/2021	<b>Piping Installed Date</b>	04/28/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/18/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/18/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	05/18/2021	<b>Line Tightness Test Date</b>	02/13/2021	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/31/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** JACKSONS FOOD STORE 402  
1250 39th St  
Missoula, MT 59803 Missoula

System Facility ID:32-05763

**Facility Code:** 25380  
**Last Inspected On:** 08/15/2022  
**Operating Permit Renewal Date:** 12/10/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** JACKSONS FOOD STORE INC (208) 888-6061 compliance@jacksons.com

---

**Operator Contact:** Earl Allen;John Monahan (406) 396-7578 jmonahan@hi-noon.com

---

**Owner/Operator:** JACKSONS FOOD STORE INC (208) 888-6061 compliance@jacksons.com

- Earl Allen, UST Class A Operator
  - Earl Allen, UST Class A Operator
  - Earl Allen, UST Class B Global Operator
  - Earl Allen, UST Class B Global Operator
  - John Monahan, UST Class A Operator
  - John Monahan, UST Class A Operator
  - John Monahan, UST Class B Global Operator
  - John Monahan, UST Class B Global Operator
  - Joshua Shay, UST Class B Operator
  - Lisa Millspaugh, UST Class B Operator
  - Lisa Millspaugh, UST Class B Operator
  - Willy Baker, UST Class B Operator
  - Willy Baker, UST Class B Operator
- jmonahan@hi-noon.com
  - jmonahan@hi-noon.com
  - jmonahan@hi-noon.com
  - jmonahan@hi-noon.com
  - nightwolf2008@gmail.com
  - lisamillspaugh@yahoo.com
  - lisamillspaugh@yahoo.com
  - silly-willy-69@hotmail.com
  - silly-willy-69@hotmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	01/01/1980	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1348	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/04/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>	06/14/2010	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

<b>Tank Code</b>	02	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	01/01/1980	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1349	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/04/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>	06/14/2010	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	01/01/1980	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1350	<b>Spill Test Date</b>	05/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/04/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	05/04/2022	<b>Line Tightness Test Date</b>	06/14/2010	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	05/04/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** JACKSONS FOOD STORES 401  
1605 S Russell St  
Missoula, MT 59801-5636 Missoula

System Facility ID:32-08863

**Facility Code:** 25478  
**Last Inspected On:** 10/23/2024  
**Operating Permit Renewal Date:** 02/09/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** GYPSY LLC (208) 888-6061 compliance@jacksons.com

**Operator Contact:** Earl Allen;John Monahan (406) 396-7578 jmonahan@hi-noon.com

**Owner/Operator:** GYPSY LLC (208) 888-6061 compliance@jacksons.com

- Deven Cornell, UST Class B Global Operator devencornell@live.com
- Deven Cornell, UST Class B Global Operator devencornell@live.com
- Earl Allen, UST Class A Operator
- Earl Allen, UST Class A Operator
- Earl Allen, UST Class B Operator
- Earl Allen, UST Class B Operator
- John Monahan, UST Class A Operator jmonahan@hi-noon.com
- John Monahan, UST Class A Operator jmonahan@hi-noon.com
- John Monahan, UST Class B Global Operator jmonahan@hi-noon.com
- John Monahan, UST Class B Global Operator jmonahan@hi-noon.com
- Lisa Millspaugh, UST Class B Operator lisamillspaugh@yahoo.com
- Lisa Millspaugh, UST Class B Operator lisamillspaugh@yahoo.com
- Willy Baker, UST Class B Global Operator silly-willy-69@hotmail.com
- Willy Baker, UST Class B Global Operator silly-willy-69@hotmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	06/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1357	<b>Spill Test Date</b>	10/23/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/25/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/23/2024			<b>ATG Type</b>	Veeder Root/TLS-300				

<b>Tank Code</b>	02	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	06/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1358	<b>Spill Test Date</b>	11/26/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/25/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/26/2024			<b>ATG Type</b>	Veeder Root/TLS-300				
<b>Tank Code</b>	03	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	06/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1359	<b>Spill Test Date</b>	10/23/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/25/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/23/2024			<b>ATG Type</b>	Veeder Root/TLS-300				

### Facility Summary in Missoula County in the City of Missoula

**Location:** JAYS 1 STOP  
505 Highton St  
Missoula, MT 59801-5424 Missoula

System Facility ID:32-06680

**Facility Code:** 25412  
**Last Inspected On:** 06/06/2023  
**Operating Permit Renewal Date:** 07/31/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jays Corporation

polsonbay@yahoo.com

**Operator Contact:** Jagpreet Ghuman;Jays 1 Stop;Jaspal Sandhu;Jays Corporation

(406) 880-7677;(406) 549-1031

jas\_sandhu75@hotmail.com;polsonbay@yahoo.com;jaysfood08@outlook.com;jays1stop21@outlook.com

**Owner/Operator:** Jays Corporation

polsonbay@yahoo.com

Jagpreet Ghuman, UST Class A Operator  
Jagpreet Ghuman, UST Class B Operator  
Jaspal Sandhu, UST Class A Operator  
Jaspal Sandhu, UST Class B Operator

jays1stop21@outlook.com  
jays1stop21@outlook.com  
polsonbay@yahoo.com  
polsonbay@yahoo.com

<b>Tank Code</b>	03	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	01/10/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2298	<b>Spill Test Date</b>	09/03/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/21/2022	<b>Sump Tightness Test Date</b>	09/11/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/12/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	02/25/2025	<b>Line Tightness Test Date</b>	07/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/03/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	01/10/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2299	<b>Spill Test Date</b>	09/03/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/21/2022	<b>Sump Tightness Test Date</b>	09/11/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/12/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	02/25/2025	<b>Line Tightness Test Date</b>	07/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	03/03/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	01/10/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2300	<b>Spill Test Date</b>	09/03/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/21/2022	<b>Sump Tightness Test Date</b>	09/11/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/12/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	02/25/2025	<b>Line Tightness Test Date</b>	07/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/03/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	06	<b>Tank Age</b>	1	<b>Tank Installed Date</b>	08/07/2024	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	6252	<b>Spill Test Date</b>	09/03/2024	<b>Piping Installed Date</b>	02/21/2025	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/11/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	02/25/2025	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/03/2025			<b>ATG Type</b>					



**Facility Summary in Missoula County in the City of Missoula**

**Location:** JAYS FOOD STORE  
2738 W Broadway St  
Missoula, MT 59808-1622 Missoula

System Facility ID:32-05760

**Facility Code:** 25377  
**Last Inspected On:** 03/01/2023  
**Operating Permit Renewal Date:** 08/02/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jays Corporation

polsonbay@yahoo.com

**Operator Contact:** Jagpreet Ghuman;Jaspal Sandhu

(406) 880-7677

jas\_sandhu75@hotmail.com;jaysfood08@outlook.com

**Owner/Operator:** Jays Corporation

polsonbay@yahoo.com

Jagpreet Ghuman, UST Class A Operator  
Jagpreet Ghuman, UST Class B Global Operator  
Jaspal Sandhu, UST Class A Operator  
Jaspal Sandhu, UST Class B Global Operator  
Jaspal Sandhu, UST Class B Operator

jaysfood08@outlook.com  
jaysfood08@outlook.com  
jas\_sandhu75@hotmail.com  
jas\_sandhu75@hotmail.com  
jas\_sandhu75@hotmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	53	<b>Tank Installed Date</b>	11/18/1972	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1345	<b>Spill Test Date</b>	04/11/2022	<b>Piping Installed Date</b>	10/10/2015	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/22/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/03/2019	<b>Tank/Piping CP Test Date</b>	03/01/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>	10/12/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/11/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	49	<b>Tank Installed Date</b>	11/18/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1346	<b>Spill Test Date</b>	04/11/2022	<b>Piping Installed Date</b>	10/10/2015	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/22/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/03/2019	<b>Tank/Piping CP Test Date</b>	03/01/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/14/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/11/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	53	<b>Tank Installed Date</b>	11/18/1972	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1347	<b>Spill Test Date</b>	04/11/2022	<b>Piping Installed Date</b>	10/10/2015	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/22/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/03/2019	<b>Tank/Piping CP Test Date</b>	03/01/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>	10/14/2019	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/11/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** JAYS FOOD STORE CARDLOCK  
2738 W Broadway St  
Missoula, MT 59808-1622 Missoula

System Facility ID:32-05761

**Facility Code:** 25378  
**Last Inspected On:** 07/15/2022  
**Operating Permit Renewal Date:** 07/15/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Jays Corporation

polsonbay@yahoo.com

**Operator Contact:** Jagpreet Ghuman

(406) 880-7677

jaysfood08@outlook.com

**Owner/Operator:** Jays Corporation

polsonbay@yahoo.com

Jagpreet Ghuman, UST Class A Operator

jaysfood08@outlook.com

Jagpreet Ghuman, UST Class B Global Operator

jaysfood08@outlook.com

Jaspal Sandhu, UST Class B Global Operator

jas\_sandhu75@hotmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	46	<b>Tank Installed Date</b>	11/14/1979	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3627	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/28/2022	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	02	<b>Tank Age</b>	50	<b>Tank Installed Date</b>	11/14/1975	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3628	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/28/2022	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

<b>Tank Code</b>	03	<b>Tank Age</b>	46	<b>Tank Installed Date</b>	11/14/1979	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3629	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	06/28/2022	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** LITHIA AUTO CENTER  
5001 Grizzly Ct  
Missoula, MT 59808-8672 Missoula

System Facility ID:56-14004

**Facility Code:** 30665  
**Last Inspected On:** 05/16/2019  
**Operating Permit Renewal Date:** 06/24/2022

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Lithia Chrysler Dodge of Missoula (406) 721-5000

**Operator Contact:** Betty Johnson (406) 721-5000

Betty Johnson, UST Class A Operator  
Betty Johnson, UST Class B Operator

<b>Tank Code</b>	01	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4359	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	02	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4360	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** LOVES TRAVEL STOP #753  
8077 Hwy 10 W  
Missoula, MT 59808 Missoula

System Facility ID:60-15321

**Facility Code:** 31018  
**Last Inspected On:** 10/01/2024  
**Operating Permit Renewal Date:** 01/28/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Loves Travel Stops and Country Stores Inc

environmental@loves.com

**Operator Contact:** Eric Bennett;Loves Travel Stops and Country Stores Inc;Ted Lowery;Loves Travel Stops and Country Stores Inc (405) 779-3768

environmental@loves.com;environmental@loves.com

**Owner/Operator:** Loves Travel Stops and Country Stores Inc

environmental@loves.com

Eric Bennett, UST Class A Operator  
Eric Bennett, UST Class B Operator  
Eric Candelaria, UST Class B Operator  
Ted Lowery, UST Class A Operator  
Ted Lowery, UST Class B Operator

environmental@loves.com  
environmental@loves.com  
environmental@loves.com  
environmental@loves.com  
environmental@loves.com

<b>Tank Code</b>	01	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5830	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	30000	<b>ATG Test Date</b>	01/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	02	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5831	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes

		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	03	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5832	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	04	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5833	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	05	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5834	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	06	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5835	<b>Spill Test Date</b>	09/22/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	07	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5836	<b>Spill Test Date</b>	09/20/2022	<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Biodiesel B99	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	09/20/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	08	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	08/15/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5837	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/15/2019	<b>Tank Construction</b>		<b>Piping Construction</b>		<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Not Listed	<b>Primary Pipe Detection</b>	Not Listed	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/29/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Not Listed	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	09	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5863	<b>Spill Test Date</b>	10/01/2023	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				



<b>Tank Code</b>	10	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5864	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	11	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5865	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	12	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5866	<b>Spill Test Date</b>	10/01/2023	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	13	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5867	<b>Spill Test Date</b>	10/01/2023	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible

<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	14	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5868	<b>Spill Test Date</b>	10/01/2023	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	11/15/2023	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	15	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	10/26/2018	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5869	<b>Spill Test Date</b>	10/01/2023	<b>Piping Installed Date</b>	12/17/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Secondary Containment Chase	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/20/2022	<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2000	<b>ATG Test Date</b>	11/15/2023	<b>Line Tightness Test Date</b>	11/24/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	02/24/2022			<b>ATG Type</b>	Incon/TS-550 EVO				

## Facility Summary in Missoula County in the City of Missoula

**Location:** MDOT MISSOULA  
2100 W Broadway St  
Missoula, MT 59808-1816 Missoula

System Facility ID:32-09304

**Facility Code:** 25486  
**Last Inspected On:** 03/11/2024  
**Operating Permit Renewal Date:** 07/10/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

<b>Owner Operator Contact:</b> MDOT Helena	(406) 444-6163	mmurolo@mt.gov
<b>Operator Contact:</b> Joe Radonich;Montana Dept of Transportation;Michael Carstensen;MDT 11 3211 Missoula W Broadway;Mike Murolo;Montana Dept of Transportation;Tracy Deeds;MDOT Helena;Walt Kerttula;Montana Dept of Transportation	(406) 444-6151;(406) 444-7632;(406) 444-6163;(406) 444-7632;(406) 444-9204;(406) 444-7632;(406) 461-0769;(406) 444-6163;(406) 523-5836	jradonich@mt.gov;jradonich@mt.gov;mcarstensen@mt.gov;mmurolo@mt.gov;jradonich@mt.gov;tdeeds@mt.gov;mmurolo@mt.gov;wkerttula@mt.gov;jradonich@mt.gov

Chad Pearson, UST Class B Operator

chpearson@mt.gov

Cody Crawford, UST Class B Operator

cocrawford@mt.gov

Joe Radonich, UST Class A Operator

jradonich@mt.gov

Joe Radonich, UST Class B Operator

jradonich@mt.gov

Michael Carstensen, UST Class A Operator

mcarstensen@mt.gov

Michael Carstensen, UST Class B Operator

mcarstensen@mt.gov

Mike Murolo, UST Class A Operator

jradonich@mt.gov

Tracy Deeds, UST Class A Operator

mmurolo@mt.gov

Walt Kerttula, UST Class A Operator

jradonich@mt.gov

<b>Tank Code</b>	01	<b>Tank Age</b>	41	<b>Tank Installed Date</b>	05/01/1984	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2917	<b>Spill Test Date</b>	06/22/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	03/11/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	03/11/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	09/30/2021			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	06	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	04/01/1987	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2918	<b>Spill Test Date</b>	03/11/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic

<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	03/11/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	03/11/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/11/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA #7 FLYING J  
8745 Hwy 93 N  
Missoula, MT 59808 Missoula

System Facility ID:60-15158

**Facility Code:** 30899  
**Last Inspected On:** 06/27/2023  
**Operating Permit Renewal Date:** 10/31/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 7 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

**Operator Contact:** Trent Biggers

**Trentb@townpump.com**

**Owner/Operator:** Missoula 7 Town Pump LLC

**(406) 497-6700**

**environmental@townpump.com**

Trent Biggers, UST Class A Operator

Trentb@townpump.com

Trent Biggers, UST Class B Global Operator

Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5256	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	02	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5257	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

<b>Tank Code</b>	03	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5258	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	25000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	04	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5259	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	05	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5260	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	06	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5261	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	15000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	07	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5262	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	08	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5331	<b>Spill Test Date</b>	10/25/2022	<b>Piping Installed Date</b>	07/19/2010	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	09	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	09/01/2010	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5361	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	04/11/2012	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Other	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Not Listed	<b>CP Met Types</b>	

<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Approved Remote Monitoring;Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Approved Remote Monitoring;Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					



**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA AIRPORT WASHINGTON HANGER  
5225 W Broadway St  
Missoula, MT 59808-9385 Missoula

System Facility ID:32-07606

**Facility Code:** 25444  
**Last Inspected On:** 03/20/2023  
**Operating Permit Renewal Date:** 05/25/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Washington Corporations (406) 523-1349

**Operator Contact:** Andrew Ihle;Missoula Airport Washington Hanger;Roy Felt;Ryan Opheim (406) 214-8531 aihle@washcorp.com;rfelt@washcorp.com;ropheim@washcorp.com

**Owner/Operator:** Washington Corporations (406) 523-1349

- Andrew Ihle, UST Class A Operator aihle@washcorp.com
- Andrew Ihle, UST Class B Operator aihle@washcorp.com
- Roy Felt, UST Class A Operator rfelt@washcorp.com
- Roy Felt, UST Class A Operator rfelt@washcorp.com
- Roy Felt, UST Class B Global Operator rfelt@washcorp.com
- Roy Felt, UST Class B Global Operator rfelt@washcorp.com
- Ryan Opheim, UST Class A Operator ropheim@washcorp.com
- Ryan Opheim, UST Class A Operator ropheim@washcorp.com
- Ryan Opheim, UST Class B Operator ropheim@washcorp.com
- Ryan Opheim, UST Class B Operator ropheim@washcorp.com

<b>Tank Code</b>	01	<b>Tank Age</b>	41	<b>Tank Installed Date</b>	05/07/1984	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	2242	<b>Spill Test Date</b>	03/20/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/17/2024	<b>Sump Tightness Test Date</b>	03/20/2023	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Jet Fuel (Jet-A, Jet-A1, JP5)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	02/26/2020	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	07/17/2024	<b>Line Tightness Test Date</b>	03/20/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/17/2024			<b>ATG Type</b>	Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA CHEVROLET  
3663 N Reserve St  
Missoula, MT 59808-1509 Missoula

System Facility ID:56-14056

**Facility Code:** 30710  
**Last Inspected On:** 05/13/2023  
**Operating Permit Renewal Date:** 09/10/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** MISSOULA MOTOR COMPANY LLC (406) 721-2438 terryh@missoulamc.com

**Operator Contact:** Terry Hedrick (406) 532-2437 terryh@missoulamc.com

**Owner/Operator:** MISSOULA MOTOR COMPANY LLC (406) 721-2438 terryh@missoulamc.com

Terry Hedrick, UST Class A Operator  
Terry Hedrick, UST Class B Operator

terryh@missoulamc.com  
terryh@missoulamc.com

<b>Tank Code</b>	02	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	07/22/2002	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4695	<b>Spill Test Date</b>	11/17/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	11/17/2022	<b>Sump Tightness Test Date</b>	08/10/2020	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	11/17/2022	<b>Line Tightness Test Date</b>	09/20/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/17/2022			<b>ATG Type</b>	Veeder Root/TLS-300				
<b>Tank Code</b>	03	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	07/22/2002	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4696	<b>Spill Test Date</b>	11/17/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	11/17/2022	<b>Sump Tightness Test Date</b>	08/10/2020	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring;Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	4000	<b>ATG Test Date</b>	11/17/2022	<b>Line Tightness Test Date</b>	09/20/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/17/2022			<b>ATG Type</b>	Veeder Root/TLS-300				
<b>Tank Code</b>	S1	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	07/30/2002	<b>Tank Material</b>	Aboveground Tank	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4699	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/10/2020	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/17/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA COUNTY DETENTION CENTER  
2340 Mullan Rd  
Missoula, MT 59808-1830 Missoula

System Facility ID:56-13921

**Facility Code:** 30591  
**Last Inspected On:** 11/14/2022  
**Operating Permit Renewal Date:** 11/22/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula County Detention Center (406) 829-4000

**Operator Contact:** Gary Zinke;Jess Ebel (406) 531-3627 gezinke@missoulacounty.us;jebel@missoulacounty.us

**Owner/Operator:** Missoula County Detention Center (406) 829-4000

Gary Zinke, UST Class A Operator  
Gary Zinke, UST Class B Operator  
Jess Ebel, UST Class A Operator  
Jess Ebel, UST Class B Operator

gezinke@missoulacounty.us  
gezinke@missoulacounty.us  
jebel@missoulacounty.us  
jebel@missoulacounty.us

<b>Tank Code</b>	S1	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	06/01/1999	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Copper	<b>Overfill Types</b>	
<b>Tag Number</b>	3774	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Secondary Containment Chase	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/10/2024	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	3000	<b>ATG Test Date</b>	10/10/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

## Facility Summary in Missoula County in the City of Missoula

**Location:** MISSOULA SERVICE CENTER  
1900 S Russell St  
Missoula, MT 59801-6624 Missoula

System Facility ID:32-01182

**Facility Code:** 25203  
**Last Inspected On:** 01/18/2023  
**Operating Permit Renewal Date:** 06/13/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Northwestern Energy Butte (406) 655-2521 beth.stimatz@northwestern.com

---

**Operator Contact:** Brian Ranf;John Habeger brian.ranf@northwestern.com;john.habeger@northwestern.com

---

**Owner/Operator:** Northwestern Energy Butte (406) 655-2521 beth.stimatz@northwestern.com

Brian Ranf, UST Class A Operator  
 Bruce Schlichenmayer, UST Class B Operator  
 Bruce Schlichenmayer, UST Class B Operator  
 Greg Sponseller, UST Class B Operator  
 Greg Sponseller, UST Class B Operator  
 Joe Vigue, UST Class B Operator  
 Joe Vigue, UST Class B Operator  
 John Habeger, UST Class A Operator  
 John Habeger, UST Class A Operator

brian.ranf@northwestern.com  
 bruce.schlichenmayer@northwestern.com  
 bruce.schlichenmayer@northwestern.com  
 gregory.sponseller@northwestern.com  
 gregory.sponseller@northwestern.com  
  
 john.habeger@northwestern.com  
 john.habeger@northwestern.com

<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/27/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1680	<b>Spill Test Date</b>	08/25/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/18/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	13000	<b>ATG Test Date</b>	07/19/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/25/2021			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/27/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1681	<b>Spill Test Date</b>	08/25/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic

<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	01/18/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	3000	<b>ATG Test Date</b>	07/19/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/25/2021			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA TRAVEL CENTER  
8018 US Hwy 93 N  
Missoula, MT 59808 Missoula

System Facility ID:32-02822

**Facility Code:** 25272  
**Last Inspected On:** 08/17/2023  
**Operating Permit Renewal Date:** 04/15/2019

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** TA Operating LLC (440) 808-7406 kgelske@ta-petro.com

**Operator Contact:** Ben Waverek;TA Operating LLC;Daniel Stubbs;TA Operating LLC;Kelly Gelske (406) 549-2327;(440) 808-7406;(440) 522-6761 bwaverek@ta-petro.com;kgelske@ta-petro.com;dstubbs@ta-petro.com;kgelske@ta-petro.com;kgelske@ta-petro.com

**Owner/Operator:** TA Operating LLC (440) 808-7406 kgelske@ta-petro.com

Ben Waverek, UST Class A Operator kgelske@ta-petro.com  
 Ben Waverek, UST Class B Operator kgelske@ta-petro.com  
 Daniel Stubbs, UST Class A Operator kgelske@ta-petro.com  
 Daniel Stubbs, UST Class B Operator kgelske@ta-petro.com  
 Kelly Gelske, UST Class A Operator kgelske@ta-petro.com  
 Kelly Gelske, UST Class B Global Operator kgelske@ta-petro.com

<b>Tank Code</b>	13	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	08/22/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5511	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	07/29/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Other	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/18/2014	<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Not Listed	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-4I, B, C				
<b>Tank Code</b>	14	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	02/24/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	5550	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	09/18/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/30/2020	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Motor	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	03/12/2015	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	15	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	02/24/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	5551	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	09/18/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/30/2020	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Gravity Feed	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	03/12/2015	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	16	<b>Tank Age</b>	6	<b>Tank Installed Date</b>	07/31/2019	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5929	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	07/31/2019	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/30/2020	<b>Sump Tightness Test Date</b>	04/30/2020	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	04/30/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	01	<b>Tank Age</b>	47	<b>Tank Installed Date</b>	02/17/1978	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	785	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	06/10/2010	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/18/2014	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/18/2017	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2;Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No



<b>Capacity</b>	20000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	07/18/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	47	<b>Tank Installed Date</b>	02/17/1978	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	786	<b>Spill Test Date</b>	02/01/2024	<b>Piping Installed Date</b>	08/22/2014	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	02/01/2024	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/16/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	07/18/2017	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	03	<b>Tank Age</b>	47	<b>Tank Installed Date</b>	02/17/1978	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	787	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/22/2014	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	05/19/2021	<b>Sump Tightness Test Date</b>	02/01/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/16/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	05/19/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	09	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	11/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	788	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/22/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/30/2020	<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	04/30/2020	<b>Tank/Piping CP Test Date</b>	05/16/2020	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	04/30/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	10	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	11/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	789	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/22/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/30/2020	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/16/2020	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	08/04/2014	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	11	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	11/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	790	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	11/03/2010	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/18/2014	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	04/30/2020	<b>Tank/Piping CP Test Date</b>	05/16/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	04/30/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	12	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	11/01/1993	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	791	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	11/03/2010	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/18/2014	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	04/30/2020	<b>Tank/Piping CP Test Date</b>	05/16/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	04/30/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 450PLUS				
--	--	---------------------------	--	--	--	-----------------	---	--	--	--	--

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MISSOULA URBAN TRANSPORTATION  
1221 Shakespeare St  
Missoula, MT 59802-2307 Missoula

System Facility ID:32-04427

**Facility Code:** 25341  
**Last Inspected On:** 03/24/2023  
**Operating Permit Renewal Date:** 06/05/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula Urban Transportation

**Operator Contact:** Jeffrey Logan;John Roseboom

**(406) 215-2455;(406) 215-2458**

**jlogan@mountainline.com;john@mountainline.com**

**Owner/Operator:** Missoula Urban Transportation

Brian Dildine, UST Class B Operator  
Cody Bush, UST Class B Operator  
Cody Bush, UST Class B Operator  
David Loewen, UST Class B Operator  
David Loewen, UST Class B Operator  
Jacob Nolen, UST Class B Operator  
Jacob Nolen, UST Class B Operator  
Jeffrey Logan, UST Class A Operator  
Jeffrey Logan, UST Class A Operator  
Jeffrey Logan, UST Class B Operator  
Jeffrey Logan, UST Class B Operator  
John Roseboom, UST Class A Operator  
John Roseboom, UST Class B Operator  
Kent Russell, UST Class B Operator  
Kent Russell, UST Class B Operator

bdildine@mountainline.com  
cbush@mountainline.com  
cbush@mountainline.com  
  
jnolen@mountainline.com  
jnolen@mountainline.com  
jlogan@mountainline.com  
jlogan@mountainline.com  
jlogan@mountainline.com  
jlogan@mountainline.com  
john@mountainline.com  
john@mountainline.com  
krussell@mountainline.com  
krussell@mountainline.com

<b>Tank Code</b>	04	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	04/30/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	1658	<b>Spill Test Date</b>	03/24/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	03/24/2023			<b>ATG Type</b>	Gilbarco/EMC Basic;Gilbarco-Veeder Root/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	04/30/1998	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1659	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	03/24/2023	<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Gravity Feed	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	600	<b>ATG Test Date</b>	03/24/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/24/2023			<b>ATG Type</b>	Gilbarco/EMC Basic;Gilbarco-Veeder Root/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MOUNTAIN WEST COOP  
4570 N Reserve St  
Missoula, MT 59808 Missoula

System Facility ID:32-02437

**Facility Code:** 25260  
**Last Inspected On:** 03/27/2024  
**Operating Permit Renewal Date:** 06/15/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

<b>Owner Operator Contact:</b> CHS Inc Inver Grove Heights	<b>(651) 355-6343</b>	<b>Kirsten.Tindall@chsinc.com</b>
<b>Operator Contact:</b> Bob Westin;Dusty Smith;John Thompson;Michael Gourley;CHS Inc Inver Grove Heights;Robin McCurdy;Will Dukart	<b>(406) 370-3920;(651) 355-6343;(406) 546-4885;(406) 665-1728;(406) 880-8169</b>	<b>chuck.thompson@chsinc.com;dusty.smith@chsinc.com;michael.gourley@chsinc.com;Kirsten.Tindall@chsinc.com;robin.mccurdy@chsinc.com;will.dukart@chsinc.com</b>

<b>Owner/Operator:</b> CHS Inc Inver Grove Heights	(651) 355-6343	Kirsten.Tindall@chsinc.com
Bill Griffin, UST Class B Operator		
Bill Griffin, UST Class B Operator		
Bob Westin, UST Class A Operator		
Bob Westin, UST Class B Global Operator		
Dusty Smith, UST Class A Operator		dusty.smith@chsinc.com
Dusty Smith, UST Class B Global Operator		dusty.smith@chsinc.com
John Thompson, UST Class A Operator		chuck.thompson@chsinc.com
John Thompson, UST Class A Operator		chuck.thompson@chsinc.com
John Thompson, UST Class B Global Operator		chuck.thompson@chsinc.com
John Thompson, UST Class B Global Operator		chuck.thompson@chsinc.com
John Thompson, UST Class B Operator		chuck.thompson@chsinc.com
John Thompson, UST Class B Operator		chuck.thompson@chsinc.com
Michael Gourley, UST Class A Operator		Kirsten.Tindall@chsinc.com
Mike Dunlon, UST Class B Operator		michael.dunlop@chsinc.com
Mike Dunlon, UST Class B Operator		michael.dunlop@chsinc.com
Robin McCurdy, UST Class A Operator		robin.mccurdy@chsinc.com
Robin McCurdy, UST Class B Operator		robin.mccurdy@chsinc.com
Will Dukart, UST Class A Operator		will.dukart@chsinc.com
Will Dukart, UST Class A Operator		will.dukart@chsinc.com

<b>Tank Code</b>	16	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	03/29/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	2859	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	02/27/2024	<b>Line Tightness Test Date</b>	06/12/2014	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	17	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5554	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	25000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	01/16/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	18	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5555	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	25000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	01/16/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	19	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5556	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible

<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	01/16/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	20	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5557	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	01/16/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	21	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5558	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	01/16/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/07/2021			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	22	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5559	<b>Spill Test Date</b>	10/07/2021	<b>Piping Installed Date</b>	01/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible



<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/26/2024	<b>Tank/Piping CP Test Date</b>	03/27/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/27/2024	<b>Line Tightness Test Date</b>	09/16/2022	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	03/27/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** MURALTS TRUCK PLAZA  
8800 Truck Stop Rd  
Missoula, MT 59808-9708 Missoula

System Facility ID:32-00146

**Facility Code:** 25157  
**Last Inspected On:** 12/20/2023  
**Operating Permit Renewal Date:** 01/14/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Muralts Inc;Walter Muralt (406) 728-4700 walt@muralts.com

**Operator Contact:** Curtis Wilson (406) 207-5448 curtis@muralts.com

**Owner/Operator:** Muralts Inc (406) 728-4700

**Owner/Operator:** Walter Muralt (406) 728-4700

Bonnie Kelley, UST Class B Global Operator  
Curtis Wilson, UST Class A Operator  
Curtis Wilson, UST Class A Operator  
Curtis Wilson, UST Class B Operator  
Curtis Wilson, UST Class B Operator  
Kevin Linton, UST Class B Operator

bonnie@muralts.com  
curtis@muralts.com  
curtis@muralts.com  
curtis@muralts.com  
curtis@muralts.com  
jesselinton14@gmail.com

<b>Tank Code</b>	10	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	11/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1734	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/12/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	05/19/2009	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	11	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	11/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1735	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/12/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	05/19/2009	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	01	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	03/26/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3650	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/12/2016	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	02	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	03/26/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3651	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/12/2016	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	03	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	03/26/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3652	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/12/2016	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

<b>Tank Code</b>	04	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	03/26/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3653	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	05	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	03/26/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3654	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	06	<b>Tank Age</b>	52	<b>Tank Installed Date</b>	03/26/1973	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3655	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/17/2020	<b>Tank/Piping CP Test Date</b>	07/23/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	01/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** OLES COUNTRY STORE 11  
1600 S Russell St  
Missoula, MT 59801-5637 Missoula

System Facility ID:32-04620

**Facility Code:** 25345  
**Last Inspected On:** 10/22/2024  
**Operating Permit Renewal Date:** 03/05/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** DDJ Investments LLC;Jennifer Louquet (406) 728-7618 olescs11@gmail.com

**Operator Contact:** Derek Louquet (406) 369-5855 derek.louquet@gmail.com

**Owner/Operator:** DDJ Investments LLC (406) 728-7618 olescs11@gmail.com

**Owner/Operator:** Jennifer Louquet (406) 728-7618 olescs11@gmail.com

Derek Louquet, UST Class A Operator derek.louquet@gmail.com  
Derek Louquet, UST Class A Operator derek.louquet@gmail.com  
Mary Fleming, UST Class B Operator olescs11@gmail.com

<b>Tank Code</b>	04	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	10/30/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1721	<b>Spill Test Date</b>	04/15/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/23/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	02/06/2024	<b>Line Tightness Test Date</b>	02/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/06/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	10/30/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1722	<b>Spill Test Date</b>	10/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/23/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	02/06/2024	<b>Line Tightness Test Date</b>	02/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/06/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				

<b>Tank Code</b>	06	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	10/30/1988	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1723	<b>Spill Test Date</b>	10/27/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/23/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	02/06/2024	<b>Line Tightness Test Date</b>	02/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/06/2024			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** OLES COUNTRY STORE 12  
3705 MT Hwy 200 E  
Missoula, MT 59802 Missoula

System Facility ID:32-03190

**Facility Code:** 25284  
**Last Inspected On:** 10/27/2022  
**Operating Permit Renewal Date:** 02/09/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Tri East Inc (406) 728-7736

**Operator Contact:** Peggy Wolfe peggy\_wlf@yahoo.com

**Owner/Operator:** Tri East Inc (406) 728-7736

LeeAnn Dean, UST Class B Global Operator  
LeeAnn Dean, UST Class B Global Operator  
Peggy Wolfe, UST Class A Operator  
Peggy Wolfe, UST Class A Operator  
Peggy Wolfe, UST Class B Operator  
Peggy Wolfe, UST Class B Operator

peggy\_wlf@yahoo.com  
peggy\_wlf@yahoo.com  
peggy\_wlf@yahoo.com  
peggy\_wlf@yahoo.com

<b>Tank Code</b>	01	<b>Tank Age</b>	61	<b>Tank Installed Date</b>	05/01/1964	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1427	<b>Spill Test Date</b>	07/12/2021	<b>Piping Installed Date</b>	01/11/2018	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/12/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/21/2025	<b>Line Tightness Test Date</b>	04/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	02	<b>Tank Age</b>	61	<b>Tank Installed Date</b>	05/01/1964	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1428	<b>Spill Test Date</b>	07/12/2021	<b>Piping Installed Date</b>	01/11/2018	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/12/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current

<b>Product</b>	Diesel	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/21/2025	<b>Line Tightness Test Date</b>	04/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	03	<b>Tank Age</b>	61	<b>Tank Installed Date</b>	05/01/1964	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1429	<b>Spill Test Date</b>	07/12/2021	<b>Piping Installed Date</b>	01/11/2018	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/12/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/21/2025	<b>Line Tightness Test Date</b>	04/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	04	<b>Tank Age</b>	61	<b>Tank Installed Date</b>	05/01/1964	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1430	<b>Spill Test Date</b>	07/12/2021	<b>Piping Installed Date</b>	01/11/2018	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/12/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	03/21/2025	<b>Line Tightness Test Date</b>	04/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	05	<b>Tank Age</b>	46	<b>Tank Installed Date</b>	05/02/1979	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1431	<b>Spill Test Date</b>	07/12/2021	<b>Piping Installed Date</b>	01/11/2018	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/12/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>	07/20/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No



<b>Capacity</b>	4000	<b>ATG Test Date</b>	03/21/2025	<b>Line Tightness Test Date</b>	04/21/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 450PLUS				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** OLES COUNTRY STORE 2  
923 N Orange St  
Missoula, MT 59802-2927 Missoula

System Facility ID:32-05216

**Facility Code:** 25359  
**Last Inspected On:** 11/08/2022  
**Operating Permit Renewal Date:** 03/14/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Oles Country Stores Inc Missoula

**Operator Contact:** Casie Schwindt

rschwindt92@yahoo.com

**Owner/Operator:** Oles Country Stores Inc Missoula

Casie Schwindt, UST Class A Operator  
Casie Schwindt, UST Class A Operator  
Casie Schwindt, UST Class B Operator  
Casie Schwindt, UST Class B Operator

rschwindt92@yahoo.com  
rschwindt92@yahoo.com  
rschwindt92@yahoo.com  
rschwindt92@yahoo.com

<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/25/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2357	<b>Spill Test Date</b>	11/08/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Secondary Containment Chase	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/08/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>	08/22/2007	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/09/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/25/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2358	<b>Spill Test Date</b>	11/08/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Secondary Containment Chase	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	10/07/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/08/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>	10/07/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/09/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				

<b>Tank Code</b>	06	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/25/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2359	<b>Spill Test Date</b>	11/08/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Secondary Containment Chase	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/08/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	11/08/2022	<b>Line Tightness Test Date</b>	08/22/2007	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/09/2022			<b>ATG Type</b>	Gilbarco/EMC Basic				

### Facility Summary in Missoula County in the City of Missoula

**Location:** PHILLIPS 66 EXXON MOBIL JOINTLY OWNED MISSOULA TERMINAL  
3330 Raser Dr  
Missoula, MT 59808-1534 Missoula

System Facility ID:32-08732

**Facility Code:** 25472  
**Last Inspected On:** 01/23/2025  
**Operating Permit Renewal Date:** 06/09/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal (406) 255-5714 allen.eggen@p66.com

---

**Operator Contact:** Chris Cote;Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal;Tanner Beadles;Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal (406) 255-5714 chris.r.cote@p66.com;allen.eggen@p66.com;tanner.j.beadles@p66.com;allen.eggen@p66.com

---

**Owner/Operator:** Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal (406) 255-5714 allen.eggen@p66.com

Andrew Snyder, UST Class B Operator andrew.a.snyder@conocophillips.com  
 Andrew Snyder, UST Class B Operator andrew.a.snyder@conocophillips.com  
 Chris Binder, UST Class B Operator  
 Chris Binder, UST Class B Operator  
 Chris Cote, UST Class A Operator allen.eggen@p66.com  
 Chris Cote, UST Class B Operator allen.eggen@p66.com  
 Dusty Nagel, UST Class B Operator dusty.a.nagel@p66.com  
 Orlando Rodriguez, UST Class B Operator orlando.r.rodriquez@conocophillips.com  
 Orlando Rodriguez, UST Class B Operator orlando.r.rodriquez@conocophillips.com  
 Tanner Beadles, UST Class A Operator allen.eggen@p66.com  
 Tanner Beadles, UST Class B Operator allen.eggen@p66.com

<b>Tank Code</b>	S15	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2793	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	630000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/03/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S18	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2796	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	1260000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S19	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2797	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	647892	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	08/30/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S23	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2800	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	847000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S24	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2801	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	847000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S25	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2802	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes

<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	648000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S26	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	2803	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	648000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S13	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	4581	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	630000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/04/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S17	<b>Tank Age</b>	71	<b>Tank Installed Date</b>	06/01/1954	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	4909	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	840000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	08/29/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** PHILLIPS 66 EXXON MOBIL JOINTLY OWNED MISSOULA  
 TERMINAL  
 3330 Raser Dr  
 Missoula, MT 59808-1534 Missoula

System Facility ID:32-03320

**Facility Code:** 25289  
**Last Inspected On:** 01/23/2025  
**Operating Permit Renewal Date:** 06/09/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal (406) 255-5714 allen.eggen@p66.com

**Operator Contact:** Adam Pfeifer;Dusty Nagel adam.pfeifer@p66.com;dusty.a.nagel@p66.com

**Owner/Operator:** Phillips 66/Exxon Mobil Jointly Owned Missoula Terminal (406) 255-5714 allen.eggen@p66.com

Adam Pfeifer, UST Class A Operator adam.pfeifer@p66.com  
 Adam Pfeifer, UST Class B Global Operator adam.pfeifer@p66.com  
 Andrew Snyder, UST Class B Operator andrew.a.snyder@conocophillips.com  
 Andrew Snyder, UST Class B Operator andrew.a.snyder@conocophillips.com  
 Chris Binder, UST Class B Operator  
 Chris Binder, UST Class B Operator  
 Dustin Rogers, UST Class B Operator dustin.w.rogers@conocophillips.com  
 Dustin Rogers, UST Class B Operator dustin.w.rogers@conocophillips.com  
 Dusty Nagel, UST Class A Operator dusty.a.nagel@p66.com  
 Dusty Nagel, UST Class B Operator dusty.a.nagel@p66.com  
 Marcus Eppard, UST Class B Operator marcus.k.eppard@p66.com  
 Orlando Rodriguez, UST Class B Operator orlando.r.rodriquez@conocophillips.com  
 Orlando Rodriguez, UST Class B Operator orlando.r.rodriquez@conocophillips.com

<b>Tank Code</b>	22	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	11/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	738	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Gravity Feed	<b>CP Met Types</b>	
<b>Product</b>	Mixture	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/22/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S09	<b>Tank Age</b>	72	<b>Tank Installed Date</b>	01/01/1953	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	

<b>Tag Number</b>	739	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	1260000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/09/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S11	<b>Tank Age</b>	72	<b>Tank Installed Date</b>	01/01/1953	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	741	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	840000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/09/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S13	<b>Tank Age</b>	72	<b>Tank Installed Date</b>	01/01/1953	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	743	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Mixture	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	840000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/16/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S15	<b>Tank Age</b>	72	<b>Tank Installed Date</b>	01/01/1953	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	745	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasohol/Ethanol	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	840000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	08/27/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S17	<b>Tank Age</b>	53	<b>Tank Installed Date</b>	01/01/1972	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	



<b>Tag Number</b>	747	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	840000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/24/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S19	<b>Tank Age</b>	51	<b>Tank Installed Date</b>	01/01/1974	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	749	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4200000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/24/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S20	<b>Tank Age</b>	51	<b>Tank Installed Date</b>	01/01/1974	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel - Terminal Piping	<b>Overfill Types</b>	
<b>Tag Number</b>	750	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	05/21/2024	<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Terminal Piping Annual Line Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2646000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** PROVIDENCE CENTER  
900 N Orange St  
Missoula, MT 59802-2998 Missoula

System Facility ID:32-13405

**Facility Code:** 25746  
**Last Inspected On:** 11/12/2023  
**Operating Permit Renewal Date:** 04/03/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Saint Patricks Hospital

**(406) 543-7271**

**Operator Contact:** Timothy Chopp

**tchopp@saintpatrick.org**

**Owner/Operator:** Saint Patricks Hospital

**(406) 543-7271**

Harry McGuire, UST Class B Operator  
Timothy Chopp, UST Class A Operator  
Timothy Chopp, UST Class B Operator

mtrses@q.com  
tchopp@saintpatrick.org  
tchopp@saintpatrick.org

<b>Tank Code</b>	02	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	08/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	1960	<b>Spill Test Date</b>	11/06/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2500	<b>ATG Test Date</b>	11/06/2023	<b>Line Tightness Test Date</b>	02/12/2021	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300;Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** RANGITSCH BROTHERS 2001 WEST BROADWAY  
2001 W Broadway St  
Missoula, MT 59808-1817 Missoula

System Facility ID:32-09919

**Facility Code:** 25529  
**Last Inspected On:** 08/21/2023  
**Operating Permit Renewal Date:** 10/29/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Rangitsch Brothers (406) 728-4040 service1@rangitschbrosv.com.

**Operator Contact:** Gerry Wolner;Joel Jasperson (406) 721-7561 joelj@rangitschbrosv.com;service1@rangitschbrosv.com.

**Owner/Operator:** Rangitsch Brothers (406) 728-4040 service1@rangitschbrosv.com.  
David Crowder, UST Class B Operator acewheeler65@gmail.com  
Gerry Wolner, UST Class A Operator service1@rangitschbrosv.com.  
Joel Jasperson, UST Class A Operator joelj@rangitschbrosv.com  
Joel Jasperson, UST Class B Operator joelj@rangitschbrosv.com  
Russ Dickey, UST Class B Operator service2@rangitschbrosv.com

<b>Tank Code</b>	03	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	01/01/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3917	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	EMCO Electronics/EECO 1500				

### Facility Summary in Missoula County in the City of Missoula

**Location:** ROSAUERS 127 FUEL STATION  
2350 S Reserve St  
Missoula, MT 59801 Missoula

System Facility ID:60-15318

**Facility Code:** 31015  
**Last Inspected On:** 09/23/2024  
**Operating Permit Renewal Date:** 12/23/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Rosauers Supermarkets Inc Marshall (509) 326-8900 lillig@rosauers.com

---

**Operator Contact:** Dean Hansen;Paco Sutton (406) 721-5430 127mgr@rosauers.com

---

**Owner/Operator:** Rosauers Supermarkets Inc Marshall (509) 326-8900 lillig@rosauers.com

Dean Hansen, UST Class A Operator 127mgr@rosauers.com  
Dean Hansen, UST Class B Operator 127mgr@rosauers.com  
Jerry Kuykendall, UST Class B Global Operator  
Paco Sutton, UST Class A Operator 127mgr@rosauers.com  
Paco Sutton, UST Class B Operator 127mgr@rosauers.com

<b>Tank Code</b>	01	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	06/21/2018	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5814	<b>Spill Test Date</b>	08/31/2021	<b>Piping Installed Date</b>	06/24/2018	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/10/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	20000	<b>ATG Test Date</b>	04/10/2025	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	04/10/2025			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	02	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	06/21/2018	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5815	<b>Spill Test Date</b>	07/25/2024	<b>Piping Installed Date</b>	06/24/2018	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/10/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	9000	<b>ATG Test Date</b>	04/10/2025	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	04/10/2025			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	03	<b>Tank Age</b>	7	<b>Tank Installed Date</b>	06/21/2018	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5816	<b>Spill Test Date</b>	07/25/2024	<b>Piping Installed Date</b>	06/24/2018	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/10/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	6000	<b>ATG Test Date</b>	04/10/2025	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	04/10/2025			<b>ATG Type</b>	Incon/TS-550 EVO				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** SILVER SLIPPER  
4055 Hwy 93 S  
Missoula, MT 59804-7300 Missoula

System Facility ID:32-13711

**Facility Code:** 25780  
**Last Inspected On:** 08/18/2023  
**Operating Permit Renewal Date:** 08/21/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Noah Castle;Preslyn LLC (406) 251-5402 noahcastle@hotmail.com

**Operator Contact:** Melissa Rausch (406) 253-4921 thesilverslippermissoula@gmail.com

**Owner/Operator:** Noah Castle (406) 251-5402 noahcastle@hotmail.com  
**Owner/Operator:** Preslyn LLC (406) 251-5402 noahcastle@hotmail.com  
 Melissa Rausch, UST Class A Operator thesilverslippermissoula@gmail.com  
 Melissa Rausch, UST Class B Operator thesilverslippermissoula@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	29	<b>Tank Installed Date</b>	03/01/1996	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3251	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	02	<b>Tank Age</b>	29	<b>Tank Installed Date</b>	03/01/1996	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3252	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

<b>Tank Code</b>	03	<b>Tank Age</b>	29	<b>Tank Installed Date</b>	03/01/1996	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	3253	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Missoula**

**Location:** SORENSEN TRANSPORT  
6575 US Hwy 10 W  
Missoula, MT 59808-9086 Missoula

System Facility ID:32-13428

**Facility Code:** 25748  
**Last Inspected On:** 05/30/2024  
**Operating Permit Renewal Date:** 10/15/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Sorensen Transport (406) 721-5404 jake@sorco-inc.com

**Operator Contact:** Lane Sorensen (406) 721-5404 Isorensen@trans-system.com

**Owner/Operator:** Sorensen Transport (406) 721-5404 jake@sorco-inc.com

Lane Sorensen, UST Class A Operator  
Lane Sorensen, UST Class B Operator

Isorensen@trans-system.com  
Isorensen@trans-system.com

<b>Tank Code</b>	02	<b>Tank Age</b>	10	<b>Tank Installed Date</b>	06/04/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5576	<b>Spill Test Date</b>	05/30/2024	<b>Piping Installed Date</b>	06/04/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/30/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/30/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	05/30/2024	<b>Line Tightness Test Date</b>	06/03/2015	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	05/30/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				



**Facility Summary in Missoula County in the City of Missoula**

**Location:** SOUTH AVENUE MARKET #11  
2401 S Higgins Ave  
Missoula, MT 59801 Missoula

System Facility ID:32-05764

**Facility Code:** 25381  
**Last Inspected On:** 11/11/2022  
**Operating Permit Renewal Date:** 02/19/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Hi-Star Properties LLC

histarms3@yahoo.com

**Operator Contact:** Manpreet Singh;Hi-Star Properties LLC

(509) 994-6599

sbsm065@gmail.com;histarms3@yahoo.com

**Owner/Operator:** Hi-Star Properties LLC

histarms3@yahoo.com

Manpreet Singh, UST Class A Operator

histarms3@yahoo.com

Manpreet Singh, UST Class B Operator

histarms3@yahoo.com

<b>Tank Code</b>	02	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/26/1981	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3849	<b>Spill Test Date</b>	08/18/2020	<b>Piping Installed Date</b>	07/21/2000	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/30/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/29/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/18/2020			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	03	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/26/1981	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3850	<b>Spill Test Date</b>	08/18/2020	<b>Piping Installed Date</b>	07/21/2000	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/30/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/29/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/18/2020			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				

<b>Tank Code</b>	01	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/26/1981	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4668	<b>Spill Test Date</b>	08/18/2020	<b>Piping Installed Date</b>	07/21/2000	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	02/21/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/30/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/29/2024	<b>Line Tightness Test Date</b>	02/21/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/18/2020			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				

## Facility Summary in Missoula County in the City of Missoula

**Location:** SOUTHGATE MARKET  
1900 South Ave W  
Missoula, MT 59801-6508 Missoula

System Facility ID:32-08862

**Facility Code:** 25477  
**Last Inspected On:** 01/26/2024  
**Operating Permit Renewal Date:** 03/13/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

<b>Owner Operator Contact:</b> Jays Inc DBA Southgate Market	<b>(406) 549-1750</b>	<b>jaysfood08@yahoo.com</b>
<b>Operator Contact:</b> Jagpreet Ghuman;Jays 1 Stop;Jaspal Sandhu;Jays Corporation	<b>(406) 880-7677;(406) 549-1031</b>	<b>jas_sandhu75@hotmail.com;polsonbay@yahoo.com;jaysfood08@outlook.com;jays1stop21@outlook.com</b>

<b>Owner/Operator:</b> Jays Inc DBA Southgate Market	(406) 549-1750	jaysfood08@yahoo.com
Jagpreet Ghuman, UST Class A Operator Jagpreet Ghuman, UST Class A Operator Jagpreet Ghuman, UST Class B Operator Jagpreet Ghuman, UST Class B Operator Jaspal Sandhu, UST Class A Operator Jaspal Sandhu, UST Class B Operator		jays1stop21@outlook.com jays1stop21@outlook.com jays1stop21@outlook.com jays1stop21@outlook.com polsonbay@yahoo.com polsonbay@yahoo.com

<b>Tank Code</b>	01	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	12/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1354	<b>Spill Test Date</b>	01/25/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/25/2024	<b>Tank/Piping CP Test Date</b>	01/25/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	01/25/2024	<b>Line Tightness Test Date</b>	01/28/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/25/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	12/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1355	<b>Spill Test Date</b>	01/25/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	01/25/2024	<b>Tank/Piping CP Test Date</b>	01/25/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	01/25/2024	<b>Line Tightness Test Date</b>	01/28/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	01/25/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	40	<b>Tank Installed Date</b>	12/23/1985	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1356	<b>Spill Test Date</b>	01/25/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	01/25/2024	<b>Tank/Piping CP Test Date</b>	01/25/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	01/25/2024	<b>Line Tightness Test Date</b>	01/28/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/25/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** SPRINT MISSOULA POP  
2515 Railroad St W  
Missoula, MT 59808-1680 Missoula

System Facility ID:56-14010

**Facility Code:** 30670  
**Last Inspected On:** 04/18/2023  
**Operating Permit Renewal Date:** 08/13/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Sprint Communications Co LLP (913) 762-5957

**Operator Contact:** Brian Schmitt; Brian Wiedower (913) 315-8631 brian.c.wiedower@sprint.com; brian.schmitt@bolininc.com

**Owner/Operator:** Sprint Communications Co LLP (913) 762-5957

Brian Schmitt, UST Class A Operator  
Brian Schmitt, UST Class B Operator  
Brian Wiedower, UST Class A Operator  
Matt Santee, UST Class B Global Operator  
Scott Hallesy, UST Class B Operator

brian.schmitt@bolininc.com  
brian.schmitt@bolininc.com  
brian.c.wiedower@sprint.com  
matt.santee@bolininc.com  
scott.g.hallesy@sprint.com

<b>Tank Code</b>	01	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	06/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve; High Level Alarm
<b>Tag Number</b>	4321	<b>Spill Test Date</b>	03/13/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test; Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2500	<b>ATG Test Date</b>	04/24/2024	<b>Line Tightness Test Date</b>	04/18/2023	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/18/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** ST PATRICKS HOSPITAL  
500 W Broadway St  
Missoula, MT 59802-4008 Missoula

System Facility ID:32-04266

**Facility Code:** 25338  
**Last Inspected On:** 11/06/2023  
**Operating Permit Renewal Date:** 05/29/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Saint Patricks Hospital

**(406) 543-7271**

**Operator Contact:** Timothy Chopp

**tchopp@saintpatrick.org**

**Owner/Operator:** Saint Patricks Hospital

**(406) 543-7271**

Timothy Chopp, UST Class A Operator  
Timothy Chopp, UST Class B Operator

tchopp@saintpatrick.org  
tchopp@saintpatrick.org

<b>Tank Code</b>	03	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	10/01/2001	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	4497	<b>Spill Test Date</b>	11/06/2023	<b>Piping Installed Date</b>	02/29/2008	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/06/2023	<b>Line Tightness Test Date</b>	11/06/2023	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300;Veeder Root/TLS-300				
<b>Tank Code</b>	04	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	07/18/2008	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm;Positive Shutoff
<b>Tag Number</b>	5175	<b>Spill Test Date</b>	11/06/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	3-Year Line Tightness Test	<b>Vapor Recovery</b>	No

<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/06/2023	<b>Line Tightness Test Date</b>	11/06/2023	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	11/06/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300;Veeder Root/TLS-300				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** TABISH BROTHERS DISTRIBUTORS INC  
501 Taylor St  
Missoula, MT 59802-4920 Missoula

System Facility ID:32-06523

**Facility Code:** 25407  
**Last Inspected On:** 06/20/2023  
**Operating Permit Renewal Date:** 06/22/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

**Operator Contact:** Heather Stiles hstiles@gwpetrol.com

**Owner/Operator:** Tabish Brothers Distributors Inc (406) 543-7621 lss@gwpetrol.com

Heather Stiles, UST Class A Operator hstiles@gwpetrol.com  
Heather Stiles, UST Class B Global Operator hstiles@gwpetrol.com

<b>Tank Code</b>	01	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/16/1981	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2080	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Heating Oil	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.1;Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7600	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/16/1981	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	2081	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	06/20/2023	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	Gravity Feed	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Oil, Waste	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7600	<b>ATG Test Date</b>	06/20/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No



		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC				
--	--	---------------------------	--	--	--	-----------------	--	--	--	--	--

**Facility Summary in Missoula County in the City of Missoula**

**Location:** THE OLDE DAIRY  
2106 Clements Rd  
Missoula, MT 59804-6212 Missoula

System Facility ID:32-08475

**Facility Code:** 25464  
**Last Inspected On:** 08/16/2023  
**Operating Permit Renewal Date:** 09/03/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Dale Johnson;Target Range Development LLC (406) 721-3322 mark@theolde dairy.com

**Operator Contact:** Jessica Rogers;Target Range Development LLC (406) 721-3322 jessica@theolde dairy.com;mark@theolde dairy.com

**Owner/Operator:** Dale L Johnson (406) 721-3322

**Owner/Operator:** Target Range Development LLC (406) 721-3322

Jessica Rogers, UST Class A Operator  
Jessica Rogers, UST Class B Operator

mark@theolde dairy.com  
mark@theolde dairy.com

<b>Tank Code</b>	05	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	03/23/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4086	<b>Spill Test Date</b>	08/16/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/20/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				
<b>Tank Code</b>	06	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	03/23/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4087	<b>Spill Test Date</b>	08/16/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/14/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	07/20/2024	<b>Line Tightness Test Date</b>	02/01/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	07/20/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				
<b>Tank Code</b>	07	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	03/23/1999	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4088	<b>Spill Test Date</b>	08/16/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	07/20/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/20/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** TOWN PUMP INC MISSOULA 1  
5310 Grant Creek Rd  
Missoula, MT 59808-1483 Missoula

System Facility ID:32-13336

**Facility Code:** 25739  
**Last Inspected On:** 06/09/2023  
**Operating Permit Renewal Date:** 10/28/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 1 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Missoula 1 Town Pump LLC (406) 497-6700 environmental@townpump.com

Trent Biggers, UST Class A Operator Trentb@townpump.com  
Trent Biggers, UST Class B Global Operator Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	12/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2342	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	03/19/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	12/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2343	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	03/19/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	6000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

<b>Tank Code</b>	03	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	12/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2344	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	03/19/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	04	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	12/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2345	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	03/19/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	05	<b>Tank Age</b>	16	<b>Tank Installed Date</b>	01/25/2009	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5196	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/25/2009	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/04/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	01/11/2010	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	20000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	06	<b>Tank Age</b>	16	<b>Tank Installed Date</b>	01/25/2009	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5197	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	01/25/2009	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/04/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/04/2021	<b>Tank/Piping CP Test Date</b>	01/11/2010	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** TOWN PUMP INC MISSOULA 2  
318 S Orange St  
Missoula, MT 59801-1811 Missoula

System Facility ID:32-08715

**Facility Code:** 25471  
**Last Inspected On:** 06/20/2023  
**Operating Permit Renewal Date:** 10/29/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 2 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Missoula 2 Town Pump LLC (406) 497-6700 environmental@townpump.com

Trent Biggers, UST Class A Operator	Trentb@townpump.com
Trent Biggers, UST Class A Operator	Trentb@townpump.com
Trent Biggers, UST Class B Global Operator	Trentb@townpump.com
Trent Biggers, UST Class B Global Operator	Trentb@townpump.com

<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	05/24/1990	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2552	<b>Spill Test Date</b>	10/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/05/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/12/2023	<b>Tank/Piping CP Test Date</b>	05/04/2021	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/20/2023	<b>Line Tightness Test Date</b>	05/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/04/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	05/29/1990	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2553	<b>Spill Test Date</b>	07/11/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/12/2023	<b>Tank/Piping CP Test Date</b>	05/04/2021	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/20/2023	<b>Line Tightness Test Date</b>	05/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	07/11/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	06	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	05/29/1990	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2554	<b>Spill Test Date</b>	07/11/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/12/2023	<b>Tank/Piping CP Test Date</b>	05/04/2021	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/20/2023	<b>Line Tightness Test Date</b>	05/12/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/11/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				



**Facility Summary in Missoula County in the City of Missoula**

**Location:** TOWN PUMP INC MISSOULA 3  
2210 N Reserve St  
Missoula, MT 59808-1323 Missoula

System Facility ID:32-13172

**Facility Code:** 25725  
**Last Inspected On:** 06/20/2023  
**Operating Permit Renewal Date:** 10/30/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 3 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Missoula 3 Town Pump LLC (406) 497-6700 environmental@townpump.com  
 Trent Biggers, UST Class A Operator Trentb@townpump.com  
 Trent Biggers, UST Class A Operator Trentb@townpump.com  
 Trent Biggers, UST Class B Global Operator Trentb@townpump.com  
 Trent Biggers, UST Class B Global Operator Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2559	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	07/09/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/05/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/22/2006	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2560	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/05/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/22/2006	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	03	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2561	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	05/05/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/30/2006	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	04	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2562	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/05/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/30/2006	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	05	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	06/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	2563	<b>Spill Test Date</b>	10/04/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	05/05/2021	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	09/30/2006	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/04/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** TOWN PUMP INC MISSOULA 8  
3420 Mullan Rd Ste A  
Missoula, MT 59808-5126 Missoula

System Facility ID:56-13823

**Facility Code:** 30509  
**Last Inspected On:** 06/21/2023  
**Operating Permit Renewal Date:** 06/21/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 8 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Missoula 8 Town Pump LLC (406) 497-6700 environmental@townpump.com

Trent Biggers, UST Class A Operator Trentb@townpump.com  
Trent Biggers, UST Class B Global Operator Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1444	<b>Spill Test Date</b>	07/18/2022	<b>Piping Installed Date</b>	05/24/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/21/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/21/2023	<b>Line Tightness Test Date</b>	05/05/2016	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/18/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1445	<b>Spill Test Date</b>	07/18/2022	<b>Piping Installed Date</b>	05/24/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/21/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	06/21/2023	<b>Line Tightness Test Date</b>	05/18/2016	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/18/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

<b>Tank Code</b>	03	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/01/1997	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1446	<b>Spill Test Date</b>	07/18/2022	<b>Piping Installed Date</b>	05/24/2016	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/21/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	06/21/2023	<b>Line Tightness Test Date</b>	05/17/2016	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/18/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	04	<b>Tank Age</b>	9	<b>Tank Installed Date</b>	05/24/2016	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5629	<b>Spill Test Date</b>	07/18/2022	<b>Piping Installed Date</b>	05/24/2016	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	04/27/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/21/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	06/21/2023	<b>Line Tightness Test Date</b>	05/18/2016	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/18/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** TOWN PUMP MISSOULA 9  
2001 Brooks St  
Missoula, MT 59808 Missoula

System Facility ID:60-15288

**Facility Code:** 30995  
**Last Inspected On:** 06/22/2023  
**Operating Permit Renewal Date:** 06/22/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Missoula 9 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Missoula 9 Town Pump LLC (406) 497-6700 environmental@townpump.com

Trent Biggers, UST Class A Operator Trentb@townpump.com  
Trent Biggers, UST Class B Operator Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	8	<b>Tank Installed Date</b>	03/28/2017	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5683	<b>Spill Test Date</b>	07/12/2022	<b>Piping Installed Date</b>	03/28/2017	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/10/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	25000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				
<b>Tank Code</b>	02	<b>Tank Age</b>	8	<b>Tank Installed Date</b>	03/28/2017	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5684	<b>Spill Test Date</b>	07/12/2022	<b>Piping Installed Date</b>	03/28/2017	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/10/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	15000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

<b>Tank Code</b>	03	<b>Tank Age</b>	8	<b>Tank Installed Date</b>	03/28/2017	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5685	<b>Spill Test Date</b>	07/12/2022	<b>Piping Installed Date</b>	03/28/2017	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	05/10/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	06/22/2023	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	06/22/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** UNITED PARCEL SERVICES MISSOULA  
221 Expressway Ln  
Missoula, MT 59808-1553 Missoula

System Facility ID:32-04536

**Facility Code:** 25343  
**Last Inspected On:** 04/18/2022  
**Operating Permit Renewal Date:** 10/11/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** United Parcel Service Inc Seattle

**cdd6jxd@ups.com**

**Operator Contact:** Dino Ostrow;Jonathan Dunbar;United Parcel Service Inc Seattle

**(503) 329-7154**

**dostrow@ups.com;jxdunbar@ups.com;cdd6jxd@ups.com**

**Owner/Operator:** United Parcel Service Inc Seattle

cdd6jxd@ups.com

Dino Ostrow, UST Class A Operator

dostrow@ups.com

Dino Ostrow, UST Class A Operator

dostrow@ups.com

Dino Ostrow, UST Class B Operator

dostrow@ups.com

Dino Ostrow, UST Class B Operator

dostrow@ups.com

Jonathan Dunbar, UST Class A Operator

cdd6jxd@ups.com

Jonathan Dunbar, UST Class B Operator

cdd6jxd@ups.com

<b>Tank Code</b>	04	<b>Tank Age</b>	32	<b>Tank Installed Date</b>	07/01/1993	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2182	<b>Spill Test Date</b>	04/18/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	04/18/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	04/18/2022	<b>Line Tightness Test Date</b>	04/18/2022	<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/26/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** WESTERN TRANSPORT  
9310 Cartage Rd  
Missoula, MT 59808-9758 Missoula

System Facility ID:32-01348

**Facility Code:** 25211  
**Last Inspected On:** 05/11/2022  
**Operating Permit Renewal Date:** 06/09/2025

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Western Land Investments LLC

**(307) 674-6305**

**Operator Contact:** Cari Goss

**(307) 674-6305**

**cari@westerntransllc.com**

**Owner/Operator:** Western Land Investments LLC

**(307) 674-6305**

Cari Goss, UST Class A Operator

cari@westerntransllc.com

<b>Tank Code</b>	01	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	01/17/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1654	<b>Spill Test Date</b>	09/29/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	09/29/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	09/30/2021	<b>Line Tightness Test Date</b>	09/12/2012	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-250				
<b>Tank Code</b>	02	<b>Tank Age</b>	57	<b>Tank Installed Date</b>	01/17/1968	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	1655	<b>Spill Test Date</b>	09/29/2021	<b>Piping Installed Date</b>	12/11/2006	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	03/22/2022	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	09/29/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	09/30/2021	<b>Line Tightness Test Date</b>	03/22/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-250				
<b>Tank Code</b>	03	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	01/16/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	High Level Alarm



<b>Tag Number</b>	1656	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	12/11/2006	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	09/29/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	05/27/2010	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Veeder Root/TLS-250				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** WESTFIELD MISSOULA  
8448 US Hwy 10 W  
Missoula, MT 59808-9319 Missoula

System Facility ID:32-13674

**Facility Code:** 25776  
**Last Inspected On:** 05/01/2023  
**Operating Permit Renewal Date:** 07/22/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Finest Oil Co (406) 543-6969

**Operator Contact:** Christopher Glasser;David Peyton;James Brady;James DeWaters;Justin Gaudot;Stephen Hanson (406) 218-1563;(406) 360-6327;(406) 543-6969;(406) 544-1005;(714) 333-8926 chrisglasser@hotmail.com;finestoil@finest-oil.com;jeepin247.jb@gmail.com;justgaudot@yahoo.com;rivban22@gmail.com

**Owner/Operator:** Finest Oil Co (406) 543-6969

Christopher Glasser, UST Class A Operator	chrisglasser@hotmail.com
David Peyton, UST Class A Operator	
David Peyton, UST Class B Global Operator	
James Brady, UST Class A Operator	jeepin247.jb@gmail.com
James DeWaters, UST Class A Operator	rivban22@gmail.com
Joseph McClain, UST Class B Operator	jgmccclain25@gmail.com
Justin Gaudot, UST Class A Operator	justgaudot@yahoo.com
Justin Gaudot, UST Class B Global Operator	justgaudot@yahoo.com
Stephen Hanson, UST Class A Operator	finestoil@finest-oil.com
Stephen Hanson, UST Class B Operator	finestoil@finest-oil.com

<b>Tank Code</b>	01	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1077	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	04/28/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1078	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>	04/28/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1079	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>	09/19/2007	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	04/28/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	04	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1080	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	04/28/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	05	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1081	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>	05/17/2012	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	12000	<b>ATG Test Date</b>	04/28/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	06	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	12/01/1995	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1082	<b>Spill Test Date</b>	04/28/2023	<b>Piping Installed Date</b>	05/17/2012	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/28/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	04/25/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/28/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** YOKES FRESH MARKET 21  
800 W Broadway St  
Missoula, MT 59802-3944 Missoula

System Facility ID:60-15098

**Facility Code:** 30858  
**Last Inspected On:** 04/09/2024  
**Operating Permit Renewal Date:** 06/11/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** YOKE'S FOOD INC (509) 921-2292

**Operator Contact:** Rebecca Spicer;Rich Thornock;Shari Goodmanson (406) 251-7170;(406) 721-2549

fuelmgr21@yokesfoods.com;MRMBR@YOKESFOODS.COM;sgoodmanson@yokesfoods.com

**Owner/Operator:** YOKE'S FOOD INC (509) 921-2292

Rebecca Spicer, UST Class A Operator  
Rebecca Spicer, UST Class B Operator  
Rich Thornock, UST Class A Operator  
Rich Thornock, UST Class B Operator  
Shari Goodmanson, UST Class A Operator  
Shari Goodmanson, UST Class B Global Operator

fuelmgr21@yokesfoods.com  
fuelmgr21@yokesfoods.com  
MRMBR@YOKESFOODS.COM  
MRMBR@YOKESFOODS.COM  
sgoodmanson@yokesfoods.com  
sgoodmanson@yokesfoods.com

<b>Tank Code</b>	01	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	08/08/2008	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5167	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	07/01/2008	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	04/09/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	04/09/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	08/01/2008	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5168	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	07/01/2008	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	04/09/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No

<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/09/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	08/01/2008	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	5169	<b>Spill Test Date</b>	04/09/2024	<b>Piping Installed Date</b>	07/01/2008	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	04/09/2024	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	04/09/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC;OPW / EMCO/TLS-350				

### Facility Summary in Missoula County in the City of Missoula

**Location:** YOKES FRESH MARKET 22  
3801 S Reserve St  
Missoula, MT 59801-7322 Missoula

System Facility ID:56-14025

**Facility Code:** 30684  
**Last Inspected On:** 07/12/2022  
**Operating Permit Renewal Date:** 01/04/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** YOKE'S FOOD INC (509) 921-2292

**Operator Contact:** Brittany Zeller;Charles Franklin;Jason Rhinehart;YOKE'S FOOD INC;Shari Goodmanson (406) 251-3311;(406) 251-7170;(509) 921-2292 mrasst@yokesfoods.com;MRMGR@YOKESFOODS.COM;pipsnchips2@gmail.com;sgoodmanson@yokesfoods.com

**Owner/Operator:** YOKE'S FOOD INC (509) 921-2292

Brittany Zeller, UST Class A Operator  
Charles Franklin, UST Class A Operator  
Charles Franklin, UST Class B Global Operator  
Jason Rhinehart, UST Class A Operator  
Shari Goodmanson, UST Class A Operator  
Shari Goodmanson, UST Class B Global Operator

MRMGR@YOKESFOODS.COM  
pipsnchips2@gmail.com  
pipsnchips2@gmail.com  
mrasst@yokesfoods.com  
sgoodmanson@yokesfoods.com  
sgoodmanson@yokesfoods.com

<b>Tank Code</b>	01	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	09/01/2001	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4416	<b>Spill Test Date</b>	10/19/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/12/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	07/12/2022	<b>Line Tightness Test Date</b>	01/16/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	02	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	09/01/2001	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4417	<b>Spill Test Date</b>	07/12/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/12/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/12/2022	<b>Line Tightness Test Date</b>	01/17/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				
<b>Tank Code</b>	03	<b>Tank Age</b>	24	<b>Tank Installed Date</b>	09/01/2001	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Ball Float Valve;High Level Alarm
<b>Tag Number</b>	4418	<b>Spill Test Date</b>	07/12/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	07/12/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/12/2022	<b>Line Tightness Test Date</b>	07/09/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/12/2022			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350				



**Facility Summary in Missoula County in the City of Missoula**

**Location:** ZIP TRIP 31  
3325 Brooks St  
Missoula, MT 59801-8289 Missoula

System Facility ID:32-09730

**Facility Code:** 25516  
**Last Inspected On:** 02/05/2025  
**Operating Permit Renewal Date:** 05/20/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** CHS Inc Spokane Valley (509) 535-7701 Donald.Widdicombe@chsinc.com

**Operator Contact:** Jim Alford;Sean Hurley (509) 535-7701;(509) 536-7418 jim.alford@chsinc.com;sean.hurley@chsinc.com

**Owner/Operator:** CHS Inc Spokane Valley (509) 535-7701 Donald.Widdicombe@chsinc.com

Jason Brenner, UST Class B Operator  
Jim Alford, UST Class A Operator  
Jim Alford, UST Class B Operator  
Luci Tuttle, UST Class B Operator  
Sean Hurley, UST Class A Operator

jason.brenner@chsinc.com  
jim.alford@chsinc.com  
jim.alford@chsinc.com  
Lucinda.Tuttle@chsinc.com  
sean.hurley@chsinc.com

<b>Tank Code</b>	01	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	03/18/1988	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1363	<b>Spill Test Date</b>	02/05/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/04/2010	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	08/06/2024	<b>Line Tightness Test Date</b>	08/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/06/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	03/18/1988	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1364	<b>Spill Test Date</b>	02/05/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/06/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	08/06/2024	<b>Line Tightness Test Date</b>	08/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	02/05/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	37	<b>Tank Installed Date</b>	03/18/1988	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1365	<b>Spill Test Date</b>	02/05/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/06/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	08/04/2010	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	08/06/2024	<b>Line Tightness Test Date</b>	08/06/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/05/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** ZIP TRIP 32  
1540 Toole Ave  
Missoula, MT 59802-2241 Missoula

System Facility ID:32-03912

**Facility Code:** 25317  
**Last Inspected On:** 10/27/2022  
**Operating Permit Renewal Date:** 02/04/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** CHS Inc Spokane Valley (509) 535-7701 Donald.Widdicombe@chsinc.com

**Operator Contact:** Jim Alford;Sean Hurley (509) 535-7701;(509) 536-7418 jim.alford@chsinc.com;sean.hurley@chsinc.com

**Owner/Operator:** CHS Inc Spokane Valley (509) 535-7701 Donald.Widdicombe@chsinc.com

- |                                     |                           |
|-------------------------------------|---------------------------|
| Jason Brenner, UST Class B Operator | jason.brenner@chsinc.com  |
| Jim Alford, UST Class A Operator    | jim.alford@chsinc.com     |
| Jim Alford, UST Class A Operator    | jim.alford@chsinc.com     |
| Jim Alford, UST Class B Operator    | jim.alford@chsinc.com     |
| Jim Alford, UST Class B Operator    | jim.alford@chsinc.com     |
| Luci Tuttle, UST Class B Operator   | Lucinda.Tuttle@chsinc.com |
| Sean Hurley, UST Class A Operator   | sean.hurley@chsinc.com    |
| Sean Hurley, UST Class A Operator   | sean.hurley@chsinc.com    |

<b>Tank Code</b>	01	<b>Tank Age</b>	41	<b>Tank Installed Date</b>	03/22/1984	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1342	<b>Spill Test Date</b>	01/13/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/27/2022	<b>Tank/Piping CP Test Date</b>	07/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/27/2022	<b>Line Tightness Test Date</b>	07/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/13/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	41	<b>Tank Installed Date</b>	03/22/1984	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1343	<b>Spill Test Date</b>	01/13/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic

<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/27/2022	<b>Tank/Piping CP Test Date</b>	07/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/27/2022	<b>Line Tightness Test Date</b>	07/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/13/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	03	<b>Tank Age</b>	41	<b>Tank Installed Date</b>	03/22/1984	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1344	<b>Spill Test Date</b>	08/31/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	07/27/2022	<b>Tank/Piping CP Test Date</b>	07/27/2022	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/27/2022	<b>Line Tightness Test Date</b>	07/27/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	08/31/2021			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** ZOOTOWN SUPER STOP  
2105 S Higgins Ave  
Missoula, MT 59801-6714 Missoula

System Facility ID:32-07244

**Facility Code:** 25429  
**Last Inspected On:** 12/20/2023  
**Operating Permit Renewal Date:** 03/13/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Greg Tabish (406) 728-2575 zootown@gwpetrol.com

**Operator Contact:** Daniel Marx;Erin Keffeler;Karly Shafer;Yvonne Bunch (406) 274-2435;(406) 396-2206;(406) 880-0056 DanielMarx@inmissoula.com;karly@gwpetrol.com;noons470@hi-noon.com;ybunch1@gmail.com

**Owner/Operator:** Greg Tabish (406) 728-2575 zootown@gwpetrol.com

Daniel Marx, UST Class A Operator DanielMarx@inmissoula.com  
 Daniel Marx, UST Class B Global Operator DanielMarx@inmissoula.com  
 Erin Keffeler, UST Class A Operator noons470@hi-noon.com  
 Erin Keffeler, UST Class B Operator noons470@hi-noon.com  
 Karly Shafer, UST Class A Operator karly@gwpetrol.com  
 Karly Shafer, UST Class B Global Operator karly@gwpetrol.com  
 Yvonne Bunch, UST Class A Operator ybunch1@gmail.com  
 Yvonne Bunch, UST Class B Operator ybunch1@gmail.com

<b>Tank Code</b>	03	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	12/07/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1799	<b>Spill Test Date</b>	12/20/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/20/2023	<b>Tank/Piping CP Test Date</b>	12/20/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	12/20/2023	<b>Line Tightness Test Date</b>	07/13/2011	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/20/2023			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	04	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	12/07/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1800	<b>Spill Test Date</b>	12/20/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	12/20/2023	<b>Tank/Piping CP Test Date</b>	12/20/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No

<b>Capacity</b>	6000	<b>ATG Test Date</b>	12/20/2023	<b>Line Tightness Test Date</b>	07/13/2011	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/20/2023			<b>ATG Type</b>	Gilbarco/EMC Basic				
<b>Tank Code</b>	05	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	12/07/1990	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	1801	<b>Spill Test Date</b>	12/20/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	12/20/2023	<b>Tank/Piping CP Test Date</b>	12/20/2023	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	12/20/2023	<b>Line Tightness Test Date</b>	07/13/2011	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/20/2023			<b>ATG Type</b>	Gilbarco/EMC Basic				

**Facility Summary in Missoula County in the City of Missoula**

**Location:** ZOOTOWN SUPER STOP 2  
2125 S Higgins Ave  
Missoula, MT 59801-6760 Missoula

System Facility ID:32-10053

**Facility Code:** 25541  
**Last Inspected On:** 01/19/2024  
**Operating Permit Renewal Date:** 01/19/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Great Western Petroleum (406) 728-7736

**Operator Contact:** Karly Shafer (406) 396-2206 karly@gwpetrol.com

**Owner/Operator:** Great Western Petroleum (406) 728-7736

Karly Shafer, UST Class A Operator  
Karly Shafer, UST Class A Operator  
Karly Shafer, UST Class B Operator  
Karly Shafer, UST Class B Operator

karly@gwpetrol.com  
karly@gwpetrol.com  
karly@gwpetrol.com  
karly@gwpetrol.com

<b>Tank Code</b>	08	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/30/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2139	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	12/02/2020	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	12/02/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				
<b>Tank Code</b>	09	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/30/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2140	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>	12/02/2020	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	12/02/2020	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				

<b>Tank Code</b>	10	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	09/30/1990	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2141	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	3000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/15/2018	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-300				
<b>Tank Code</b>	11	<b>Tank Age</b>	0	<b>Tank Installed Date</b>		<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	6200	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>		<b>AST</b>	No
<b>Tank Status</b>	Under Construction	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>				<b>ATG Type</b>					



### Facility Summary in Missoula County in the City of Seeley Lake

**Location:** 1 STOP SEELEY LAKE  
3072 MT Hwy 83  
Seeley Lake, MT 59868 Missoula

System Facility ID:32-09288

**Facility Code:** 25483  
**Last Inspected On:** 04/10/2024  
**Operating Permit Renewal Date:** 08/22/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** MONTANA GAS N SHOP LLC (510) 714-5045 TONY@MONTANAGNS.COM

---

**Operator Contact:** Gurinderbir Muhar (408) 660-9884 gasnshop133@gmail.com

---

**Owner/Operator:** MONTANA GAS N SHOP LLC (510) 714-5045 TONY@MONTANAGNS.COM

Gurinderbir Muhar, UST Class A Operator  
Gurinderbir Muhar, UST Class B Operator

gasnshop133@gmail.com  
gasnshop133@gmail.com

<b>Tank Code</b>	S1	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	04/22/1987	<b>Tank Material</b>		<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	416	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	10/17/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/17/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S2	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	04/22/1987	<b>Tank Material</b>		<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	417	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	10/17/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/17/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S3	<b>Tank Age</b>	38	<b>Tank Installed Date</b>	04/22/1987	<b>Tank Material</b>		<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	418	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Single Walled	<b>AST</b>	Yes

<b>Tank Status</b>	<b>Currently in Use</b>	<b>MLLD Test Date</b>	10/17/2023	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/17/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Seeley Lake**

**Location:** LINDEYS LANDING WEST SPB  
 MT Hwy 83  
 Seeley Lake, MT 59868 Missoula

System Facility ID:32-05837

**Facility Code:** 25389  
**Last Inspected On:** 06/24/2023  
**Operating Permit Renewal Date:** 10/17/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Lindeys Inc Saint Paul (406) 677-9229

**Operator Contact:** Michael Lindemer (406) 677-4101 lindeys@blackfoot.net

**Owner/Operator:** Lindeys Inc Saint Paul (406) 677-9229

Michael Lindemer, UST Class A Operator  
 Michael Lindemer, UST Class B Operator  
 Tanner Stevenson, UST Class B Global Operator

lindeys@blackfoot.net  
 lindeys@blackfoot.net  
 jenco1992@gmail.com

<b>Tank Code</b>	S3	<b>Tank Age</b>	26	<b>Tank Installed Date</b>	05/01/1999	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	4104	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/22/2024	<b>Sump Tightness Test Date</b>	06/24/2023	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	1500	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/25/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Missoula County in the City of Seeley Lake**

**Location:** ROVEROS  
3182 Hwy 83  
Seeley Lake, MT 59868 Missoula

System Facility ID:60-15146

**Facility Code:** 30890  
**Last Inspected On:** 10/18/2022  
**Operating Permit Renewal Date:** 01/28/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Greg Tabish;Tabish Brothers Distributors Inc (406) 543-7621;(406) 728-2575 [iss@gwpetrol.com](mailto:iss@gwpetrol.com);[zootown@gwpetrol.com](mailto:zootown@gwpetrol.com)

**Operator Contact:** Karly Shafer;Kyle Marx (406) 396-2206;(406) 396-2296 [karly@gwpetrol.com](mailto:karly@gwpetrol.com);[roverosace@yahoo.com](mailto:roverosace@yahoo.com)

**Owner/Operator:** Greg Tabish (406) 728-2575 [zootown@gwpetrol.com](mailto:zootown@gwpetrol.com)

**Owner/Operator:** Tabish Brothers Distributors Inc (406) 728-2575 [zootown@gwpetrol.com](mailto:zootown@gwpetrol.com)

Karly Shafer, UST Class A Operator [karly@gwpetrol.com](mailto:karly@gwpetrol.com)  
 Karly Shafer, UST Class B Global Operator [karly@gwpetrol.com](mailto:karly@gwpetrol.com)  
 Kyle Marx, UST Class A Operator [roverosace@yahoo.com](mailto:roverosace@yahoo.com)  
 Kyle Marx, UST Class B Global Operator [roverosace@yahoo.com](mailto:roverosace@yahoo.com)  
 RaeDean Bartlett, UST Class B Global Operator [raedean68@gmail.com](mailto:raedean68@gmail.com)

<b>Tank Code</b>	07	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3337	<b>Spill Test Date</b>	10/18/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	08	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3338	<b>Spill Test Date</b>	10/18/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	09	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3339	<b>Spill Test Date</b>	01/23/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	10	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3340	<b>Spill Test Date</b>	10/18/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	11	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3341	<b>Spill Test Date</b>	01/23/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	12	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3342	<b>Spill Test Date</b>	01/23/2023	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	13	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/01/1995	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3343	<b>Spill Test Date</b>	10/18/2022	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	2000	<b>ATG Test Date</b>	10/14/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	01/23/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				

**Facility Summary in Missoula County in the City of TURAH**

**Location:** TURAH STORE and CAMPGROUND  
13555 Turah Rd  
TURAH, MT 59825-9775 Missoula

System Facility ID:32-04899

**Facility Code:** 25351  
**Last Inspected On:** 09/09/2019  
**Operating Permit Renewal Date:** 11/01/2022

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Turah Store and Campground LLC

**(406) 258-9773**

**Operator Contact:** Kathleen Marshall

**turahrvpark@aol.com**

Jerry Kinney, UST Class B Operator  
Jerry Kinney, UST Class B Operator  
Kathleen Marshall, UST Class A Operator  
Kathleen Marshall, UST Class B Global Operator  
Pamela Asbridge, UST Class B Operator  
Pamela Asbridge, UST Class B Operator

turahrvpark@aol.com  
turahrpark@aol.com  
turahrpark@aol.com  
turahrpark@aol.com  
1959pamz@optimum.net  
1959pamz@optimum.net

<b>Tank Code</b>	01	<b>Tank Age</b>	53	<b>Tank Installed Date</b>	04/18/1972	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4007	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/17/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	6000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/10/2007	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	02	<b>Tank Age</b>	53	<b>Tank Installed Date</b>	04/18/1972	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Steel	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4008	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Permanently Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/17/2019	<b>Primary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No

<b>Capacity</b>	2000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	10/10/2007	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					