

**APPENDIX D**  
**SURFACE WATER RUNOFF MANAGEMENT FACILITIES**  
**SUMMER 2013 PHOTOS**

OTTER CREEK MINE - BASELINE REPORT 325A

**APPENDIX D**

**PHOTOS OF SURFACE WATER RUNOFF MANAGEMENT STRUCTURES,  
SEPTEMBER, 2013**

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



1. Ditches channeling runoff from upper Otter Creek.



2. Upper Otter Creek spreader dike.



3. Upper Otter Creek spreader dikes.



4. Upper Otter Creek spreader dikes.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



5. Otter Creek at mouth of 15-Mile Creek; spreader dikes.



6. Otter Creek at mouth of 15-Mile Creek; dike along Otter Creek.



7. Tenmile Creek looking south; dike along Otter Creek.



8. Tenmile Creek looking south; spreader dikes & dike along Otter Creek.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



9. Tenmile Creek looking west from CNF boundary.



10. Tenmile Creek looking SW below CNF boundary. Dike below pond.



11. Tenmile Creek looking west toward Otter Creek.



12. Otter Creek looking downstream from Tenmile Creek road; no diking.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



13. Dikes in field below mouth of Chromo Creek.



14. Dikes in field below mouth of Chromo Creek.



15. Chromo Creek culvert.



16. Spreader dikes E of Otter Crk below Tenmile Crk; dike along Otter Crk.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



17. Lower end of dike directing Gene Creek flow to Otter Creek fields.



18. See Photo 17 caption; spreader dike. Note Culvert.



19. Gene Creek diversion dike below highway culvert.



20. Otter Creek dike north of Gene Creek mouth.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



21. Spreader dikes below E side drainage in back. Otter Crk dike in front.



22. Spreader dikes capturing flow from east side drainages.



23. Spreader dike on west side of Otter Creek below small side drainage.



24. Dike along west side of Otter Creek at lower crossing.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



25. Spreader dike on east side of Otter Creek at lower crossing.



26. Spreader dikes below Newell Creek; AVF8P1 in foreground.



27. Dikes along Otter Creek.



28. Dikes along Otter Creek.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



29. Dikes along Otter Creek.



30. Dike along west side of Otter Creek at Badgett crossing.



31. Dike along east side of Otter Creek at Badgett crossing.



32. Otter Creek below Badgett house. Very wet with little if any diking.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



33. Dike on west side of Otter Creek south of old house.



34. Dike along edge of upper terrace below side drainage.



35. Dike along edge of upper terrace below side drainage looking south.



36. Dike along W side of Otter Creek below diked upper terrace looking south.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



37. Dike along upper terrace below side drainage looking north.



38. Otter creek downstream from Stevens crossing; no dikes.



39. Otter Creek looking downstream from Gratwohl house. No dikes.



40. Spreader dike and dike along Otter Creek west of road.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



41. West of Road; no dikes along Otter Creek.



42. Spreader dikes on higher terraces south of East Fork.



43. Dike on lower edge of upper terrace south of East Fork.



44. Dike at mouth of Fortune Coulee diverting flow to a field to N.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



45. Dike at mouth of Fortune Coulee diverting flow to field to south.



46. Diversion outlet into field at mouth of Fortune Coulee. Well AVF4-2 and Piezometer AVF4-P5 at edge of field.



47. Ditch diverting flow away from Otter Creek and into another field below.



48. Direct view of diversion outlet shown on Photo 46.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



49. Dike on east side of Otter Creek at Badgett crossing looking south.



50. Spreader dike below mouth of east side drainage below Badgett crossing.



51. Dike at mouth of W side drainage diverting flow away from Otter Creek.



52. Mouth of Threemile Creek looking upstream; dike visible.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



53. Close-up view of dike near mouth of Threemile Creek.



54. Diversion ditch from overflow of Pond 4 to field on upper bench on upper Threemile Creek.



55. Outlet of diversion shown in Photo 54; dike along lower edge.



56. Spreader dike at lower edge of uppermost field on Threemile Creek.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



57. Second dike on Threemile Creek below Photo 56.



58. Third dike.



59. Fourth and fifth dikes. Note dike along lower edge of field in background.



60. Upper Threemile Creek below Section 12.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



61. Threemile Creek above Stevens corrals.



62. Threemile Creek below Stevens corrals.



63. Dam and spreader dikes below south side drainage on Home Creek.



64. Dam and diversion/spreader dikes below S side drainage on Home Creek.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



65. Dike at lower edge of field shown in Photos 63 and 64.



66. Diversion dike on lower Home creek diverting entire flow.



67. Diversion dike on lower Home creek looking downstream.



68. Perpendicular dike with head gate below Photo 67.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



69. Ditch below head gate.



70. Ditch looking upstream.



71. Ditch looking downstream to outlet at upper edge of field.



72. Interception of side drainage by lower Home Creek ditch.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



73. Spreader and lower dikes along Home Creek.



74. Spreader/diversion dike below side drainage on south side of Home Creek just below Stevens barn.



75. Another view of spreader/diversion dike shown in Photo 74.



76. Home Creek spreader dikes.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



77. Home Creek spreader dikes.



78. Home Creek spreader dikes.



79. Spreader dikes below upper Home Creek side drainage.



80. Spreader dikes below upper Home Creek side drainage (below Photo 79).

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



81. Spreader dikes below upper Home Creek side drainage (below Photo 80).



82. Spreader dikes below upper Home Creek side drainage (below Photo 81).



83. Spreader dikes below upper Home Creek side drainage (below Photo 82).



84. Spreader dikes in upper Home Crk side drainage just above Stevens barn.

APPENDIX D. Photos of Surface Water Runoff Management Structures, September 2013.



85. Dike across ephemeral tributary of Home Creek diverting flow to hay field.



86. Spreader/interception dike along W side of Otter Crk (from Hwy 212).