

Soda Butte Creek upstream of McLaren Tailings  
September 30, 2008



MDEQ-AML  
McLaren Tailings  
photo 1/18



Soda Butte Creek upstream of McLaren Tailings  
May 14, 2009



MDEQ-AML  
McLaren Tailings  
photo 2/18

Existing soil cap over tailings impoundment  
June 19, 2008



MDEQ-AML  
McLaren Tailings  
photo 3/18



Excavated tailings for characterization  
September 11, 2008



MDEQ-AML  
McLaren Tailings  
photo 4/18



Excavated tailings for characterization  
September 11, 2008



MDEQ-AML  
McLaren Tailings  
photo 5/18



Iron stained alluvial sediments underlying tailings  
September 11, 2008



MDEQ-AML  
McLaren Tailings  
photo 6/18



Seep discharging below tailings dam  
September 8, 2008



MDEQ-AML  
McLaren Tailings  
photo 7/18



Acid mine drainage discharging from north end of tailings dam  
July 10, 2008



MDEQ-AML  
McLaren Tailings  
photo 8/18



Acid mine drainage discharging to Soda Butte Creek  
July 10, 2008



MDEQ-AML  
McLaren Tailings  
photo 9/18



Acid mine drainage discharging to Soda Butte Creek  
September 8, 2008



MDEQ-AML  
McLaren Tailings  
photo 10/18



Acid mine drainage discharging from south end of tailings dam  
May 14, 2009



MDEQ-AML  
McLaren Tailings  
photo 11/18



Acid mine drainage discharging from south end of tailings dam  
May 14, 2009



MDEQ-AML  
McLaren Tailings  
photo 12/18



Acid Mine Drainage discharging from McLaren Tailings  
May 14, 2009



MDEQ-AML  
McLaren Tailings  
photo 13/18



Seep discharging to Soda Butte Creek  
September 18, 2008



MDEQ-AML  
McLaren Tailings  
photo 14/18



Seep discharging to Soda Butte Creek  
September 18, 2008



MDEQ-AML  
McLaren Tailings  
photo 15/18



Iron staining in Soda Butte Creek downstream of McLaren Tailings  
May 14, 2009



MDEQ-AML  
McLaren Tailings  
photo 16/18



Iron staining in Soda Butte Creek downstream of McLaren Tailings  
September 8, 2008



MDEQ-AML  
McLaren Tailings  
photo 17/18



Iron staining in Soda Butte Creek downstream of McLaren Tailings  
September 8, 2008



MDEQ-AML  
McLaren Tailings  
photo 18/18