

Cross-Section of Underground Workings Showing Hydraulic Barriers Installed in Closure

