

Facility Summary in Chouteau County in the City of

Location: MALMSTROM AFB J 4
US Hwy 87 Rural Location
, MT Chouteau

Legacy ID:08-09077

Facility ID: 19299
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	08/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
158	No	05/14/2018	Double-Walled	Double Walled	Yes
Currently in Use		06/19/2017	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000		05/30/2017	Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Chouteau County in the City of

Location: MALMSTROM AFB J 7
US Hwy 87 Rural Location
, MT Chouteau

Legacy ID:08-09080

Facility ID: 19302
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator

Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
02	30	08/01/1991	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
161	No	08/08/2018	Double-Walled	Double Walled	Yes
Currently in Use		08/08/2018	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Chouteau County in the City of Big Sandy

Location: EZZIES WHOLESALE BIG SANDY
 418 Judith Landing Rd
 Big Sandy, MT 59520-0395 Chouteau

Legacy ID:08-00855

Facility ID: 19100
Last Inspected On: 01/30/2019
Operating Permit Renewal Date: 07/09/2022

Owner Operator Contact: Ezzies Wholesale Inc;Lawrence Poulton;Ezzies Wholesale Inc

4066542331

Operator Contact: David Skiff

4066542331

Owner/Operator: Ezzies Wholesale Inc

David Skiff, UST Class A Operator
 David Skiff, UST Class B Global Operator
 David Skiff, UST Class B Operator
 Kenneth Martin, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
12	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1841	No			Double Walled	Yes
Currently in Use		02/27/2007	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
10	31	05/18/1990	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1842	No			Double Walled	Yes
Currently in Use		02/27/2007	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
09	31	05/18/1990	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1843	No			Double Walled	Yes
Currently in Use		02/27/2007	Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
2,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
13	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1844	No			Double Walled	Yes
Currently in Use		02/27/2007	Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
14	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1845	No			Double Walled	Yes

Currently in Use	02/27/2007	Electronic Line Leak Detector	Pressurized
Gasoline		Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2
4,000		Gilbarco-Veeder Root/TLS-350/Gilbarco EMC	No

Facility Summary in Chouteau County in the City of Big Sandy

Location: MOUNTAIN VIEW COOP BIG SANDY
79211 US Hwy 87
Big Sandy, MT 59520 Chouteau

Legacy ID:56-14150

Facility ID: 30786
Last Inspected On: 04/21/2020
Operating Permit Renewal Date: 05/27/2023

Owner Operator Contact: Mountain View Coop Black Eagle

4064535900

Operator Contact: David Douglas

Owner/Operator: Mountain View Coop Black Eagle

David Douglas, UST Class A Operator
David Douglas, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act

S1	16	01/31/2005	Bare Steel	Flexible Plastic	High Level Alarm
4965	Yes	04/09/2013		Double Walled	Yes

Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring; MLLD Line Tightness Testing	No
5,000		09/10/2014			No

S2	16	01/31/2005	Bare Steel	Flexible Plastic	High Level Alarm
4966	Yes	04/15/2016		Double Walled	Yes

Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring; MLLD Line Tightness Testing	No

5,000		09/10/2014			No
S3	0		Bare Steel	Flexible Plastic	
4967	Yes	04/15/2013		Double Walled	Yes
Temporarily Out of Use				Pressurized	
Unknown			Deferred	Continuous Interstitial Monitoring	No
1					No
S4	0		Bare Steel	Flexible Plastic	
4968	Yes	04/15/2013		Double Walled	Yes
Temporarily Out of Use				Not Listed	
Unknown			Deferred	Continuous Interstitial Monitoring	No
1					No

Facility Summary in Chouteau County in the City of Carter

Location: MALMSTROM AFB J 3
US Hwy 87
Carter, MT 59420 Chouteau

Legacy ID:08-09076

Facility ID: 19298
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	08/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
157	No	05/14/2018	Double-Walled	Double Walled	Yes
Currently in Use		05/23/2017	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000		05/23/2017	Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Chouteau County in the City of Carter

Location: MALMSTROM AFB J 5
US Hwy 87
Carter, MT 59420 Chouteau

Legacy ID:08-09078

Facility ID: 19300
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator

Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	08/01/1991	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
159	No	05/14/2018	Double-Walled	Double Walled	Yes
Currently in Use		06/19/2017	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000		06/13/2017	Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Chouteau County in the City of Carter

Location: SCHULER LANDS EAST FARM
 17105 Dent Bridge Rd
 Carter, MT 59420 Chouteau

Legacy ID:08-03976

Facility ID: 19168
Last Inspected On: 09/29/2021
Operating Permit Renewal Date: 11/21/2024

Owner Operator Contact:

Operator Contact: Dale Schuler

4067345404

Owner/Operator: Dale Schuler

Owner/Operator: Schuler Lands Inc

Dale Schuler, UST Class A Operator
 Dale Schuler, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act

01	39	04/22/1982	Fiberglass Reinforced Plastic	No Piping	Flapper Valve
4133	No			None	Yes
Currently in Use			Not Required		Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Not Listed	No
9,000			Gilbarco/EMC Basic		No

Facility Summary in Chouteau County in the City of Floweree

Location: MALMSTROM AFB J 6
17333 Bootlegger Trl
Floweree, MT 59440 Chouteau

Legacy ID:08-09079

Facility ID: 19301
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 11/09/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	6	07/06/2015	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
5590	No	05/14/2018	Double-Walled	Double Walled	Yes
Currently in Use		07/06/2015	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		Yes

Facility Summary in Chouteau County in the City of Fort Benton

Location: COUNTY COURTHOUSE and JAIL
1215 Washington St
Fort Benton, MT 59442 Chouteau

Legacy ID:08-05930

Facility ID: 19222
Last Inspected On: 08/24/2020
Operating Permit Renewal Date: 09/09/2023

Owner Operator Contact: Chouteau County;Daren Schuster;Chouteau County **4066223631**

Operator Contact: Robert Stevenson **4062524661**

Owner/Operator: Chouteau County

Kelly Harding, UST Class B Operator
Michael Hingiss, UST Class B Operator
Robert Stevenson, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	33	06/01/1988	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4118	No	08/01/2017		Double Walled	Yes
Currently in Use			Not Required	U.S. Suction	Non-corrodible
Diesel			Manual Tank Gauging	Manual Interstitial Monitoring	No
550					No

Facility Summary in Chouteau County in the City of Fort Benton

Location: JOYCE FUEL and FEEDS FORT BENTON
2118 Saint Charles St
Fort Benton, MT 59442 Chouteau

Legacy ID:56-13981

Facility ID: 30643
Last Inspected On: 12/29/2020
Operating Permit Renewal Date: 01/14/2024

Owner Operator Contact: Perry Joyce

Operator Contact: Perry Joyce

Owner/Operator: Perry Joyce

Owner/Operator: Perry W Joyce

Bradley Bramlette, UST Class B Operator
Cody Joyce, UST Class B Global Operator
Perry Joyce, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
-----------	-----	-----------	----------------------------	-----------------	----------------

Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	21	07/27/2000	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4210	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No
02	21	07/27/2000	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4211	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No
03	21	07/27/2000	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4212	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No

Facility Summary in Chouteau County in the City of Fort Benton

Location: JOYCE STORE 1
1221 Main St
Fort Benton, MT 59442 Chouteau

Legacy ID:08-00093

Facility ID: 19071
Last Inspected On: 11/12/2019
Operating Permit Renewal Date: 11/20/2022

Owner Operator Contact: Riverside Business Inc; Robert Moss; Thriftway Marketing Corp - Former Gasamat of MT

4065863531;5053265571

Operator Contact: Bryan Nevers; Perry Joyce

4066223381

Owner/Operator: Riverside Business Inc

Bryan Nevers, UST Class A Operator
 Bryan Nevers, UST Class B Operator
 Kevin Joyce, UST Class B Global Operator
 Perry Joyce, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
04	22	06/01/1999	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4134	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		12/04/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
12,000			Gilbarco/EMC Basic		No
05	22	06/01/1999	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4135	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		12/04/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
12,000			Gilbarco/EMC Basic		No
06	22	06/01/1999	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
4136	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		09/10/2011	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
12,000			Gilbarco/EMC Basic		No

Facility Summary in Chouteau County in the City of Fort Benton

Location: MOUNTAIN VIEW COOP FORT BENTON
 1820 Saint Charles St
 Fort Benton, MT 59442 Chouteau

Legacy ID:08-00005

Facility ID: 19068
Last Inspected On: 05/17/2020
Operating Permit Renewal Date: 06/19/2023

Owner Operator Contact: Marc Freund;Mountain View Coop Black Eagle;Mountain View Coop Black Eagle

4064535900

Operator Contact: John Lindeman;Judy Statham;Pat Trainor;Patricia Holskey

4066225121;4067506802;8008233276

Owner/Operator: Mountain View Coop Black Eagle

David Douglas, UST Class B Global Operator
 John Lindeman, UST Class A Operator
 John Lindeman, UST Class B Operator
 Judy Statham, UST Class A Operator
 Pat Trainor, UST Class A Operator
 Pat Trainor, UST Class B Global Operator
 Patricia Holskey, UST Class A Operator
 Patricia Holskey, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
06	45	12/11/1976	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1021	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
6,000		03/30/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
12	30	12/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1022	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
6,000		03/30/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

13	30	12/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1023	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
6,000		03/30/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
14	30	12/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1024	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
6,000		03/30/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
15	30	12/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1025	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
6,000		03/30/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
16	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4628	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
17	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4629	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible

Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
18	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4630	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
19	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4631	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
20	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4632	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
30,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
21	19	03/28/2002	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
4633	No	05/09/2017		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
30,000		03/03/2008	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Chouteau County in the City of Geraldine

Location: CENTRAL MONTANA COOP GERALDINE
28720 MT Hwy 80
Geraldine, MT 59446 Chouteau

Legacy ID:08-06615

Facility ID: 19239
Last Inspected On: 10/11/2021
Operating Permit Renewal Date: 01/08/2022

Owner Operator Contact: Central Montana Coop Geraldine

4067374480

Operator Contact: Kirk Protsman;Shawn Bray

Owner/Operator: Central Montana Coop Geraldine

Kirk Protsman, UST Class A Operator

Shawn Bray, UST Class A Operator

Shawn Bray, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S1	47	04/29/1974	Bare Steel	Fiberglass Reinforced Plastic	High Level Alarm
864	Yes			None	No
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	MLLD Line Tightness Testing	No
2,000		05/13/2013			No
S2	47	04/29/1974	Bare Steel	Fiberglass Reinforced Plastic	High Level Alarm
865	Yes			None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	MLLD Line Tightness Testing	No
2,000		05/13/2013			No

Facility Summary in Chouteau County in the City of Loma

Location: PA'S MART
204 Broadway
Loma, MT 59460-0184 Chouteau

Legacy ID:08-01445

Facility ID: 19112
Last Inspected On: 07/22/2021
Operating Permit Renewal Date:

Owner Operator Contact: Gregory Bouchard;N/A ZZZ - TBL_OWN : 369;First State Bank Fort Benton

4066223351;4067394422

Operator Contact: Gregory Bouchard

4067394422

Owner/Operator: Gregory Bouchard

Gregory Bouchard, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	35	12/30/1986	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
3957	No			None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		05/29/2012	Inventory Reconciliation;Statistical Inventory Reconciliation	MLLD Line Tightness Testing	No
6,000					No
04	35	12/30/1986	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
3958	No			None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		05/29/2012	Inventory Reconciliation;Statistical Inventory Reconciliation	MLLD Line Tightness Testing	No
6,000					No