

**Facility Summary in Golden Valley County in the City of Lavina**

**Location:** FARMERS OASIS LLC  
4666 MT Hwy 3  
Lavina, MT 59046-7156 Golden Valley

System Facility ID:19-13681

**Facility Code:** 22075  
**Last Inspected On:** 07/03/2025  
**Operating Permit Renewal Date:** 10/24/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Mike Bury;FARMERS OASIS LLC (406) 632-4329;(561) 693-8795 mike@raysoasis.com;MIKE@RAYOASIS.COM

**Operator Contact:** Jeff Parker;FARMERS OASIS LLC (406) 636-4005;(561) 693-8795 jeff@oasistravelcenters.com;MIKE@RAYOASIS.COM

**Owner/Operator:** Mike Bury,FARMERS OASIS LLC (406) 632-4329 mike@raysoasis.com  
Jeff Parker, UST Class A Operator MIKE@RAYOASIS.COM  
Jeff Parker, UST Class B Operator MIKE@RAYOASIS.COM

<b>Tank Code</b>	S1	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	03/01/1996	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	3381	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/03/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Deferred	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/03/2025	<b>Line Tightness Test Date</b>	07/14/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S2	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	03/01/1996	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	3382	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/03/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Deferred	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	07/03/2025	<b>Line Tightness Test Date</b>	07/14/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Golden Valley County in the City of Ryegate**

**Location:** RYEGATE PUBLIC SCHOOLS DIST 1  
207 2nd Ave W  
Ryegate, MT 59074-0129 Golden Valley

System Facility ID:19-07975

**Facility Code:** 22067  
**Last Inspected On:** 08/01/2024  
**Operating Permit Renewal Date:** 11/01/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** School Dist 1 Ryegate (406) 568-2211

**Operator Contact:** Penny Stradtman pstradtman@ryegate.k12.mt.us

**Owner/Operator:** School Dist 1 Ryegate (406) 568-2211

Penny Stradtman, UST Class A Operator  
Penny Stradtman, UST Class B Operator

pstradtman@ryegate.k12.mt.us  
pstradtman@ryegate.k12.mt.us

<b>Tank Code</b>	S2	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	08/01/1996	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1870	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	07/30/2014	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>	05/28/2025	<b>Line Tightness Test Date</b>	07/31/2014	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

## Facility Summary in Golden Valley County in the City of Ryegate

**Location:** SUPER D GROCERY  
203 E Railway Ave  
Ryegate, MT 59074 Golden Valley

System Facility ID:19-13735

**Facility Code:** 22076  
**Last Inspected On:** 09/26/2024  
**Operating Permit Renewal Date:** 12/10/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Clifford Sutton;Super D Grocery Inc (406) 568-2378 superd@midrivers.com

---

**Operator Contact:** Peggy Sutton (406) 568-2378 superd@midrivers.com

---

**Owner/Operator:** Clifford Sutton (406) 568-2378

**Owner/Operator:** Super D Grocery Inc (406) 568-2378

Peggy Sutton, UST Class A Operator  
Peggy Sutton, UST Class B Operator

superd@midrivers.com  
superd@midrivers.com

<b>Tank Code</b>	S1	<b>Tank Age</b>	30	<b>Tank Installed Date</b>	04/08/1996	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3462	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Deferred	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S2	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm
<b>Tag Number</b>	3727	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	08/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/25/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Deferred	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S3	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Unknown	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	High Level Alarm

<b>Tag Number</b>	3728	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Deferred	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					