

Facility Summary in McCone County in the City of Circle

Location: CARLSEN SINCLAIR and SERVICE LLC
 210 A Ave
 Circle, MT 59215 McCone

Legacy ID:29-00041

Facility ID: 24841
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 03/30/2022

Owner Operator Contact:

Operator Contact: Cody Carlsen;Grant Herden;Leonard Kuntz;Les Carlsen
4064852268;4064853645

Owner/Operator: Les D Carlsen

Cody Carlsen, UST Class A Operator
 Cody Carlsen, UST Class B Global Operator
 Cory Hirschfeld, UST Class B Global Operator
 Denny Hogan, UST Class B Global Operator
 Grant Herden, UST Class A Operator
 Grant Herden, UST Class B Global Operator
 Leonard Kuntz, UST Class A Operator
 Les Carlsen, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
08	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
612	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Gasoline			Manual Interstitial Monitoring	Deferred	No
6,000					No
09	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
613	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Diesel			Manual Interstitial Monitoring	Deferred	No

2,000					No
10	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
614	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Diesel			Manual Interstitial Monitoring	Deferred	No
2,000					No
11	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
615	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Diesel			Manual Interstitial Monitoring	Deferred	No
6,000					No
12	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
616	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Gasoline			Manual Interstitial Monitoring	Deferred	No
4,000					No
13	24	10/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
617	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Diesel			Manual Interstitial Monitoring	Deferred	No
2,000					No

Facility Summary in McCone County in the City of Circle

Location: CIRCLE COUNTRY MARKET LLC
105 10th St
Circle, MT 59215 McCone

Legacy ID:29-00042

Facility ID: 24842
Last Inspected On: 12/03/2018
Operating Permit Renewal Date: 03/30/2022

Owner Operator Contact: Circle Country Market LLC

Operator Contact: Cody Carlsen;Julian Hoffman;Leonard Kuntz;Les Carlsen;Tammy Leeson

4064852680;4064853645;4069412131

Owner/Operator: Circle Country Market LLC

Cody Carlsen, UST Class A Operator
Cody Carlsen, UST Class B Global Operator
Cory Hirschfeld, UST Class B Global Operator
Denny Hogan, UST Class B Global Operator
Julian Hoffman, UST Class A Operator
Julian Hoffman, UST Class B Global Operator
Julian Hoffman, UST Class B Operator
Leonard Kuntz, UST Class A Operator
Les Carlsen, UST Class A Operator
Les Carlsen, UST Class B Global Operator
Tammy Leeson, UST Class A Operator
Tammy Leeson, UST Class B Global Operator
Tammy Leeson, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	24	10/01/1997	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
618	No		Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		10/26/2015	Manual Interstitial Monitoring	Deferred	No
4,000					No
04	24	10/01/1997	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
619	No		Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic

Gasoline	10/26/2015	Manual Interstitial Monitoring	Deferred	No
4,000				No

Facility Summary in McCone County in the City of Circle

Location: CIRCLE EXXON
706 B Ave
Circle, MT 59215 McCone

Legacy ID:29-03433

Facility ID: 24879
Last Inspected On: 03/11/2020
Operating Permit Renewal Date: 08/11/2023

Owner Operator Contact: BMC LLC;N/A ZZZ - TBL_OWN : 175;Circle Service Center Inc **4064853663**

Operator Contact: Megan Curtiss **4064853401**

Owner/Operator: BMC LLC

Owner/Operator: Wayne Kleppelid

Alicia Alborg, UST Class B Operator
Megan Curtiss, UST Class A Operator
Megan Curtiss, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
07	23	11/01/1998	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
3802	No		Double-Walled	Double Walled	Yes
Currently in Use		02/14/2013	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
6,000		07/06/2014	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
08	23	11/01/1998	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
3803	No		Double-Walled	Double Walled	Yes
Currently in Use		02/14/2013	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No

4,000		07/06/2014	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
09	23	11/01/1998	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
3804	No		Double-Walled	Double Walled	Yes
Currently in Use		02/14/2013	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
6,000		07/06/2014	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in McCone County in the City of Circle

Location: CIRCLE PUBLIC SCHOOL DIST 1
1105 F Ave
Circle, MT 59215 McCone

Legacy ID:29-00874

Facility ID: 24849
Last Inspected On: 01/08/2019
Operating Permit Renewal Date: 06/04/2022

Owner Operator Contact: School Dist 1 Circle

4064853600

Operator Contact: Dwain Jensen;Gary Fisher

4064853600;4068523475

Owner/Operator: School Dist 1 Circle

Dwain Jensen, UST Class A Operator
Dwain Jensen, UST Class B Global Operator
Dwain Jensen, UST Class B Operator
Gary Fisher, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S2	24	08/01/1997	Steel Clad	Flexible Plastic	Flapper Valve
1890	No	04/25/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		04/10/2013	Manual Interstitial Monitoring	Continuous Interstitial Monitoring	No
8,000					No

Facility Summary in McCone County in the City of Circle

Location: FARMERS UNION OIL CO CIRCLE
906 A Ave
Circle, MT 59215 McCone

Legacy ID:29-06376

Facility ID: 24902
Last Inspected On: 10/16/2018
Operating Permit Renewal Date: 03/04/2022

Owner Operator Contact: Cory Vorderbruggen;Farmers Union Oil Co
Circle;Farmers Union Oil Co Circle

4064853475;4064853475;4064853475

Operator Contact: Cory Vorderbruggen;Jeffrey Schaefer;Terry Wahl

4064853475

Owner/Operator: Farmers Union Oil Co Circle

Cory Vorderbruggen, UST Class A Operator
Jeffrey Schaefer, UST Class A Operator
Jeffrey Schaefer, UST Class B Operator
Larry Kwasney, UST Class B Operator
Terry Wahl, UST Class A Operator
Terry Wahl, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S12	15	10/06/2006	Unknown	Flexible Plastic	
5108	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
5,000		08/22/2018			No
S08	23	11/01/1998	Unknown	Fiberglass Reinforced Plastic	
951	Yes			Double Walled	Yes
Currently in Use		08/16/2006	Electronic Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
15,000		08/19/2018			No

S09	23	11/01/1998	Unknown	Fiberglass Reinforced Plastic	
952	Yes			Double Walled	Yes
Currently in Use		08/16/2006	Electronic Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring; ELLD 0.2; ELLD Line Tightness Testing	No
15,000		08/18/2018			No
S10	23	11/01/1998	Unknown	Fiberglass Reinforced Plastic	
953	Yes			Double Walled	Yes
Currently in Use		08/16/2006	Electronic Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring; ELLD 0.2; ELLD Line Tightness Testing	No
15,000		09/03/2018			No
S11	23	11/01/1998	Unknown	Fiberglass Reinforced Plastic	
954	Yes			Double Walled	Yes
Currently in Use		08/16/2006	Electronic Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring; ELLD 0.2; ELLD Line Tightness Testing	No
15,000		08/18/2018			No

Facility Summary in McCone County in the City of Circle

Location: FARMERS UNION OIL C-STORE
200 B Ave
Circle, MT 59215 McCone

Legacy ID:60-15206

Facility ID: 30926
Last Inspected On: 10/16/2018
Operating Permit Renewal Date: 04/09/2022

Owner Operator Contact: Farmers Union Oil C-Store

Operator Contact: Cory Vorderbruggen; Jeffrey Schaefer; Terry Wahl **4064853475**

Owner/Operator: Farmers Union Oil C-Store

Cory Vorderbruggen, UST Class A Operator
Dharlyne Kirkegard, UST Class B Operator
Dorothy Johnson, UST Class B Operator
Jeffrey Schaefer, UST Class A Operator

Jeffrey Schaefer, UST Class B Operator
 Sadie Idland, UST Class B Operator
 Terry Wahl, UST Class A Operator
 Terry Wahl, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	9	06/01/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5356	No	08/12/2012	Double-Walled	Double Walled	Yes
Currently in Use		10/10/2012	Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
15,000		10/15/2018	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes
03	9	06/01/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5357	No	08/12/2012	Double-Walled	Double Walled	Yes
Currently in Use		10/10/2012	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
14,000		10/15/2018	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes
04	9	06/01/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5358	No	08/12/2012	Double-Walled	Double Walled	Yes
Currently in Use		10/10/2012	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
14,000		04/18/2018	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes

05	9	06/01/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5359	No	08/12/2012	Double-Walled	Double Walled	Yes
Currently in Use		10/10/2012	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
6,000		04/24/2018	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes
06	9	06/01/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5360	No	08/12/2012	Double-Walled	Double Walled	Yes
Currently in Use		10/10/2012	Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.2;ELLD Line Tightness Testing	No
6,000		10/09/2018	Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes

Facility Summary in McCone County in the City of Circle

Location: HALES DISTRIBUTING
901 B Ave
Circle, MT 59215 McCone

Legacy ID:29-03684

Facility ID: 24887
Last Inspected On: 12/15/2020
Operating Permit Renewal Date: 01/08/2024

Owner Operator Contact: Hales Distributing;N/A ZZZ - TBL_OWN : 446;Hales Distributing **4064852510**

Operator Contact: William Hale **4064852510**

Owner/Operator: Hales Distributing

William Hale, UST Class A Operator
William Hale, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
05	31	09/12/1990	Cathodically Protected Steel	Steel	Flapper Valve
1267	No		Double-Walled	None	Yes

Currently in Use		Not Required	Safe Suction	Impressed Current
Gasoline	09/11/2017	Manual Interstitial Monitoring	Deferred	No
5,000				No

Facility Summary in McCone County in the City of Vida

Location: AGLAND COOP VIDA
MT Hwy 13
Vida, MT 59274 McCone

Legacy ID:56-14042

Facility ID: 30697
Last Inspected On: 07/08/2021
Operating Permit Renewal Date: 08/07/2024

Owner Operator Contact: Agland Coop Wolf Point

Operator Contact: Aaron Bradley;David Parsley;Waldo Wall	4066531510;4068530492
---	------------------------------

Owner/Operator: Agland Coop Wolf Point

- Aaron Bradley, UST Class A Operator
- Aaron Bradley, UST Class B Operator
- Allen Richard, UST Class B Global Operator
- Allen Richard, UST Class B Operator
- David Parsley, UST Class A Operator
- Michael Pallvoda, UST Class B Operator
- Waldo Wall, UST Class A Operator
- Waldo Wall, UST Class B Operator
- Weston Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	20	12/01/2001	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
4560	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		03/02/2016	Automatic Tank Gauging 0.2	Deferred	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	20	12/01/2001	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve

4561	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		03/02/2016	Automatic Tank Gauging 0.2	Deferred	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	20	12/01/2001	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
4562	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		03/02/2016	Automatic Tank Gauging 0.2	Deferred	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No