

Facility Summary in Pondera County in the City of Brady

Location: MOUNTAIN VIEW COOP BRADY
102 Railroad St N
Brady, MT 59416 Pondera

Legacy ID:37-04241

Facility ID: 26390
Last Inspected On: 07/25/2019
Operating Permit Renewal Date: 08/04/2022

Owner Operator Contact: Kila Moore;Marc Freund;Mountain View Coop
Brady;Mark Freund;Mountain View Coop Great
Falls;Mountain View Coop Black Eagle

4064535900;4067532241

Operator Contact: David Douglas

Owner/Operator: Mountain View Coop Black Eagle

David Douglas, UST Class A Operator
David Douglas, UST Class B Global Operator
Jeremy Kulpas, UST Class B Global Operator
Jeremy Kulpas, UST Class B Operator
Laura Mehrer, UST Class B Operator
Lorena Rouns, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S11	24	11/01/1997	Unknown	Flexible Plastic	
2142	Yes	07/07/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring	No
17,000					No
S12	24	11/01/1997	Unknown	Flexible Plastic	
2143	Yes	07/07/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring	No
17,000					No

S13	24	11/01/1997	Unknown	Flexible Plastic	
2144	Yes	07/07/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring	No
12,000					No
S14	24	11/01/1997	Unknown	Flexible Plastic	
2145	Yes	07/07/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring	No
5,000					No

Facility Summary in Pondera County in the City of Conrad

Location: MOUNTAIN VIEW COOP CONRAD
19 S Main St
Conrad, MT 59425-1828 Pondera

Legacy ID:37-01649

Facility ID: 26344
Last Inspected On: 11/02/2020
Operating Permit Renewal Date: 01/06/2024

Owner Operator Contact: Dave Chalfon Manager;Farmers Supply Coop
Conrad;Mountain View Coop Black Eagle;Mountain
View Co-Op Conrad **4062785524;4064535900**

Operator Contact: Dave Douglas;Jeremy Kulpas **4062785524;4067506748**

Owner/Operator: Mountain View Coop Black Eagle

Dave Douglas, UST Class A Operator
Jeremy Kulpas, UST Class A Operator
Jeremy Kulpas, UST Class B Global Operator
Jeremy Kulpas, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
13	0		Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve

5978	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
12,000				Yes
14	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5979	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
8,000				Yes
15	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5980	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
11,000				Yes
16	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5981	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
9,000				Yes
17	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5982	No	Double-Walled	Double Walled	No

Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
8,000				Yes
18	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5983	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
7,000				Yes
19	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
5984	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
6,000				Yes

Facility Summary in Pondera County in the City of Conrad

Location: TOMS SUPER SERVICE
301 S. Main Street
Conrad, MT 59425 Pondera

Legacy ID:37-06114

Facility ID: 26416
Last Inspected On: 04/17/2019
Operating Permit Renewal Date: 07/20/2022

Owner Operator Contact: Ben Taylor Inc;Ben Taylor;Ben Taylor Inc

4064345076

Operator Contact: Tom Fetters

4062785213

Owner/Operator: Ben Taylor Inc

Gail Mullennax, UST Class B Operator
Tom Fetters, UST Class A Operator
Tom Fetters, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types

Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
03	28	05/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
423	No		Double-Walled	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Continuous Interstitial Monitoring	MLLD Line Tightness Testing	No
4,000	05/10/2016		Gilbarco-Veeder Root/ILS-250		No
04	28	05/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
424	No		Double-Walled	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Continuous Interstitial Monitoring	MLLD Line Tightness Testing	No
8,000	05/10/2016		Gilbarco-Veeder Root/ILS-250		No
05	28	05/12/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
425	No		Double-Walled	None	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Continuous Interstitial Monitoring	MLLD Line Tightness Testing	No
4,000	05/10/2016				No

Facility Summary in Pondera County in the City of Conrad

Location: TOWN PUMP INC CONRAD
215 N Main St
Conrad, MT 59425-1628 Pondera

Legacy ID:37-08692

Facility ID: 26453
Last Inspected On: 01/21/2019
Operating Permit Renewal Date: 04/01/2022

Owner Operator Contact: Don Edmisten;Town Pump O Mat of Conrad Inc **4064976948;4064976700**

Operator Contact: Daniel Sampson

Owner/Operator: Conrad 1 Town Pump LLC

Daniel Sampson, UST Class A Operator
Daniel Sampson, UST Class B Global Operator
Don Edmisten, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	38	08/30/1983	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2584	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		12/13/2018	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000		07/28/2006			No
02	38	08/30/1983	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
2585	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		12/13/2018	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000		07/29/2006			No
03	38	08/30/1983	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
2586	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		12/13/2018	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
12,000		07/30/2006			No
04	35	08/30/1986	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
2587	No			None	Yes

Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		12/13/2018	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000		08/01/2006			No
05	33	07/01/1988	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2588	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel		12/03/2009	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
12,000		10/26/2006			No
08	22	09/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4151	No		Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel		12/03/2009	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
10,000		10/30/2006			No
09	22	09/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff
4152	No		Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel		12/03/2009	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
5,000		10/30/2006			No
10	7	07/01/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
5495	No	07/21/2014	Double-Walled	Double Walled	Yes

Currently in Use		04/16/2014	Electronic Line Leak Detector	Pressurized	
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000					No
11	7	07/01/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
5496	No	07/21/2014	Double-Walled	Double Walled	Yes
Currently in Use		04/16/2014	Electronic Line Leak Detector	Pressurized	
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
20,000					No
12	7	07/01/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
5497	No	07/21/2014	Double-Walled	Double Walled	Yes
Currently in Use		04/16/2014	Electronic Line Leak Detector	Pressurized	
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000					No

Facility Summary in Pondera County in the City of Heart Butte

Location: HEART BUTTE SCHOOL DIST 1
School Bus Barn Rd
Heart Butte, MT 59448 Pondera

Legacy ID:37-09353

Facility ID: 26492
Last Inspected On: 12/20/2019
Operating Permit Renewal Date: 12/28/2022

Owner Operator Contact: School Dist 1 Heart Butte

4063382200

Operator Contact: Merlin Running Crane

4063383151

Owner/Operator: School Dist 1 Heart Butte

Merlin Running Crane, UST Class A Operator
Merlin Running Crane, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected

Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
03	35	05/06/1986	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1901	No		None	Yes	
Currently in Use		Not Required	Safe Suction	Non-corrodible	
Gasoline		Automatic Tank Gauging 0.2	Deferred	No	
2,000		Gilbarco/EMC Basic		No	
04	35	05/06/1986	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1902	No		None	Yes	
Currently in Use		Not Required	Safe Suction	Non-corrodible	
Diesel		Automatic Tank Gauging 0.2	Deferred	No	
2,000		Gilbarco/EMC Basic		No	

Facility Summary in Pondera County in the City of Valier

Location: ONE STOP CENEX
518 Teton
Valier, MT 59486-0000 Pondera

Legacy ID:37-03112

Facility ID: 26371
Last Inspected On: 12/18/2020
Operating Permit Renewal Date: 12/17/2023

Owner Operator Contact: One Stop LLC

4062793600

Operator Contact: Pardeep Kumar;Paul Johnson;Scott Curry

4065050386;4084499333

Owner/Operator: One Stop LLC

Owner/Operator: Pardeep Kumar

Pardeep Kumar, UST Class A Operator
Paul Johnson, UST Class A Operator
Paul Johnson, UST Class B Global Operator
Scott Curry, UST Class A Operator
Scott Curry, UST Class B Global Operator
Scott Curry, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected

Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
03	31	03/21/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
1878	No		Double Walled	Yes	
Currently in Use		Mechanical Line Leak Detector	Pressurized	Galvanic	
Gasoline	08/25/2016	Statistical Inventory Reconciliation	MLLD Line Tightness Testing	No	
1,000	12/07/2017			No	
04	31	03/21/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
1879	No		Double Walled	Yes	
Currently in Use		Mechanical Line Leak Detector	Pressurized	Galvanic	
Diesel	08/25/2016	Statistical Inventory Reconciliation	MLLD Line Tightness Testing	No	
1,000	12/07/2017			No	
05	31	03/21/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
4445	No		Double Walled	Yes	
Currently in Use		Mechanical Line Leak Detector	Pressurized	Galvanic	
Gasoline	08/25/2016	Statistical Inventory Reconciliation	MLLD Line Tightness Testing	No	
2,000	12/07/2017			No	

Facility Summary in Pondera County in the City of Valier

Location: VALIER CARDLOCK
810 Teton
Valier, MT 59486 Pondera

Legacy ID:56-14043

Facility ID: 30698
Last Inspected On: 03/23/2021
Operating Permit Renewal Date: 03/25/2024

Owner Operator Contact: Ben Taylor Inc

4064345076

Operator Contact: Scott Curry

Owner/Operator: Ben Taylor Inc

Rita Swanson, UST Class B Operator
Scott Curry, UST Class A Operator

Scott Curry, UST Class B Global Operator
 Scott Curry, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S1	19	08/19/2002	Concrete	Flexible Plastic	
4710	Yes	02/23/2015		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
8,000					No
S2	19	08/19/2002	Concrete	Flexible Plastic	
4711	Yes	02/23/2015		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
8,000					No
S3	19	08/19/2002	Concrete	Flexible Plastic	
4712	Yes	02/23/2015		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
17,000					No
S4	19	08/19/2002	Concrete	Flexible Plastic	

4713	Yes	02/23/2015		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
17,000					No