

**Facility Summary in Richland County in the City of Fairview**

**Location:** BRAKE TIME 251717  
516 S Ellery Ave  
Fairview, MT 59221 Richland

System Facility ID:42-03914

**Facility Code:** 27193  
**Last Inspected On:** 08/05/2025  
**Operating Permit Renewal Date:** 10/04/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** FAIRVIEW MT LLC (406) 747-5024 licensing@btcmstores.com

**Operator Contact:** Theodore Bezel;Mini Mart Inc dba Loaf 'N Jug Pueblo (513) 964-1568 elegaldept@eg-america.com

**Owner/Operator:** FAIRVIEW MT LLC (406) 747-5024 licensing@btcmstores.com

Theodore Bezel, UST Class A Operator elegaldept@eg-america.com  
Theodore Bezel, UST Class B Global Operator  
Theodore Bezel, UST Class B Operator

<b>Tank Code</b>	06	<b>Tank Age</b>	13	<b>Tank Installed Date</b>	03/01/2013	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5410	<b>Spill Test Date</b>	02/05/2026	<b>Piping Installed Date</b>	03/01/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/05/2025	<b>Sump Tightness Test Date</b>	09/26/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	08/05/2025	<b>Line Tightness Test Date</b>	02/27/2025	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.1	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/05/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	07	<b>Tank Age</b>	13	<b>Tank Installed Date</b>	03/01/2013	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5411	<b>Spill Test Date</b>	02/05/2026	<b>Piping Installed Date</b>	03/01/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/05/2025	<b>Sump Tightness Test Date</b>	09/26/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No

<b>Capacity</b>	10000	<b>ATG Test Date</b>	08/05/2025	<b>Line Tightness Test Date</b>	07/20/2022	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.1	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/05/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	08	<b>Tank Age</b>	13	<b>Tank Installed Date</b>	03/01/2013	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve;High Level Alarm
<b>Tag Number</b>	5412	<b>Spill Test Date</b>	02/05/2026	<b>Piping Installed Date</b>	03/01/2013	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	08/05/2025	<b>Sump Tightness Test Date</b>	09/26/2024	<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	07/20/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	08/05/2025	<b>Line Tightness Test Date</b>	07/20/2022	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.1	<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/05/2025			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350;Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Richland County in the City of Fairview**

**Location:** HORIZON RESOURCES FAIRVIEW STORE  
605 S Ellery Ave  
Fairview, MT 59221 Richland

System Facility ID:42-03363

**Facility Code:** 27175  
**Last Inspected On:** 04/12/2023  
**Operating Permit Renewal Date:** 07/24/2026

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Horizon Resources Cooperative

**Operator Contact:** Darcie Yadon

**dyadon@horizonresources.coop**

**Owner/Operator:** Horizon Resources Cooperative

Darcie Yadon, UST Class A Operator  
Darcie Yadon, UST Class B Operator

dyadon@horizonresources.coop  
dyadon@horizonresources.coop

<b>Tank Code</b>	07	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3722	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/09/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	7800	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	08	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3723	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/09/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4200	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	09	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve

<b>Tag Number</b>	3724	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/09/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	5500	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	10	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	12/01/1998	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3725	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/09/2018	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4500	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	15	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	01/02/2011	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5274	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450;Veeder Root/TLS-450				
<b>Tank Code</b>	16	<b>Tank Age</b>	15	<b>Tank Installed Date</b>	01/02/2011	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5275	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>	01/24/2011	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	12/13/2021	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible

<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	11/22/2022	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	04/12/2023			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450;Veeder Root/TLS-450				

**Facility Summary in Richland County in the City of Lambert**

**Location:** NORTANA GRAIN CO  
100 1st Ave SW  
Lambert, MT 59243 Richland

System Facility ID:42-00317

**Facility Code:** 27067  
**Last Inspected On:** 10/21/2024  
**Operating Permit Renewal Date:** 03/04/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Nortana Grain Co;Shane Keller (406) 443-2580;(406) 478-4122 kellershane@hotmail.com

**Operator Contact:** Mike Arneson;Shane Keller (406) 478-4122;(406) 489-3589 kellershane@hotmail.com;mikenortana@outlook.com

**Owner/Operator:** Nortana Grain Co (406) 443-2580

**Owner/Operator:** Shane Keller (406) 443-2580

Mike Arneson, UST Class A Operator  
Mike Arneson, UST Class B Operator  
Shane Keller, UST Class A Operator  
Shane Keller, UST Class B Operator

mikenortana@outlook.com  
mikenortana@outlook.com  
kellershane@hotmail.com  
kellershane@hotmail.com

<b>Tank Code</b>	S5	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	03/06/2009	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5201	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/10/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	21000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S6	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	03/06/2009	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5202	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/10/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	21000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

<b>Tank Code</b>	S7	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	03/06/2009	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5203	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/10/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	13000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S8	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	03/06/2009	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5204	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/10/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S9	<b>Tank Age</b>	17	<b>Tank Installed Date</b>	03/06/2009	<b>Tank Material</b>	Concrete	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	5205	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	10/20/2008	<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/10/2024	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	21000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	06/10/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

## Facility Summary in Richland County in the City of Savage

**Location:** VALLEY FUEL SUPPLY  
 MT Hwy 16  
 Savage, MT 59262 Richland

System Facility ID:42-03815

**Facility Code:** 27187  
**Last Inspected On:** 09/26/2023  
**Operating Permit Renewal Date:** 03/14/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** Gregory Cross (406) 698-2967 gcross@crosspetroleumservice.com

---

**Operator Contact:** Gregory Cross;R J Serpe;Timothy Fife (406) 698-2967 gcross@crosspetroleumservice.com;rlsrp@yahoo.com

---

**Owner/Operator:** Greg Cross (406) 698-2967 gcross@crosspetroleumservice.com

Greg Cross, UST Class A Operator	gcross@crosspetroleumservice.com
R J Serpe, UST Class A Operator	rlsrp@yahoo.com
R J Serpe, UST Class B Global Operator	rlsrp@yahoo.com
Ron Serpe, UST Class B Global Operator	rserpe@crosssps.com
Timothy Fife, UST Class A Operator	

<b>Tank Code</b>	03	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/25/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	780	<b>Spill Test Date</b>	02/01/2023	<b>Piping Installed Date</b>	02/01/2023	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>	11/18/2008	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	09/26/2023	<b>Line Tightness Test Date</b>	02/01/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Franklin Fueling Systems/EVO 600				
<b>Tank Code</b>	04	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	781	<b>Spill Test Date</b>	02/01/2023	<b>Piping Installed Date</b>	02/01/2023	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>	11/18/2008	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	09/26/2023	<b>Line Tightness Test Date</b>	02/01/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No

		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Franklin Fueling Systems/EVO 600				
<b>Tank Code</b>	05	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	08/01/1998	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	782	<b>Spill Test Date</b>	02/01/2023	<b>Piping Installed Date</b>	02/01/2023	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>	11/18/2008	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	3000	<b>ATG Test Date</b>	09/26/2023	<b>Line Tightness Test Date</b>	02/01/2023	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	02/01/2023			<b>ATG Type</b>	Franklin Fueling Systems/EVO 600				

### Facility Summary in Richland County in the City of Sidney

**Location:** BRAKE TIME 251716  
706 S Central Ave  
Sidney, MT 59270-4939 Richland

System Facility ID:42-05084

**Facility Code:** 27233  
**Last Inspected On:** 08/07/2025  
**Operating Permit Renewal Date:** 10/04/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

---

**Owner Operator Contact:** SIDNEY MT LLC (406) 482-5647 licensing@btcmstores.com

---

**Operator Contact:** Muhammad Akhtar (832) 539-8190 akhatarmuhammad65@gmail.com

---

**Owner/Operator:** SIDNEY MT LLC (406) 482-5647 licensing@btcmstores.com  
Muhammad Akhtar, UST Class A Operator akhatarmuhammad65@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	50	<b>Tank Installed Date</b>	04/24/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4586	<b>Spill Test Date</b>	03/13/2026	<b>Piping Installed Date</b>	12/22/2010	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/25/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/13/2026	<b>Tank/Piping CP Test Date</b>	08/07/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	08/05/2025	<b>Line Tightness Test Date</b>	07/20/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/13/2026			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				
<b>Tank Code</b>	02	<b>Tank Age</b>	50	<b>Tank Installed Date</b>	04/24/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4587	<b>Spill Test Date</b>	03/13/2026	<b>Piping Installed Date</b>	12/22/2010	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/25/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	03/13/2026	<b>Tank/Piping CP Test Date</b>	08/07/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	08/05/2025	<b>Line Tightness Test Date</b>	07/20/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/13/2026			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

<b>Tank Code</b>	03	<b>Tank Age</b>	50	<b>Tank Installed Date</b>	04/24/1976	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4588	<b>Spill Test Date</b>	03/13/2026	<b>Piping Installed Date</b>	12/22/2010	<b>Tank Construction</b>	Lined Interior/Impressed Current	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	09/25/2024	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	03/13/2026	<b>Tank/Piping CP Test Date</b>	08/07/2024	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	03/13/2026	<b>Line Tightness Test Date</b>	07/20/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	03/13/2026			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC				

**Facility Summary in Richland County in the City of Sidney**

**Location:** LOWER YELLOWSTONE RURAL ELECTRIC ASSOCIATION  
INC  
3200 W Holly St  
Sidney, MT 59270 Richland

System Facility ID:42-00001

**Facility Code:** 27062  
**Last Inspected On:** 06/11/2024  
**Operating Permit Renewal Date:** 09/29/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Lower Yellowstone Rural Electric Association Inc (406) 482-1602

**Operator Contact:** Bodrey Kindopp;Justin King (406) 488-1602 bodreyk@lyrec.com;justink@lyrec.coop

**Owner/Operator:** Lower Yellowstone Rural Electric Association Inc (406) 482-1602

Bodrey Kindopp, UST Class A Operator  
Justin King, UST Class A Operator  
Justin King, UST Class B Global Operator  
Mike Eberling, UST Class B Global Operator

bodreyk@lyrec.com  
justink@lyrec.coop  
justink@lyrec.coop  
arthur\_mike@hotmail.com

<b>Tank Code</b>	05	<b>Tank Age</b>	33	<b>Tank Installed Date</b>	10/01/1993	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1558	<b>Spill Test Date</b>	06/11/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/11/2024			<b>ATG Type</b>					
<b>Tank Code</b>	06	<b>Tank Age</b>	33	<b>Tank Installed Date</b>	10/01/1993	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	1559	<b>Spill Test Date</b>	06/11/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/11/2024			<b>ATG Type</b>					

**Facility Summary in Richland County in the City of Sidney**

**Location:** METZ FUEL and SERVICE  
625 S Central Ave  
Sidney, MT 59270-4936 Richland

System Facility ID:42-03224

**Facility Code:** 27172  
**Last Inspected On:** 07/24/2024  
**Operating Permit Renewal Date:** 10/01/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Metz Fuel Service Inc metzfuel@gmail.com

**Operator Contact:** Jim Metz (406) 480-1872 metzfuel@gmail.com

**Owner/Operator:** Metz Fuel Service Inc metzfuel@gmail.com  
 Jim Metz, UST Class A Operator metzfuel@gmail.com  
 Jim Metz, UST Class B Global Operator metzfuel@gmail.com

<b>Tank Code</b>	10	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/11/1991	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2110	<b>Spill Test Date</b>	07/24/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/24/2024			<b>ATG Type</b>					
<b>Tank Code</b>	11	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/11/1991	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2111	<b>Spill Test Date</b>	07/26/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	Safe Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/26/2024			<b>ATG Type</b>					
<b>Tank Code</b>	12	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/11/1991	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2112	<b>Spill Test Date</b>	07/24/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No

<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/24/2024	<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	07/24/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/24/2024			<b>ATG Type</b>					
<b>Tank Code</b>	13	<b>Tank Age</b>	35	<b>Tank Installed Date</b>	07/11/1991	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	2113	<b>Spill Test Date</b>	07/24/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	07/24/2024	<b>Sump Tightness Test Date</b>	10/07/2021	<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring; Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	07/24/2024	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	07/24/2024			<b>ATG Type</b>					

**Facility Summary in Richland County in the City of Sidney**

**Location:** MILLERS CORNER  
2201 W Holly St  
Sidney, MT 59270 Richland

System Facility ID:56-14071

**Facility Code:** 30723  
**Last Inspected On:** 11/18/2025  
**Operating Permit Renewal Date:** 04/22/2029

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Millers Corner LLC (406) 433-4041 millerscornersidney@gmail.com

**Operator Contact:** Gregory Miller;Nitin Patel (406) 227-6755;(406) 433-4041 gregm@midrivers.com;millerscornersidney@gmail.com

**Owner/Operator:** Millers Corner LLC (406) 433-4041 millerscornersidney@gmail.com  
 Gregory Miller, UST Class A Operator gregm@midrivers.com  
 Gregory Miller, UST Class B Global Operator gregm@midrivers.com  
 Nitin Patel, UST Class A Operator millerscornersidney@gmail.com  
 Nitin Patel, UST Class B Operator millerscornersidney@gmail.com

<b>Tank Code</b>	01	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	02/06/2003	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4797	<b>Spill Test Date</b>	06/09/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	11/18/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	10/09/2025	<b>Line Tightness Test Date</b>	10/24/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/18/2025			<b>ATG Type</b>	Incon/TS-550				
<b>Tank Code</b>	02	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	02/06/2003	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4798	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/09/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	10/09/2025	<b>Line Tightness Test Date</b>	10/24/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/18/2025			<b>ATG Type</b>	Incon/TS-550				

<b>Tank Code</b>	03	<b>Tank Age</b>	23	<b>Tank Installed Date</b>	02/06/2003	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4799	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/09/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	10/09/2025	<b>Line Tightness Test Date</b>	10/24/2022	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	11/18/2025			<b>ATG Type</b>	Incon/TS-550				
<b>Tank Code</b>	04	<b>Tank Age</b>	14	<b>Tank Installed Date</b>	08/01/2012	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5387	<b>Spill Test Date</b>	08/30/2021	<b>Piping Installed Date</b>	08/16/2012	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	10/09/2025	<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	10/09/2025	<b>Line Tightness Test Date</b>	10/24/2022	<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	11/18/2025			<b>ATG Type</b>	Incon/TS-550				

### Facility Summary in Richland County in the City of Sidney

**Location:** ON THE RUN 80123  
902 S Central Ave  
Sidney, MT 59270-5216 Richland

System Facility ID:42-09718

**Facility Code:** 27348  
**Last Inspected On:** 08/22/2024  
**Operating Permit Renewal Date:** 12/26/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Parkland USA Corporation

jake.thomas@sunoco.com

**Operator Contact:** Jake Thomas;Parkland USA Corporation

jake.thomas@sunoco.com;jake.thomas@sunoco.com

**Owner/Operator:** Parkland USA Corporation

jake.thomas@sunoco.com

Jake Thomas, UST Class A Operator

jake.thomas@sunoco.com

Jake Thomas, UST Class B Operator

jake.thomas@sunoco.com

<b>Tank Code</b>	06	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/16/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Positive Shutoff
<b>Tag Number</b>	5595	<b>Spill Test Date</b>	08/20/2023	<b>Piping Installed Date</b>	11/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	08/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/20/2023			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	07	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/16/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Positive Shutoff
<b>Tag Number</b>	5596	<b>Spill Test Date</b>	08/20/2023	<b>Piping Installed Date</b>	11/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>	08/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/20/2023			<b>ATG Type</b>	Incon/TS-550 EVO				
<b>Tank Code</b>	08	<b>Tank Age</b>	11	<b>Tank Installed Date</b>	11/16/2015	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Positive Shutoff

<b>Tag Number</b>	5597	<b>Spill Test Date</b>	08/20/2023	<b>Piping Installed Date</b>	11/16/2015	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	08/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Secondary Pipe Detection</b>	ELLD 0.2	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	08/20/2023			<b>ATG Type</b>	Incon/TS-550 EVO				

### Facility Summary in Richland County in the City of Sidney

**Location:** SIDNEY CARDTROL  
901 3rd St NE  
Sidney, MT 59270 Richland

System Facility ID:42-02184

**Facility Code:** 27135  
**Last Inspected On:** 07/03/2025  
**Operating Permit Renewal Date:** 10/24/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Cross Petroleum Services Glendive

**cross@midrivers.com**

**Operator Contact:** Gregory Cross;Larry Garman;R J Serpe;Timothy Fife

**(406) 433-4376;(406) 698-2967**

**gcross@crosspetroleumservice.com;rlsrp@yahoo.com**

**Owner/Operator:** Cross Petroleum Services Glendive

cross@midrivers.com

Greg Cross, UST Class A Operator

gcross@crosspetroleumservice.com

Larry Garman, UST Class A Operator

Larry Garman, UST Class B Global Operator

R J Serpe, UST Class A Operator

rlsrp@yahoo.com

R J Serpe, UST Class B Global Operator

rlsrp@yahoo.com

Timothy Fife, UST Class A Operator

<b>Tank Code</b>	01	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/17/1982	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	776	<b>Spill Test Date</b>	06/27/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/27/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/03/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/27/2025	<b>Line Tightness Test Date</b>	06/27/2025	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2025			<b>ATG Type</b>	Incon/TS-1001				
<b>Tank Code</b>	02	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/17/1982	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	777	<b>Spill Test Date</b>	06/27/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/27/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/03/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/27/2025	<b>Line Tightness Test Date</b>	06/27/2025	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2025			<b>ATG Type</b>	Incon/TS-1001				

<b>Tank Code</b>	03	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/17/1982	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	778	<b>Spill Test Date</b>	06/27/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/27/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/03/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/27/2025	<b>Line Tightness Test Date</b>	06/27/2025	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2025			<b>ATG Type</b>	Incon/TS-1001				
<b>Tank Code</b>	04	<b>Tank Age</b>	44	<b>Tank Installed Date</b>	04/17/1982	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	779	<b>Spill Test Date</b>	06/27/2025	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	None	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>	06/27/2025	<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Mechanical Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Impressed Current
<b>Product</b>	Diesel, Dyed	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	07/03/2025	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	MLLD Line Tightness Testing	<b>Vapor Recovery</b>	No
<b>Capacity</b>	8000	<b>ATG Test Date</b>	06/27/2025	<b>Line Tightness Test Date</b>	06/27/2025	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/27/2025			<b>ATG Type</b>	Incon/TS-1001				

**Facility Summary in Richland County in the City of Sidney**

**Location:** SIDNEY HEALTH CENTER  
216 14th Ave SW  
Sidney, MT 59270-3519 Richland

System Facility ID:42-06159

**Facility Code:** 27255  
**Last Inspected On:** 08/22/2024  
**Operating Permit Renewal Date:** 09/14/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Sidney Health Center Inc (406) 482-2120

**Operator Contact:** Mark Delaney mdelaney@sidneyhealth.org

**Owner/Operator:** Sidney Health Center Inc (406) 482-2120

Mark Delaney, UST Class A Operator  
Mark Delaney, UST Class B Operator

mdelaney@sidneyhealth.org  
mdelaney@sidneyhealth.org

<b>Tank Code</b>	02	<b>Tank Age</b>	29	<b>Tank Installed Date</b>	09/01/1997	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	700	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Continuous Interstitial Monitoring	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>	04/19/2012	<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>	03/18/2009	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

**Facility Summary in Richland County in the City of Sidney**

**Location:** SIDNEY RICHLAND AIRPORT AUTHORITY  
355 Airport Rd  
Sidney, MT 59270-0355 Richland

System Facility ID:42-04444

**Facility Code:** 27214  
**Last Inspected On:** 01/27/2025  
**Operating Permit Renewal Date:** 01/27/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** SIDNEY RICHLAND AIRPORT (406) 480-1820

**Operator Contact:** Ryan Huotari (406) 433-2415 sdyapt@midrivers.com

**Owner/Operator:** SIDNEY RICHLAND AIRPORT (406) 480-1820

Ryan Huotari, UST Class A Operator  
Ryan Huotari, UST Class B Operator

sdyapt@midrivers.com  
sdyapt@midrivers.com

<b>Tank Code</b>	03	<b>Tank Age</b>	27	<b>Tank Installed Date</b>	04/01/1999	<b>Tank Material</b>	Steel Clad	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	3969	<b>Spill Test Date</b>	12/14/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Single Walled	<b>AST</b>	No
<b>Tank Status</b>	Temporarily Out of Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Not Required	<b>Piping Type</b>	U.S. Suction	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Aviation Gas	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Manual Interstitial Monitoring	<b>Primary Pipe Detection</b>		<b>Vapor Recovery</b>	No
<b>Capacity</b>	12000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	12/14/2021			<b>ATG Type</b>					

**Facility Summary in Richland County in the City of Sidney**

**Location:** SWELEY OIL INC BULK PLANT  
1123 10th Ave SE  
Sidney, MT 59270-6393 Richland

System Facility ID:42-00183

**Facility Code:** 27064  
**Last Inspected On:** 10/22/2024  
**Operating Permit Renewal Date:** 02/18/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Nortana Grain Co (406) 443-2580

**Operator Contact:** John Sweley;Mike Arneson (406) 482-2508;(406) 489-3589 ksweley@midrivers.com;mikenortana@outlook.com

**Owner/Operator:** Nortana Grain Co (406) 443-2580

John Sweley, UST Class A Operator  
John Sweley, UST Class B Operator  
Mike Arneson, UST Class A Operator  
Mike Arneson, UST Class B Operator

ksweley@midrivers.com  
ksweley@midrivers.com  
mikenortana@outlook.com  
mikenortana@outlook.com

<b>Tank Code</b>	S4	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	06/16/1998	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	2076	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Diesel	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	17000	<b>ATG Test Date</b>	10/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					
<b>Tank Code</b>	S5	<b>Tank Age</b>	28	<b>Tank Installed Date</b>	06/16/1998	<b>Tank Material</b>	Bare Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	
<b>Tag Number</b>	2077	<b>Spill Test Date</b>		<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	Yes
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Auto Dialer	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>		<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	17000	<b>ATG Test Date</b>	10/22/2024	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>		<b>Energy Act</b>	No
		<b>Overfill Test Date</b>				<b>ATG Type</b>					

### Facility Summary in Richland County in the City of Sidney

**Location:** TOWN PUMP OF SIDNEY #3  
12280 Hwy 200 Unit 1  
Sidney, MT 59270 Richland

System Facility ID:60-15241

**Facility Code:** 30958  
**Last Inspected On:** 09/17/2024  
**Operating Permit Renewal Date:** 07/21/2027

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Sidney 3 Town Pump LLC (406) 497-6700 environmental@townpump.com

**Operator Contact:** Trent Biggers Trentb@townpump.com

**Owner/Operator:** Sidney 3 Town Pump LLC (406) 497-6700 environmental@townpump.com

Brian Volbrecht, UST Class B Global Operator  
Trent Biggers, UST Class A Operator  
Trent Biggers, UST Class B Global Operator

bv2\_bv2@yahoo.com  
Trentb@townpump.com  
Trentb@townpump.com

<b>Tank Code</b>	01	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5471	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	02	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5472	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes

		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	03	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;Flapper Valve
<b>Tag Number</b>	5473	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	04	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	5474	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	30000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	05	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;Flapper Valve
<b>Tag Number</b>	5475	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	Yes
<b>Capacity</b>	20000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes

		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	06	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;Flapper Valve
<b>Tag Number</b>	5476	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	07	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve;Flapper Valve
<b>Tag Number</b>	5477	<b>Spill Test Date</b>	10/01/2024	<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>	08/11/2020	<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Non-corrodible
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	08/09/2022	<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	06/14/2024	<b>Line Tightness Test Date</b>	06/14/2024	<b>Secondary Tank Leak Detection</b>	Statistical Inventory Reconciliation	<b>Secondary Pipe Detection</b>	Statistical Inventory Reconciliation	<b>Energy Act</b>	Yes
		<b>Overfill Test Date</b>	10/01/2024			<b>ATG Type</b>	Gilbarco-Veeder Root/TLS-450PLUS				
<b>Tank Code</b>	08	<b>Tank Age</b>	12	<b>Tank Installed Date</b>	03/01/2014	<b>Tank Material</b>	Fiberglass Reinforced Plastic	<b>Piping Material</b>	Fiberglass Reinforced Plastic	<b>Overfill Types</b>	Ball Float Valve
<b>Tag Number</b>	5478	<b>Spill Test Date</b>		<b>Piping Installed Date</b>	03/24/2014	<b>Tank Construction</b>	Double-Walled	<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Other	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>		<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	
<b>Product</b>	DEF (Not Regulated)	<b>PLLD Test Date</b>		<b>Tank/Piping CP Test Date</b>		<b>Primary Tank Leak Detection</b>	Continuous Interstitial Monitoring	<b>Primary Pipe Detection</b>	Continuous Interstitial Monitoring;Not Listed	<b>Vapor Recovery</b>	No
<b>Capacity</b>	10000	<b>ATG Test Date</b>		<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Not Listed	<b>Energy Act</b>	No

---

	<b>Overfill Test Date</b>		<b>ATG Type</b>	Veeder Root/TLS-450PLUS			
--	---------------------------	--	-----------------	-------------------------	--	--	--

**Facility Summary in Richland County in the City of Sidney**

**Location:** WESTERN CHOICE COOPERATIVE SIDNEY  
2920 West Holly Street (Highway 16)  
Sidney, MT 59270-5221 Richland

System Facility ID:42-03364

**Facility Code:** 27176  
**Last Inspected On:** 10/22/2024  
**Operating Permit Renewal Date:** 02/11/2028

**Note: Inspection is due 90 days before the Operating Permit Renewal Date.**

**Owner Operator Contact:** Western Choice Cooperative (701) 764-6791 jreese@killdeercoop.com

**Operator Contact:** Jade Ziman;Western Choice Cooperative;Serena Ewer;Western Choice Cooperative (701) 590-0693;(701) 764-6791;(701) 764-6791 jziman@killdeercoop.com;jreese@killdeercoop.com;serewer@killdeercoop.com;jreese@killdeercoop.com

**Owner/Operator:** Western Choice Cooperative (701) 764-6791 jreese@killdeercoop.com  
 Jade Ziman, UST Class A Operator jreese@killdeercoop.com  
 Jade Ziman, UST Class B Operator jreese@killdeercoop.com  
 Serena Ewer, UST Class A Operator jreese@killdeercoop.com  
 Serena Ewer, UST Class B Operator jreese@killdeercoop.com

<b>Tank Code</b>	05	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	06/25/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	4046	<b>Spill Test Date</b>	10/22/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/21/2023	<b>Tank/Piping CP Test Date</b>	11/23/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	4000	<b>ATG Test Date</b>	11/21/2023	<b>Line Tightness Test Date</b>	04/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/22/2024			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	01	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	06/25/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	602	<b>Spill Test Date</b>	10/22/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/21/2023	<b>Tank/Piping CP Test Date</b>	11/23/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/21/2023	<b>Line Tightness Test Date</b>		<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/22/2024			<b>ATG Type</b>	Veeder Root/TLS-450PLUS				

<b>Tank Code</b>	02	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	06/25/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	603	<b>Spill Test Date</b>	10/22/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/21/2023	<b>Tank/Piping CP Test Date</b>	11/23/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/21/2023	<b>Line Tightness Test Date</b>	04/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/22/2024			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	03	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	06/25/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	604	<b>Spill Test Date</b>	12/15/2021	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Diesel	<b>PLLD Test Date</b>	11/23/2021	<b>Tank/Piping CP Test Date</b>	11/23/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	20000	<b>ATG Test Date</b>	11/23/2021	<b>Line Tightness Test Date</b>	04/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	06/14/2022			<b>ATG Type</b>	Veeder Root/TLS-450				
<b>Tank Code</b>	04	<b>Tank Age</b>	45	<b>Tank Installed Date</b>	06/25/1981	<b>Tank Material</b>	Cathodically Protected Steel	<b>Piping Material</b>	Flexible Plastic	<b>Overfill Types</b>	Flapper Valve
<b>Tag Number</b>	605	<b>Spill Test Date</b>	10/22/2024	<b>Piping Installed Date</b>		<b>Tank Construction</b>		<b>Piping Construction</b>	Double Walled	<b>AST</b>	No
<b>Tank Status</b>	Currently in Use	<b>MLLD Test Date</b>		<b>Sump Tightness Test Date</b>		<b>Catastrophic L.D Type 3.0</b>	Electronic Line Leak Detector	<b>Piping Type</b>	Pressurized	<b>CP Met Types</b>	Galvanic
<b>Product</b>	Gasoline	<b>PLLD Test Date</b>	11/21/2023	<b>Tank/Piping CP Test Date</b>	11/23/2021	<b>Primary Tank Leak Detection</b>	Automatic Tank Gauging 0.2	<b>Primary Pipe Detection</b>	ELLD 0.2	<b>Vapor Recovery</b>	No
<b>Capacity</b>	15000	<b>ATG Test Date</b>	11/21/2023	<b>Line Tightness Test Date</b>	04/08/2021	<b>Secondary Tank Leak Detection</b>		<b>Secondary Pipe Detection</b>	Continuous Interstitial Monitoring	<b>Energy Act</b>	No
		<b>Overfill Test Date</b>	10/22/2024			<b>ATG Type</b>	Veeder Root/TLS-450				