

Facility Summary in Teton County in the City of

Location: MALMSTROM AFB F 8
US Hwy 287 Rural Location
, MT Teton

Legacy ID:50-09037

Facility ID: 28881
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
307	No	09/19/2018	Double-Walled	Double Walled	Yes
Currently in Use		09/18/2018	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: BREEN OIL CARD LOCK S
505 S Main St
Choteau, MT 59422 Teton

Legacy ID:56-14147

Facility ID: 30783
Last Inspected On: 10/11/2019
Operating Permit Renewal Date: 10/15/2022

Owner Operator Contact: K B Leasing

Operator Contact: Jerold Breen;Liam Breen **4064462575**

Owner/Operator: K B Leasing

Jerold Breen, UST Class A Operator

Jerold Breen, UST Class B Operator
 Liam Breen, UST Class A Operator
 Liam Breen, UST Class B Global Operator
 Liam Breen, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S1	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm
4950	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
6,000			Gilbarco/EMC Basic		No
S2	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm
4951	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No
S3	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm
4952	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No
S4	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm

4953	Yes			Double Walled	Yes
Currently in Use		05/10/2012	Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
5,000			Gilbarco/EMC Basic		No
S5	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm
4954	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
4,000			Gilbarco/EMC Basic		No
S6	16	01/14/2005	Concrete	Flexible Plastic	High Level Alarm
4955	Yes			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
3,000			Gilbarco/EMC Basic		No

Facility Summary in Teton County in the City of Choteau

Location: DESHS TIRE AND AUTO LLC
401 Main Ave S
Choteau, MT 59422 Teton

Legacy ID:50-07565

Facility ID: 28865
Last Inspected On: 04/29/2021
Operating Permit Renewal Date:

Owner Operator Contact: Roy and Pandora Deshner

4064662066

Operator Contact: Roy Deshner

4064662066

Owner/Operator: Roy and Pandora Deshner

Roy Deshner, UST Class A Operator
Roy Deshner, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
05	29	04/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1487	No		None	Yes	
Temporarily Out of Use		Not Required	Safe Suction	Non-corrodible	
Gasoline		Automatic Tank Gauging 0.2	Deferred	No	
6,000		Gilbarco/EMC Basic		No	
06	29	04/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1488	No		None	Yes	
Temporarily Out of Use		Not Required	Safe Suction	Non-corrodible	
Diesel		Automatic Tank Gauging 0.2	Deferred	No	
4,000		Gilbarco/EMC Basic		No	

Facility Summary in Teton County in the City of Choteau

Location: KELLYS SERVICE
215 Main Ave S
Choteau, MT 59422 Teton

Legacy ID:50-03593

Facility ID: 28795
Last Inspected On: 09/12/2019
Operating Permit Renewal Date: 10/19/2022

Owner Operator Contact: Kellys Service;Timothy Kelly;Kellys Service

4064662583;4064662583;4064662583

Operator Contact: Timothy Kelly

4064662583

Owner/Operator: Kellys Service

Timothy Kelly, UST Class A Operator
Timothy Kelly, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S6	25	05/15/1996	Bare Steel	Fiberglass Reinforced Plastic	
1469	Yes	10/16/2013		Double Walled	Yes

Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	MLLD Line Tightness Testing	No
4,000		08/19/2016			No
S7	25	08/15/1996	Bare Steel	Fiberglass Reinforced Plastic	
1470	Yes	10/16/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	MLLD Line Tightness Testing	No
10,000		08/19/2016			No
S8	18	11/26/2003	Concrete	Flexible Plastic	
4929	Yes	10/16/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
10,000		08/19/2016			No
S9	18	11/26/2003	Concrete	Flexible Plastic	
4930	Yes	10/16/2013		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	Continuous Interstitial Monitoring;MLLD Line Tightness Testing	No
4,000		08/19/2016			No

Facility Summary in Teton County in the City of Choteau

Location: MAIN STREET EXPRESS LLP
222 Main Ave N
Choteau, MT 59422 Teton

Legacy ID:56-13816

Facility ID: 30503
Last Inspected On: 10/11/2019
Operating Permit Renewal Date: 11/21/2022

Owner Operator Contact: Main Street Express LLP

Operator Contact: Jerold Breen;Liam Breen;Matt Schwedhelm

4064462575;4064665863

Owner/Operator: Main Street Express LLP

Jerold Breen, UST Class A Operator
 Jerold Breen, UST Class B Operator
 John Noyd, UST Class B Operator
 Liam Breen, UST Class A Operator
 Liam Breen, UST Class B Global Operator
 Liam Breen, UST Class B Operator
 Matt Schwedhelm, UST Class A Operator
 Matt Schwedhelm, UST Class B Global Operator
 Rhonda Brewster, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	24	10/01/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
488	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
5,000			Gilbarco/EMC Basic		No
02	24	10/01/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
489	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.2	No
10,000			Gilbarco/EMC Basic		No
03	24	10/01/1997	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
490	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible

Diesel	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.2	No
5,000	Gilbarco/EMC Basic		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB F 10
US Hwy 89
Choteau, MT 59422 Teton

Legacy ID:50-09039

Facility ID: 28883
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
309	No	05/21/2018	Double-Walled	Double Walled	Yes
Currently in Use		06/19/2015	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB F 11
US Hwy 89
Choteau, MT 59422 Teton

Legacy ID:50-09040

Facility ID: 28884
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
310	No	05/21/2018	Double-Walled	Double Walled	Yes
Currently in Use		06/19/2015	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB F 2
US Hwy 89
Choteau, MT 59422 Teton

Legacy ID:50-09031

Facility ID: 28878
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected

Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	06/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
304	No	05/21/2018	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB F 3
 US Hwy 287
 Choteau, MT 59422 Teton

Legacy ID:50-09032

Facility ID: 28879
 Last Inspected On: 06/08/2021
 Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	06/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
305	No	05/21/2018	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	

Diesel	Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000	Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB F 9
US Hwy 89
Choteau, MT 59422 Teton

Legacy ID:50-09038

Facility ID: 28882
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	06/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
308	No	09/12/2018	Double-Walled	Double Walled	Yes
Currently in Use		09/11/2018	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB H 10
US Hwy 89
Choteau, MT 59422 Teton

Legacy ID:50-09061

Facility ID: 28889
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	09/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
315	No	05/17/2018	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Choteau

Location: MALMSTROM AFB H 11
Road 221
Choteau, MT 59422 Teton

Legacy ID:50-09062

Facility ID: 28890
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	09/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
316	No	05/16/2018	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Dutton

Location: DUTTON SCHOOL DIST 28
101 2nd St NE
Dutton, MT 59433-9670 Teton

Legacy ID:50-03600

Facility ID: 28797
Last Inspected On: 09/29/2020
Operating Permit Renewal Date: 08/27/2023

Owner Operator Contact: School Dist 28C Dutton Brady

Operator Contact: Clifford Suek

4064763424

Owner/Operator: School Dist 28C Dutton Brady

Clifford Suek, UST Class A Operator
Clifford Suek, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S2	32	08/21/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
842	No			None	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Heating Oil			Automatic Tank Gauging 0.2	3-Year Line Tightness Test	No

10,000

02/21/2017

EMCO Electronics/EECO 1500

No

Facility Summary in Teton County in the City of Dutton

Location: MALMSTROM AFB H 02
Road 221
Dutton, MT 59433 Teton

Legacy ID:50-09053

Facility ID: 28886
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	32	05/21/1989	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
312	No	05/16/2018	Double-Walled	Double Walled	Yes
Currently in Use		06/30/2016	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Dutton

Location: MALMSTROM AFB J 1
I-15
Dutton, MT 59433 Teton

Legacy ID:50-09074

Facility ID: 28891
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
01	59	06/02/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
317	No	05/15/2018	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Impressed Current
Diesel		04/30/2018	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Teton County in the City of Dutton

Location: MALMSTROM AFB J 11
 I-15
 Dutton, MT 59433 Teton

Legacy ID:50-09084

Facility ID: 28894
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected

Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	30	08/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
320	No	05/15/2018	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Teton County in the City of Dutton

Location: MALMSTROM AFB J 2
Road 379
Dutton, MT 59433 Teton

Legacy ID:50-09075

Facility ID: 28892
Last Inspected On: 04/06/2021
Operating Permit Renewal Date: 05/25/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	30	08/01/1991	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
318	No	05/15/2018	Double-Walled	Double Walled	Yes
Currently in Use		01/04/2016	Auto Dialer	U.S. Suction	Non-corrodible

Diesel	Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000	Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Dutton

Location: MOUNTAIN VIEW CO OP
210 N Grain Ave
Dutton, MT 59433 Teton

Legacy ID:60-15071

Facility ID: 30842
Last Inspected On: 05/04/2020
Operating Permit Renewal Date: 05/07/2023

Owner Operator Contact: Mountain View Coop Black Eagle

4064535900

Operator Contact: Judy Statham;Pat Trainor

8008233276

Owner/Operator: Mountain View Coop Black Eagle

Judy Statham, UST Class A Operator
Pat Trainor, UST Class A Operator
Pat Trainor, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5111	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
20,000			Veeder Root/TLS-350		Yes
02	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5112	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No

20,000			Veeder Root/TLS-350		Yes
03	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5113	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
20,000			Veeder Root/TLS-350		Yes
04	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5114	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
30,000			Veeder Root/TLS-350		Yes
05	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5115	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
30,000			Veeder Root/TLS-350		Yes
06	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5116	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
30,000			Veeder Root/TLS-350		Yes

07	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5117	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
40,000			Veeder Root/TLS-350		Yes
08	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5118	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector;Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
40,000			Veeder Root/TLS-350		Yes
09	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5119	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
40,000			Veeder Root/TLS-350		Yes
10	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
5120	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
40,000			Veeder Root/TLS-350		Yes
11	14	11/07/2007	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm

5121	No	08/18/2016		Double Walled	Yes
Currently in Use		01/24/2006	Continuous Interstitial Monitoring;Electronic Line Leak Detector;Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
40,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		Yes

Facility Summary in Teton County in the City of Dutton

Location: MOUNTAIN VIEW COOP DUTTON
110 Main St W
Dutton, MT 59433-9686 Teton

Legacy ID:50-03701

Facility ID: 28798
Last Inspected On: 07/11/2019
Operating Permit Renewal Date: 09/05/2022

Owner Operator Contact: Marc Freund;Mountain View Coop Dutton;Mountain View Coop Black Eagle **4064535900;4064763690**

Operator Contact: David Douglas

Owner/Operator: Mountain View Coop Black Eagle

David Douglas, UST Class A Operator
David Douglas, UST Class B Global Operator
Thomas DeMars, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
07	22	08/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
4108	No	07/28/2016		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline		07/12/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
8,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
04	31	04/16/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
4688	No	07/28/2016		Double Walled	Yes

Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		07/12/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
2,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
05	31	04/16/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
4689	No	07/28/2016		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Diesel		07/12/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
2,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
06	31	04/16/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
4690	No	07/28/2016		Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		07/12/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
2,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Teton County in the City of Fairfield

Location: GREENFIELDS IRRIGATION DISTRICT UST
105 Central Ave W
Fairfield, MT 59436 Teton

Legacy ID:50-07428

Facility ID: 28858
Last Inspected On: 04/20/2020
Operating Permit Renewal Date: 08/05/2023

Owner Operator Contact: Bob Hardin;Greenfields Irrigation District;Greenfields Irrigation District **4064672533**

Operator Contact: Russel Barrett **4064672533**

Owner/Operator: Greenfields Irrigation District

Charlie Clement, UST Class B Global Operator
Russ Barrett, UST Class A Operator
Russ Barrett, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1241	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Not Listed	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
04	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1242	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Not Listed	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Teton County in the City of Fairfield

Location: MALMSTROM AFB F 4
Road 408
Fairfield, MT 59436 Teton

Legacy ID:50-09033

Facility ID: 28880
Last Inspected On: 06/08/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	07/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
306	No	05/23/2018	Double-Walled	Double Walled	Yes
Currently in Use		11/16/2016	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Fairfield

Location: MALMSTROM AFB H 1
US Hwy 89
Fairfield, MT 59436 Teton

Legacy ID:50-09052

Facility ID: 28885
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/22/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
07	15	09/28/2006	Steel Clad	Flexible Plastic	Flapper Valve;High Level Alarm
5086	No	05/16/2018	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel		07/31/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Teton County in the City of Fairfield

Location: MALMSTROM AFB H 9
Road 408
Fairfield, MT 59436 Teton

Legacy ID:50-09060

Facility ID: 28888
Last Inspected On: 06/07/2021
Operating Permit Renewal Date: 09/30/2024

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	30	09/01/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm

314	No	05/17/2018	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Fairfield

Location: MOUNTAIN VIEW COOP FAIRFIELD
 US Hwy 89 & Central Ave
 Fairfield, MT 59436 Teton

Legacy ID:50-03596

Facility ID: 28796
Last Inspected On: 07/25/2019
Operating Permit Renewal Date: 09/27/2022

Owner Operator Contact: Marc Freund;Mountain View Coop Black Eagle;Marc Freund;Mountain View Coop Fairfield;Mountain View Coop Black Eagle;Mountain View Co-Op Fairfield

4064535900

Operator Contact: Dave Douglas

4067506748

Owner/Operator: Mountain View Coop Black Eagle

Dave Douglas, UST Class A Operator

Nathan Pitcher, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	29	12/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1235	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
6,000			Gilbarco-Veeder Root/TLS-350		No
11	29	12/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1236	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible

Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
12	29	12/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1237	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350		No
13	23	08/01/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1238	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
6,000			Gilbarco-Veeder Root/TLS-350		No
14	23	08/01/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1239	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350		No
15	23	08/01/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1240	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Teton County in the City of Fairfield

Location: MOUNTAIN VIEW COOP THE STORE
 305 Central Ave
 Fairfield, MT 59436 Teton

Legacy ID:50-11700

Facility ID: 28945
Last Inspected On: 09/04/2020
Operating Permit Renewal Date: 09/19/2023

Owner Operator Contact: Mountain View Coop Black Eagle

4064535900

Operator Contact: Charla Merja;David Douglas;Denna Lekan

4065901235

Owner/Operator: Mountain View Coop Black Eagle

Charla Merja, UST Class A Operator
 Charla Merja, UST Class B Operator
 David Douglas, UST Class A Operator
 David Douglas, UST Class B Global Operator
 Denna Lekan, UST Class A Operator
 Denna Lekan, UST Class B Operator
 Nathan Pitcher, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	31	07/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2354	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
10,000		03/01/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	31	07/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2355	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
10,000		04/01/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	31	07/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve

2356	No		None	Yes
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
10,000	04/01/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No