

Well Abandonment Form (WAF) - Facility Information

This Well Abandonment Form (WAF) is used for routine abandonment of monitoring wells that no longer needed for petroleum release investigation or cleanup, and the owner/operator does not want to retain responsibility and use of wells for other purposes. Monitoring wells, to which this WAF applies, include groundwater monitoring wells, soil vapor extraction wells, recovery wells, observation wells, sparge/injection wells, and piezometers.

Administrative Rule s of Montana (ARM) 36.21.810 sets forth the legal requirements for properly abandoning monitoring wells. ARM 36.21.810 may be found at the Links of Interest page or may be found at the following internet address:

<http://www.mtrules.org/gateway/ruleno.asp?RN=36%2E21%2E810>

Submit the WAF with your corrective action plan. Please note that incomplete and/or unsigned WAFs will be returned and may delay processing of claims submitted to the Petroleum Tank Release Compensation Board.

Facility ID Number:	42-00825
Release Number:	1141
Work Plan ID Number:	34961

Facility Name:

Blue Rock Products

Facility Address:

501 9th Avenue NE, Sidney

Owner/Operator Name:

Blue Rock Products

Owner/Operator Mailing Address:

501 9th Avenue NE, Sidney

Consultant's Name, Address, and Phone Nubmer:

Pioneer Technical Services, Inc.

List monitoring wells to be abandoned (well name and number, e.g. MW1, RSW1, etc.):

MW-1, MW-2, and MW-3

List monitoring wells to be maintained (well name and number, e.g. MW1, RSW1, etc.):

None

Specify the method by which the monitoring wells will be abandoned:

Pull casing and fill borehole with bentonite, asphalt or concrete completion in parking lot (MW-1 and MW-2) and native soil compenion in landscaped area (MW-3).

Target date for abandonment of the monitoring well(s):

Dec-24

Will the well abandonment activity be subcontracted?

Yes or No no

Unit cost per monitoring well for abandonment (include portland cement, grout or bentonite, equipment, and consultant or contractor labor costs):

Cost per Well \$468.67 /well Cost per Foot \$36.05 /ft

Total cost of abandoning the above-listed monitoring wells: \$6,300.00

I elect to maintain the monitoring wells located at the above-referenced Facility and will monitor the wells at least every three years and in accordance with applicable requirements of the Montana Department of Natural Resources & Conservation Division.

Yes or No no

I elect to abandon the monitoring wells located at the above-referenced Facility and certify that the above-referenced monitoring wells are to be properly abandoned in accordance with the provisions ARM 36.21.810 and other applicable requirements of the Montana Department of Natural Resources & Conservation Division.

Yes or No yes
Quantity of Wells

Signature of Facility owner, operator, or authorized representative:

Charlie Peterson

Date:

11/14/2024