

Facility Summary in Judith Basin County in the City of Geyser

Location: GEYSER SCHOOL DIST 58
103 3rd St E
Geyser, MT 59447-0070 Judith Basin

Legacy ID:23-03795

Facility ID: 22697
Last Inspected On: 02/16/2021
Operating Permit Renewal Date: 03/26/2024

Owner Operator Contact: N/A ZZZ - TBL_OWN : 414;School Dist 58 Geyser **4067354368**

Operator Contact: Jamie Stahl

Owner/Operator: School Dist 58 Geyser

Jamie Stahl, UST Class A Operator
Jamie Stahl, UST Class B Operator
Kenneth Annala, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	31	07/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
4609	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Deferred	No
2,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB A 3
US Hwy 87
Geyser, MT 59447 Judith Basin

Legacy ID:23-08977

Facility ID: 22771
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/25/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator

William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	10/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
223	No	06/06/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 1
 US Hwy 87
 Geyser, MT 59447 Judith Basin

Legacy ID:23-08986

Facility ID: 22772
 Last Inspected On: 05/25/2020
 Operating Permit Renewal Date: 09/25/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act

03	59	05/02/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
224	No	06/06/2017	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Impressed Current
Diesel		05/01/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 10
 US Hwy 87
 Geyser, MT 59447 Judith Basin

Legacy ID:23-08995

Facility ID: 22778
Last Inspected On: 05/24/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
230	No	06/06/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 11
US Hwy 87
Geyser, MT 59447 Judith Basin

Legacy ID:23-08996

Facility ID: 22779
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	32	06/21/1989	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
231	No	06/06/2017	Double-Walled	Double Walled	Yes
Currently in Use		06/17/2016	Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 7
US Hwy 87
Geyser, MT 59447 Judith Basin

Legacy ID:23-08992

Facility ID: 22775
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator

Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
227	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 8
 US Hwy 87
 Geyser, MT 59447 Judith Basin

Legacy ID:23-08993

Facility ID: 22776
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
03	7	01/01/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
5466	No	06/07/2017	Double-Walled	Double Walled	Yes
Currently in Use	11/25/2013	Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		Yes	

Facility Summary in Judith Basin County in the City of Geyser

Location: MALMSTROM AFB B 9
US Hwy 87
Geyser, MT 59447 Judith Basin

Legacy ID:23-08994

Facility ID: 22777
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
229	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Hobson

Location: HOBSON SCHOOL DIST 25
Central Ave
Hobson, MT 59452 Judith Basin

Legacy ID:23-05904

Facility ID: 22732
Last Inspected On: 07/28/2021
Operating Permit Renewal Date: 08/22/2024

Owner Operator Contact: John Baule;School Dist 25 Hobson;School Dist 25 Hobson
4064235483;4064235483;4064235483

Operator Contact: Parker Campbell;Hobson School Dist 25 **4064235483**

Owner/Operator: School Dist 25 Hobson

Parker Campbell, UST Class A Operator
Parker Campbell, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S3	31	08/18/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
1388	No	06/07/2018		Secondary Containment Chase	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		06/07/2018	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
10,000			Veeder Root/TLS-300		No

Facility Summary in Judith Basin County in the City of Hobson

Location: MALMSTROM AFB L 9
Road 400
Hobson, MT 59452 Judith Basin

Legacy ID:23-09104

Facility ID: 22791
Last Inspected On: 04/25/2019
Operating Permit Renewal Date: 07/31/2022

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator

William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	28	05/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
243	No	04/08/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Hobson

Location: MALMSTROM AFB M 8
 Road 400
 Hobson, MT 59452 Judith Basin

Legacy ID:23-09114

Facility ID: 22792
Last Inspected On: 04/18/2019
Operating Permit Renewal Date: 07/24/2022

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	28	05/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm

244	No	04/07/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Judith Basin County in the City of Hobson

Location: WOODHALL DISTRIBUTING
21 Sawmill Rd
Hobson, MT 59452 Judith Basin

Legacy ID:23-06450

Facility ID: 22738
Last Inspected On: 02/03/2020
Operating Permit Renewal Date: 07/10/2023

Owner Operator Contact: Mary Nan Hill;Hill Oil Co;Woodhall Distributing - Stanford

4064235343;4065662671

Operator Contact: Greg Econom

4065672266

Owner/Operator: Woodhall Distributing - Denton

Owner/Operator: Woodhall Distributing - Stanford

- Greg Econom, UST Class A Operator
- Greg Econom, UST Class B Operator
- Gloria Hungate, UST Class B Global Operator
- Greg Econom, UST Class B Operator
- Greg Econom, UST Class A Operator
- Greg Econom, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
05	23	04/01/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4745	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		05/12/2017	Automatic Tank Gauging 0.2	Deferred	No
6,000			Gilbarco/EMC Basic		No

06	23	04/01/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4746	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		05/12/2017	Automatic Tank Gauging 0.2	Deferred	No
6,000			Gilbarco/EMC Basic		No

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB C 4
US Hwy 87
Moccasin, MT 59462 Judith Basin

Legacy ID:23-09000

Facility ID: 22783
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 07/08/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
235	No	03/27/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB C 5
US Hwy 87
Moccasin, MT 59462 Judith Basin

Legacy ID:23-09001

Facility ID: 22784
Last Inspected On: 05/25/2020
Operating Permit Renewal Date: 07/22/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
236	No	03/28/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000					No

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB C 6
Road 239
Moccasin, MT 59462 Judith Basin

Legacy ID:23-09002

Facility ID: 22785
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 07/08/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator

Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
237	No	03/28/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB C 7
 Road 239
 Moccasin, MT 59462 Judith Basin

Legacy ID:23-09003

Facility ID: 22786
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 07/08/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
238	No	03/28/2017	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB M 10
US Hwy 87
Moccasin, MT 59462 Judith Basin

Legacy ID:23-09116

Facility ID: 22794
Last Inspected On: 04/18/2019
Operating Permit Renewal Date: 08/06/2022

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	28	05/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
246	No	04/04/2016	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Moccasin

Location: MALMSTROM AFB M 9
US Hwy 87
Moccasin, MT 59462 Judith Basin

Legacy ID:23-09115

Facility ID: 22793
Last Inspected On: 04/18/2019
Operating Permit Renewal Date: 07/24/2022

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	28	05/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
245	No	04/07/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Raynesford

Location: KIBBEY KORNER TRUCK STOP
US Hwy 87 & Rte 427
Raynesford, MT 59469-0197 Judith Basin

Legacy ID:23-03301

Facility ID: 22691
Last Inspected On: 04/15/2019
Operating Permit Renewal Date: 08/04/2022

Owner Operator Contact: Marc Freund;Mountain View Coop Black Eagle;Mountain View Coop Black Eagle **4064535900**

Operator Contact: David Douglas

Owner/Operator: Mountain View Coop Black Eagle

David Douglas, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
S6	25	09/01/1996	Bare Steel	Fiberglass Reinforced Plastic	
1026	Yes			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Deferred	MLLD Line Tightness Testing	No
25,000		06/22/2016			No
S7	25	09/01/1996	Bare Steel	Fiberglass Reinforced Plastic	
1027	Yes			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	MLLD Line Tightness Testing	No
8,000		06/22/2016			No
S8	25	09/01/1996	Bare Steel	Fiberglass Reinforced Plastic	
1028	Yes			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	MLLD Line Tightness Testing	No
8,000		06/22/2016			No
S9	25	09/01/1996	Bare Steel	Fiberglass Reinforced Plastic	
1029	Yes			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	

Gasoline			Deferred	MLLD Line Tightness Testing	No
10,000		06/22/2016			No
S10	25	09/01/1996	Bare Steel	Fiberglass Reinforced Plastic	
1030	Yes			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Deferred	MLLD Line Tightness Testing	No
10,000		06/22/2016			No

Facility Summary in Judith Basin County in the City of Raynesford

Location: MALMSTROM AFB A 1
US Hwy 87
Raynesford, MT 59469 Judith Basin

Legacy ID:23-08974

Facility ID: 22770
Last Inspected On: 05/25/2020
Operating Permit Renewal Date: 09/19/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- Gavin Johnson, UST Class B Global Operator
- Josi Brosam, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	59	05/02/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
222	No	05/01/2017	Lined Interior/Impressed Current	Double Walled	Yes

Currently in Use		Auto Dialer	U.S. Suction	Impressed Current
Diesel	04/01/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000		Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Judith Basin County in the City of Raynesford

Location: MALMSTROM AFB A 4
Road 427
Raynesford, MT 59469 Judith Basin

Legacy ID:20-08978

Facility ID: 22139
Last Inspected On: 05/24/2020
Operating Permit Renewal Date: 09/25/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act

02	29	06/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
221	No	06/06/2017	Double-Walled	Double Walled	Yes

Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000		Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB B 2
MT Hwy 80
Stanford, MT 59479 Judith Basin

Legacy ID:23-08987

Facility ID: 22773
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
225	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB B 3
MT Hwy 81
Stanford, MT 59479 Judith Basin

Legacy ID:14-08988

Facility ID: 20308
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator

William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	08/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
163	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB B 4
 MT Hwy 80
 Stanford, MT 59479 Judith Basin

Legacy ID:14-08989

Facility ID: 20309
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/15/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm

164	No	05/01/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB B 5
 MT Hwy 80
 Stanford, MT 59479 Judith Basin

Legacy ID:26-08990

Facility ID: 24068
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/10/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
258	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB B 6
US Hwy 87
Stanford, MT 59479 Judith Basin

Legacy ID:23-08991

Facility ID: 22774
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
226	No	06/05/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 10
US Hwy 87
Stanford, MT 59479 Judith Basin

Legacy ID:23-09006

Facility ID: 22789
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 11/27/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator

Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	4	04/01/2017	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm;Positive Shutoff
5741	No	06/27/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		Yes

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 11
 US Hwy 87
 Stanford, MT 59479 Judith Basin

Legacy ID:23-09007

Facility ID: 22790
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	10/01/1992	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve;High Level Alarm
242	No	03/29/2017	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 2
US Hwy 87
Stanford, MT 59479 Judith Basin

Legacy ID:23-08998

Facility ID: 22781
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 07/08/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status	Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types	
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
233	No	03/27/2017	Double-Walled	Double Walled	Yes
Currently in Use		Continuous Interstitial Monitoring	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 3
US Hwy 87
Stanford, MT 59479 Judith Basin

Legacy ID:23-08999

Facility ID: 22782
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 07/08/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
Candace Ellsworth, UST Class B Global Operator
Curtis Hester, UST Class A Operator
Curtis Hester, UST Class B Global Operator
William Smith, UST Class A Operator
William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/11/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
234	No	03/27/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 8
US Hwy 87
Stanford, MT 59479 Judith Basin

Legacy ID:23-09004

Facility ID: 22787
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 10/07/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith **4067316239;4067317128**

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator

Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	29	09/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
239	No	03/28/2017	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Judith Basin County in the City of Stanford

Location: MALMSTROM AFB C 9
 US Hwy 87
 Stanford, MT 59479 Judith Basin

Legacy ID:23-09005

Facility ID: 22788
Last Inspected On: 03/20/2020
Operating Permit Renewal Date: 10/07/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith	4067316239;4067317128
--	------------------------------

Owner/Operator: 341 CES CEANQ

Candace Ellsworth, UST Class A Operator
 Candace Ellsworth, UST Class B Global Operator
 Curtis Hester, UST Class A Operator
 Curtis Hester, UST Class B Global Operator
 William Smith, UST Class A Operator
 William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types

Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
02	29	10/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
240	No	03/29/2017	Double-Walled	Double Walled	Yes
Currently in Use		Auto Dialer	U.S. Suction	Non-corrodible	
Diesel		Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No	
4,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Judith Basin County in the City of Stanford

Location: STANFORD SCHOOL DIST 12
104 4th Ave S
Stanford, MT 59479 Judith Basin

Legacy ID:23-01938

Facility ID: 22680
Last Inspected On: 08/01/2019
Operating Permit Renewal Date: 10/11/2022

Owner Operator Contact: School Dist 12 Stanford

4065662265

Operator Contact: Arnold Smith

Owner/Operator: School Dist 12 Stanford

Arnold Smith, UST Class A Operator

Arnold Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
S3	23	10/09/1998	Steel Clad	Flexible Plastic	Flapper Valve
1893	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	U.S. Suction	Non-corrodible
Heating Oil			Manual Interstitial Monitoring	3-Year Line Tightness Test;Manual Interstitial Monitoring	No
8,000		07/13/2016			No

Facility Summary in Judith Basin County in the City of Stanford

Location: WOODHALL DISTRIBUTING
 219 Central Ave
 Stanford, MT 59479 Judith Basin

Legacy ID:23-03303

Facility ID: 22692
Last Inspected On: 05/23/2019
Operating Permit Renewal Date: 08/04/2022

Owner Operator Contact: Woodhall Distributing - Denton

4065672266

Operator Contact:

Owner/Operator: Woodhall Distributing - Denton

Owner/Operator: Woodhall Distributing - Stanford

- Greg Econom, UST Class A Operator
- Greg Econom, UST Class B Operator
- Gloria Hungate, UST Class B Global Operator
- Greg Econom, UST Class B Operator
- Greg Econom, UST Class A Operator
- Greg Econom, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
04	23	07/06/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1031	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Gasoline			Vapor Monitoring	Deferred	No
2,000					No
05	23	07/06/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1032	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Gasoline			Vapor Monitoring	Deferred	No
2,000					No

Facility Summary in Judith Basin County in the City of Stanford

Location: WOODY'S FUEL STOP
 36653 US Hwy 87
 Stanford, MT 59479 Judith Basin

Legacy ID:23-01526

Facility ID: 22675
Last Inspected On: 01/14/2021
Operating Permit Renewal Date: 10/23/2023

Owner Operator Contact: Dylan Woodhall;George Woodhall

4063665509;4065662671

Operator Contact: Dylan Woodhall;Shirley Woodhall

4063665509;4065662203

Owner/Operator: Dylan Woodhall

Dylan Woodhall, UST Class A Operator
 Shirley Woodhall, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
06	25	09/01/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4410	No			None	Yes
Currently in Use			Not Required	Safe Suction	
Diesel		07/19/2017	Automatic Tank Gauging 0.2	Deferred	No
5,000		09/01/2011	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
07	23	10/01/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4411	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		07/19/2017	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
10,000		09/05/2017	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
08	23	10/01/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4412	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		07/19/2017	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No

5,000

09/05/2017

Gilbarco-Veeder Root/TLS-350/Gilbarco EMC

No

Facility Summary in Judith Basin County in the City of WINDHAM

Location: MALMSTROM AFB C 1
US Hwy 87
WINDHAM, MT 59479 Judith Basin

Legacy ID:23-08997

Facility ID: 22780
Last Inspected On: 05/25/2020
Operating Permit Renewal Date: 09/26/2023

Owner Operator Contact:

Operator Contact: Candace Ellsworth;Curtis Hester;William Smith

4067316239;4067317128

Owner/Operator: 341 CES CEANQ

- Candace Ellsworth, UST Class A Operator
- Candace Ellsworth, UST Class B Global Operator
- Curtis Hester, UST Class A Operator
- Curtis Hester, UST Class B Global Operator
- William Smith, UST Class A Operator
- William Smith, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	59	05/02/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve;High Level Alarm
232	No	03/27/2017	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Impressed Current
Diesel		03/27/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No