

Facility Summary in Silver Bow County in the City of Butte

Location: ACADIA MONTANA
55 Basin Creek Rd
Butte, MT 59701-9704 Silver Bow

Legacy ID:47-00458

Facility ID: 28332
Last Inspected On: 07/29/2019
Operating Permit Renewal Date: 09/21/2022

Owner Operator Contact:

Operator Contact: Leon Huizinga;Todd Skartved **4064966329;4065604052**

Owner/Operator: Kids Behavioral Health

Bill English, UST Class B Global Operator
Leon Huizinga, UST Class A Operator
Leon Huizinga, UST Class B Operator
Todd Skartved, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	34	06/22/1987	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
3974	No	04/02/2016		Secondary Containment Chase	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	3-Year Line Tightness Test;Continuous Interstitial Monitoring	No
2,000		05/26/2016	Veeder Root/TLS-300		No

Facility Summary in Silver Bow County in the City of Butte

Location: BUTTE AVIATION INC
4602 Harrison Ave
Butte, MT 59701-6965 Silver Bow

Legacy ID:47-13713

Facility ID: 28509
Last Inspected On: 11/26/2001
Operating Permit Renewal Date:

Owner Operator Contact: Butte Aviation Inc;Eugene Hughes;Butte Aviation Inc **4064946694**

Operator Contact:

Owner/Operator: Butte Aviation Inc

Owner/Operator: Eugene F Hughes Jr

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	26	12/01/1995	Cathodically Protected Steel	Steel	
4663	No			None	Yes
Currently in Use			Not Required	Gravity Feed	Galvanic
Aviation Gas			Manual Tank Gauging	Deferred	No
100					No

Facility Summary in Silver Bow County in the City of Butte

Location: BUTTE MAIN CENTRAL OFFICE
200 W Broadway St
Butte, MT 59701-9226 Silver Bow

Legacy ID:56-14034

Facility ID: 30690
Last Inspected On: 02/28/2020
Operating Permit Renewal Date: 04/18/2023

Owner Operator Contact:

Operator Contact: Stephanie Miller

5016808141

Owner/Operator: CenturyLink Communications

Stephanie Miller, UST Class A Operator
Stephanie Miller, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	19	10/02/2002	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4732	No	10/14/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	
Diesel			Continuous Interstitial Monitoring	3-Year Line Tightness Test;Continuous Interstitial Monitoring	No

2,500

Gilbarco-Veeder Root/TLS-300

No

Facility Summary in Silver Bow County in the City of Butte

Location: BUTTE SCHOOL DIST 1 BUS BARN
1220 E Front St
Butte, MT 59701-2936 Silver Bow

Legacy ID:47-01980

Facility ID: 28355
Last Inspected On: 01/13/2020
Operating Permit Renewal Date: 01/31/2023

Owner Operator Contact: Jed Hoopes;School Dist 1 Butte;School Dist 1 Butte

Operator Contact: Jed Johnson;Leonard Diaz;Todd Skartved

4065604052

Owner/Operator: School Dist 1 Butte

- Jed Johnson, UST Class A Operator
- Jed Johnson, UST Class B Global Operator
- Leonard Diaz, UST Class A Operator
- Leonard Diaz, UST Class B Operator
- Todd Skartved, UST Class A Operator
- Todd Skartved, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
03	29	08/01/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1892	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Diesel			Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;Deferred	No
10,000			Gilbarco/EMC Basic;Gilbarco- Veeder Root/EMC Basic		No

Facility Summary in Silver Bow County in the City of Butte

Location: CENEX ZIP TRIP #72
2801 Harrison Ave
Butte, MT 59701-3715 Silver Bow

Legacy ID:47-05148

Facility ID: 28404
Last Inspected On: 11/06/2020
Operating Permit Renewal Date: 12/26/2023

Owner Operator Contact: CHS Inc Spokane Valley;Jim Alford;CHS Inc -
Spokane

5095367418

Operator Contact: Deb Morris;Jim Alford;Roy Morris;Sean Hurley

4067824255;5095357701;5095367418

Owner/Operator: CHS Inc Spokane Valley

Deb Morris, UST Class A Operator
 Deb Morris, UST Class B Operator
 Isaac Durnford, UST Class B Operator
 Jim Alford, UST Class A Operator
 Jim Alford, UST Class B Global Operator
 Karina Serrano, UST Class B Global Operator
 Roy Morris, UST Class A Operator
 Sean Hurley, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
08	31	03/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1707	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
09	31	03/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1708	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
10	31	03/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1709	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible

Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
11	31	03/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1710	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
12	31	03/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
1711	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
6,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: CENEX ZIP TRIP #73
848 W Park St
Butte, MT 59701-9066 Silver Bow

Legacy ID:47-00386

Facility ID: 28330
Last Inspected On: 05/22/2019
Operating Permit Renewal Date: 11/13/2022

Owner Operator Contact: CHS Inc Spokane Valley;Roy Morris;Morris Marketing Co Inc **4067824255**

Operator Contact: Jim Alford;Roy Morris;Sean Hurley **4067824255;5095357701;5095367418**

Owner/Operator: CHS Inc Spokane Valley

- Jim Alford, UST Class A Operator
- Jim Alford, UST Class B Global Operator
- Luci Tuttle, UST Class B Operator
- Roy Morris, UST Class A Operator
- Sean Hurley, UST Class A Operator
- Terri Stringer, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types

Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
05	23	09/01/1998	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4425	No	04/27/2016		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
06	23	09/01/1998	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4426	No	04/27/2016		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
6,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
07	23	09/01/1998	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4427	No	04/27/2016		Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
5,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: DETENTION CENTER
155 W Quartz St
Butte, MT 59701-9200 Silver Bow

Legacy ID:56-14119

Facility ID: 30760
Last Inspected On: 01/28/2020
Operating Permit Renewal Date: 05/27/2023

Owner Operator Contact:

Operator Contact: Jed Johnson; John Stajcar

4064976569

Owner/Operator: Butte Silver Bow County

Jed Johnson, UST Class A Operator
Jed Johnson, UST Class B Global Operator
John Stajcar, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	16	01/31/2005	Steel Clad	Flexible Plastic	High Level Alarm
5006	No	03/12/2014	Double-Walled	Double Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
1,000			Gilbarco-Veeder Root/TLS-300		No

Facility Summary in Silver Bow County in the City of Butte

Location: FED EX DISTRIBUTION
119771 Rick Jones Way
Butte, MT 59750 Silver Bow

Legacy ID:60-15178

Facility ID: 30904
Last Inspected On: 10/28/2020
Operating Permit Renewal Date: 04/12/2024

Owner Operator Contact:

Operator Contact: Chong Lee;Greg Peters

4067824176;4086543112

Owner/Operator: Arc Febttmt 001 LLC

Chong Lee, UST Class A Operator
Greg Peters, UST Class A Operator
Greg Peters, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	10	03/01/2011	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve;High Level Alarm
5286	No		Double-Walled	Double Walled	Yes

Currently in Use	12/20/2010	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Automatic Tank Gauging 0.2;Continuous Interstitial Monitoring	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
20,000	08/02/2017	Gilbarco-Veeder Root/TLS- 350;Gilbarco-Veeder Root/TLS- 350/Gilbarco EMC		Yes

Facility Summary in Silver Bow County in the City of Butte

Location: HOLLOW CONSTRUCTION
404 W Greenwood Ave
Butte, MT 59701-2898 Silver Bow

Legacy ID:47-05359

Facility ID: 28410
Last Inspected On: 10/15/2020
Operating Permit Renewal Date: 05/22/2024

Owner Operator Contact: Hollow Contracting

4067826033

Operator Contact: Susan Lasher

Owner/Operator: Hollow Contracting

Owner/Operator: William J Hollow

Susan Lasher, UST Class A Operator

Susan Lasher, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	21	01/01/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4162	No			Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
15,000			Gilbarco-Veeder Root/EMC Basic		No
03	21	01/01/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4163	No			Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible

Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
10,000			Gilbarco-Veeder Root/EMC Basic		No
04	21	01/01/2000	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4164	No			Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
5,000			Gilbarco-Veeder Root/EMC Basic		No

Facility Summary in Silver Bow County in the City of Butte

Location: LISACS SOUTHSIDE EXXON
2544 Harrison Ave
Butte, MT 59701 Silver Bow

Legacy ID:47-05202

Facility ID: 28406
Last Inspected On: 08/14/2020
Operating Permit Renewal Date: 08/19/2023

Owner Operator Contact: Edward Lisac

4064947056

Operator Contact: Nadene Lisac

Owner/Operator: Edward G Lisac

Owner/Operator: Edward Lisac

Nadene Lisac, UST Class A Operator

Nadene Lisac, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
06	31	03/08/1990	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
1546	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		04/28/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

07	31	03/08/1990	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
1547	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		04/28/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
08	26	06/01/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
1548	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
12,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
09	26	06/01/1995	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
1549	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
5,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: MDOT BUTTE
3751 Wynne Ave
Butte, MT 59701-6712 Silver Bow

Legacy ID:47-01062

Facility ID: 28342
Last Inspected On: 03/19/2019
Operating Permit Renewal Date: 07/14/2022

Owner Operator Contact: Doug Compton; Montana Dept of Transportation **4064447647**

Operator Contact: Jeff Gleason; Joe Radonich; Mike Murolo; Walt Kerttula

Owner/Operator: MDOT Helena

Charles Stratford, UST Class B Operator
Donald Serich, UST Class B Operator
Jeff Gleason, UST Class A Operator
Joe Radonich, UST Class A Operator
Joe Radonich, UST Class B Global Operator
Mike Murolo, UST Class A Operator

Paul Jordan, UST Class B Operator
 Roy Beckman, UST Class B Operator
 Walt Kerttula, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
08	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2937	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	Deferred	No
10,000			Gilbarco/EMC Basic		No
09	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2938	No			None	Yes
Currently in Use			Not Required	Safe Suction	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	Deferred	No
10,000			Gilbarco/EMC Basic		No

Facility Summary in Silver Bow County in the City of Butte

Location: MONTANA RESOURCES INC
 600 Shields Ave
 Butte, MT 59701-2705 Silver Bow

Legacy ID:47-13549

Facility ID: 28507
Last Inspected On: 12/29/2020
Operating Permit Renewal Date: 03/05/2024

Owner Operator Contact: Montana Resources **4067234081**

Operator Contact: Jeremy Fleege;Thomas Dale **4064988360**

Owner/Operator: Montana Resources

Daniel Lorengo, UST Class B Operator
 Jeremy Fleege, UST Class A Operator
 Jerry Frohreich, UST Class B Operator
 Jody D'Arcy, UST Class B Operator

Thomas Dale, UST Class A Operator
 Thomas Dale, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
02	24	10/01/1997	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm
1687	No	08/20/2015	Double-Walled	Double Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Gravity Feed	Non-corrodible
Oil, Waste			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
6,000			Gilbarco-Veeder Root/ILS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: NORTHWEST PETROLEUM FACILITY
 28 Dewey Blvd
 Butte, MT 59701-3195 Silver Bow

Legacy ID:56-14033

Facility ID: 30689
 Last Inspected On: 04/14/2021
 Operating Permit Renewal Date: 08/04/2024

Owner Operator Contact:

Operator Contact: Trent Biggers

Owner/Operator: Northwest Petroleum Co

Trent Biggers, UST Class A Operator
 Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4639	No	11/21/2017	Double-Walled	Double Walled	Yes

Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
02	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4640	No	11/21/2017	Double-Walled	Double Walled	Yes
Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
03	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4641	No	11/21/2017	Double-Walled	Double Walled	Yes
Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
04	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4642	No	11/21/2017	Double-Walled	Double Walled	Yes
Currently in Use		09/15/2006	Continuous Interstitial Monitoring	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
05	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4643	No	11/21/2017	Double-Walled	Double Walled	Yes

Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
06	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4644	No	11/21/2017	Double-Walled	None	Yes
Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
07	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4645	No	11/21/2017	Double-Walled	None	Yes
Currently in Use		09/15/2006	Not Required	Safe Suction	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No
08	19	04/17/2002	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4646	No	11/21/2017	Double-Walled	None	Yes
Currently in Use		09/15/2006	Not Required	Gravity Feed	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
25,000			Gilbarco-Veeder Root/TLS-450		No

Facility Summary in Silver Bow County in the City of Butte

Location: RD'S QUICK FUEL
 16 E Dewey Blvd
 Butte, MT 59701-3195 Silver Bow

Legacy ID:47-13531

Facility ID: 28506
Last Inspected On: 08/15/2019
Operating Permit Renewal Date: 12/05/2022

Owner Operator Contact: City Service Valcon LLC

Operator Contact: Jay Brookie;Roy Morris

4062524661;4067824255

Owner/Operator: City Service Valcon LLC

Jay Brookie, UST Class A Operator
 Jay Brookie, UST Class B Global Operator
 Mitchell Kilmer, UST Class B Operator
 Roy Morris, UST Class A Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1712	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
20,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1713	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
20,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1714	No			None	Yes

Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
20,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
04	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1715	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
05	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1716	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
06	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1717	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
07	27	08/01/1994	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
1718	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Automatic Tank Gauging 0.2	ELLD 0.2	No
10,000		08/20/2013	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: SILVER BOW COUNTY PUBLIC WORKS
 Browns Gulch
 Butte, MT 59701 Silver Bow

Legacy ID:47-13157

Facility ID: 28500
Last Inspected On: 01/16/2019
Operating Permit Renewal Date: 06/09/2022

Owner Operator Contact: Silver Bow County Browns Gulch Landfill

4064976521

Operator Contact: John Stajcar;Todd Skartved

4064976569;4065604052

Owner/Operator: Silver Bow County Browns Gulch Landfill

John Stajcar, UST Class A Operator
 John Stajcar, UST Class B Global Operator
 Todd Skartved, UST Class A Operator
 Todd Skartved, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
4465	No		Double-Walled	Double Walled	Yes
Currently in Use			Not Required	Safe Suction	
Diesel			Automatic Tank Gauging 0.2	Deferred	No
12,000			Gilbarco/EMC Basic		No

Facility Summary in Silver Bow County in the City of Butte

Location: ST JAMES HEALTHCARE INC
 400 S Clark St
 Butte, MT 59701-2328 Silver Bow

Legacy ID:47-06924

Facility ID: 28426
Last Inspected On: 06/21/2019
Operating Permit Renewal Date: 12/05/2022

Owner Operator Contact: St James Healthcare Inc

4067232747

Operator Contact: Keith Walsh;Thomas McKenna

4064171869;4066986391

Owner/Operator: St James Healthcare Inc

James Sullivan, UST Class B Operator
 Keith Walsh, UST Class A Operator
 Mark McGivern, UST Class B Operator

Matt Yelenich, UST Class B Operator
 Thomas McKenna, UST Class A Operator
 Thomas McKenna, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
05	20	05/01/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4449	No	10/06/2016	Double-Walled	Double Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring	No
15,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: THREE BEARS ALASKA
 45 Three Bears Dr
 Butte, MT 59701-7171 Silver Bow

Legacy ID:60-15058

Facility ID: 30832
Last Inspected On: 08/15/2019
Operating Permit Renewal Date: 01/09/2023

Owner Operator Contact: Three Bears Alaska **9078834324**

Operator Contact: Dave Goody;Lindsay Myers;Wendy Whelchel **4064947547**

Owner/Operator: Three Bears Alaska

Dave Goody, UST Class A Operator
 Dave Goody, UST Class B Operator
 Lindsay Myers, UST Class A Operator
 Lindsay Myers, UST Class B Operator
 Matt Dunne, UST Class B Global Operator
 Wendy Whelchel, UST Class A Operator
 Wendy Whelchel, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery

Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
01	14	04/24/2007	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5103	No		Double-Walled	Double Walled	Yes
Currently in Use		10/25/2006	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring; ELLD 0.2	No
17,000			Gilbarco-Veeder Root/TLS-350		No
02	14	04/24/2007	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
5104	No		Double-Walled	Double Walled	Yes
Currently in Use		10/25/2006	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Continuous Interstitial Monitoring	Continuous Interstitial Monitoring; ELLD 0.2	No
8,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: THRIFTWAY SUPER STOP 1
3501 Harrison Ave
Butte, MT 59701-3547 Silver Bow

Legacy ID:47-07932

Facility ID: 28433
Last Inspected On: 03/18/2019
Operating Permit Renewal Date: 05/06/2022

Owner Operator Contact: Sutey Oil Co Inc

4064942305

Operator Contact: Jack Hook; Linda Otonicar; Louis Sutey

4064915808; 4064942305

Owner/Operator: David L Sutey

Owner/Operator: Sutey Oil Co Inc

Cindy Beck, UST Class B Operator
Jack Hook, UST Class A Operator
Jack Hook, UST Class B Global Operator
Jack Hook, UST Class B Operator
James Brown, UST Class B Operator
Linda Otonicar, UST Class A Operator
Louis Sutey, UST Class A Operator
Louis Sutey, UST Class B Global Operator
Shelby Hart, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
-----------	-----	-----------	----------------------------	-----------------	----------------

Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
07	31	04/10/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2062	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	
Gasoline		06/02/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
14,783		06/23/2009	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
08	31	04/10/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2063	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	
Gasoline		06/02/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
11,627		06/23/2009	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
09	31	04/10/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2064	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	
Diesel		06/02/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
11,627		06/23/2009	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
10	31	04/10/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2065	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	
Diesel		06/02/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
5,929		06/23/2009	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

11	31	04/10/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2066	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Not Listed	
Diesel		06/02/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
5,929		06/23/2009	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: THRIFTWAY SUPER STOP 16
4701 Harrison Ave
Butte, MT 59701-7002 Silver Bow

Legacy ID:47-10657

Facility ID: 28486
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 07/10/2022

Owner Operator Contact: Sutey Oil Co Inc

4064942305

Operator Contact: Adriana Rigney;Jack Hook;Linda Otonicar;Louis Sutey **4064915808;4064942305;4064945703**

Owner/Operator: Sutey Oil Co Inc

Adriana Rigney, UST Class A Operator
Adriana Rigney, UST Class B Operator
Jack Hook, UST Class A Operator
Jack Hook, UST Class B Global Operator
Jack Hook, UST Class B Operator
James Brown, UST Class B Operator
Linda Otonicar, UST Class A Operator
Louis Sutey, UST Class A Operator
Mark Hodges, UST Class B Operator
William Shorter, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	34	11/01/1987	Cathodically Protected Steel	Steel	Flapper Valve
1921	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic

Diesel		07/18/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
10,000		06/03/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	34	11/01/1987	Cathodically Protected Steel	Steel	Flapper Valve
1922	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		07/18/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
10,000		06/03/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	34	11/01/1987	Cathodically Protected Steel	Steel	Flapper Valve
1923	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline		07/18/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
6,000		06/08/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
04	34	11/01/1987	Cathodically Protected Steel	Steel	Flapper Valve
1924	No			None	Yes
Currently in Use		09/14/2006	Electronic Line Leak Detector	Pressurized	Galvanic
Diesel		07/18/2016	Automatic Tank Gauging 0.2	ELLD 0.1;ELLD 0.2	No
6,000		06/08/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: THRIFTWAY SUPER STOP 2
1900 S Montana St
Butte, MT 59701-3023 Silver Bow

Legacy ID:47-07935

Facility ID: 28436
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 06/12/2022

Owner Operator Contact: Sutey Oil Co Inc

4064942305

Operator Contact: Jack Hook;Linda Otonicar;Louis Sutey

4064915808;4064942305

Owner/Operator: Sutey Oil Co Inc

Chelline Black, UST Class B Operator
Jack Hook, UST Class A Operator

Jack Hook, UST Class B Global Operator
 Jack Hook, UST Class B Operator
 Linda Otonicar, UST Class A Operator
 Louis Sutey, UST Class A Operator
 Louis Sutey, UST Class B Global Operator
 Marianne Taylor, UST Class B Global Operator
 Selena Hollins, UST Class B Operator
 Tracy Brown, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
04	32	05/15/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2070	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
11,627		04/21/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
05	32	05/15/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2071	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Diesel			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
11,627		04/21/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
06	32	05/15/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2072	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No

11,627

04/21/2016

Gilbarco-Veeder Root/TLS-
350/Gilbarco EMC

No

Facility Summary in Silver Bow County in the City of Butte**Location:** THRIFTWAY SUPER STOP 4
2610 Harrison Ave
Butte, MT 59701 Silver Bow

Legacy ID:47-07934

Facility ID: 28435
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 06/20/2022**Owner Operator Contact:** Linda Sutey;Sutey Oil Co Inc;Sutey Oil Co Inc**4064942305;4064942305;4064942305****Operator Contact:** Geoff Gifford;Jack Hook;Linda Otonicar;Louis Sutey**4064915808;4064942305;4064943155****Owner/Operator:** David L Sutey**Owner/Operator:** Sutey Oil Co IncChristopher Otonicar, UST Class B Operator
Geoff Gifford, UST Class A Operator
Geoff Gifford, UST Class B Operator
Jack Hook, UST Class A Operator
Jack Hook, UST Class B Global Operator
Jack Hook, UST Class B Operator
Kyle Wonnacott, UST Class B Operator
Linda Otonicar, UST Class A Operator
Louis Sutey, UST Class A Operator
Louis Sutey, UST Class B Global Operator
Rebecca Hook, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
05	31	03/13/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2067	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	
Gasoline			Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	No
11,627		04/20/2016	Veeder Root/TLS-300		No
06	31	03/13/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve

2068	No			None	Yes
Currently in Use				Mechanical Line Leak Detector	Pressurized
Gasoline				Automatic Tank Gauging 0.2	MLLD Line Tightness Testing
11,627		04/20/2016		Veeder Root/TLS-300	No
07	31	03/13/1990		Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic
					Ball Float Valve
2069	No			None	Yes
Currently in Use				Mechanical Line Leak Detector	Pressurized
Diesel				Automatic Tank Gauging 0.2	MLLD Line Tightness Testing
11,627		04/20/2016		Veeder Root/TLS-300	No

Facility Summary in Silver Bow County in the City of Butte

Location: THRIFTWAY SUPER STOP 5
901 E Front St
Butte, MT 59701-2929 Silver Bow

Legacy ID:47-00942

Facility ID: 28334
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 06/12/2022

Owner Operator Contact: Linda Sutey;Sutey Oil Co Inc;Sutey Oil Co Inc **4064942305;4064942305;4064942305**

Operator Contact: Jack Hook;Linda Otonicar;Louis Sutey **4064915808;4064942305**

Owner/Operator: David L Sutey

Owner/Operator: Sutey Oil Co Inc

- Allen Beagley, UST Class B Global Operator
- Allen Beagley, UST Class B Operator
- Jack Hook, UST Class A Operator
- Jack Hook, UST Class B Global Operator
- Jack Hook, UST Class B Operator
- Linda Otonicar, UST Class A Operator
- Linda Otonicar, UST Class B Operator
- Louis Sutey, UST Class A Operator
- Louis Sutey, UST Class B Global Operator
- Robert Osmanson, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types

Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
05	27	08/01/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2059	No	11/01/2016		Double Walled	Yes
Currently in Use		Electronic Line Leak Detector	Pressurized		
Gasoline		Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No	
12,000		Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No	
06	27	08/01/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2060	No	11/01/2016		Double Walled	Yes
Currently in Use		Electronic Line Leak Detector	Pressurized		
Diesel		Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No	
12,000		Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No	
07	27	08/01/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2061	No	11/01/2016		Double Walled	Yes
Currently in Use		Electronic Line Leak Detector	Pressurized		
Gasoline		Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No	
12,000		Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No	

Facility Summary in Silver Bow County in the City of Butte

Location: THRIFTWAY SUPER STOP 6
2401 Continental Dr
Butte, MT 59701-6562 Silver Bow

Legacy ID: 47-07936

Facility ID: 28437
Last Inspected On: 02/21/2019
Operating Permit Renewal Date: 02/27/2022

Owner Operator Contact: Sutey Oil Co Inc

4064942305

Operator Contact: Jack Hook; Ken Beck; Linda Otonicar; Louis Sutey

4064915808; 4064942305; 4067232022

Owner/Operator: David L Sutey

Owner/Operator: Sutey Oil Co Inc

Dean Brown, UST Class B Operator

Jack Hook, UST Class A Operator
 Jack Hook, UST Class B Global Operator
 Jack Hook, UST Class B Operator
 Jessica Willis, UST Class B Global Operator
 Ken Beck, UST Class A Operator
 Ken Beck, UST Class B Operator
 Linda Otonicar, UST Class A Operator
 Louis Sutey, UST Class A Operator
 Louis Sutey, UST Class B Global Operator
 Marianne Taylor, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	53	05/07/1968	Bare Steel	Flexible Plastic	Flapper Valve
2073	No	07/23/2014	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use		06/23/2014	Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		06/06/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
10,000		06/03/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	53	05/07/1968	Bare Steel	Flexible Plastic	Flapper Valve
2074	No	07/23/2014	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use		06/23/2014	Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		06/06/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
10,000		06/05/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	48	05/07/1973	Bare Steel	Flexible Plastic	Flapper Valve
2075	No	07/23/2014	Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use		06/23/2014	Electronic Line Leak Detector	Pressurized	Impressed Current

Diesel	06/06/2016	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring; ELLD 0.1; ELLD 0.2	No
8,000	06/18/2016	Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP BUTTE #5
2305 Continental Dr
Butte, MT 59701 Silver Bow

Legacy ID:60-15187

Facility ID: 30912
Last Inspected On: 01/06/2021
Operating Permit Renewal Date: 06/11/2024

Owner Operator Contact:

Operator Contact: Trent Biggers

Owner/Operator: Butte 5 Town Pump LLC

Owner/Operator: Town Pump Inc Northwest Missoula

Trent Biggers, UST Class A Operator

Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	10	11/01/2011	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve; Flapper Valve
5310	No		Double-Walled	Double Walled	No
Currently in Use		07/28/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Interstitial Monitoring; Statistical Inventory Reconciliation	Approved Remote Monitoring; Continuous Interstitial Monitoring; Statistical Inventory Reconciliation	Yes
20,000			Gilbarco-Veeder Root/TLS-350		Yes
02	10	11/01/2011	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve; Flapper Valve
5311	No		Double-Walled	Double Walled	No
Currently in Use		07/28/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible

Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		Yes
03	10	11/01/2011	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5312	No		Double-Walled	Double Walled	No
Currently in Use		07/28/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Yes
12,000			Gilbarco-Veeder Root/TLS-350		Yes

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 1
1370 Harrison Ave
Butte, MT 59701-4848 Silver Bow

Legacy ID:47-08679

Facility ID: 28450
Last Inspected On: 12/21/2020
Operating Permit Renewal Date: 05/31/2024

Owner Operator Contact: Don Edmisten;Town Pump

4064976948

Operator Contact: Trent Biggers

Owner/Operator: Butte 1 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
05	33	04/11/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2618	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current

Gasoline		11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No
06	35	04/11/1986	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2619	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No
07	33	04/11/1988	Cathodically Protected Steel	Flexible Plastic	Ball Float Valve
2620	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No
08	30	07/28/1991	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2621	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 10
901 N Excelsior Ave
Butte, MT 59701 Silver Bow

Legacy ID:47-08687

Facility ID: 28458
Last Inspected On: 09/11/2020
Operating Permit Renewal Date: 02/09/2024

Owner Operator Contact: Don Edmisten;Travel Plaza of Montana Inc

4064976948

Operator Contact: Trent Biggers

Owner/Operator: Butte 10 Town Pump LLC

Trent Biggers, UST Class A Operator

Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	50	04/12/1971	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
2633	No		Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-350		Yes
02	50	04/12/1971	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
2634	No		Lined Interior/Impressed Current	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
4,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 2
531 S Montana St
Butte, MT 59701 Silver Bow

Legacy ID:47-08680

Facility ID: 28451
Last Inspected On: 07/20/2021
Operating Permit Renewal Date: 10/09/2024

Owner Operator Contact:

Operator Contact: Trent Biggers

Owner/Operator: Butte 2 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	36	09/01/1985	Cathodically Protected Steel	Steel	Flapper Valve
2622	No			None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000		05/07/2006	Gilbarco-Veeder Root/TLS-350		No
02	36	09/01/1985	Cathodically Protected Steel	Steel	Flapper Valve
2623	No			None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000		05/07/2006	Gilbarco-Veeder Root/TLS-350		No
03	33	09/01/1988	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
2624	No			None	Yes
Temporarily Out of Use			Electronic Line Leak Detector	Pressurized	Impressed Current

Diesel		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
10,000		05/07/2006	Gilbarco-Veeder Root/TLS-350		No
04	0		Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
6038	No		Double-Walled	Double Walled	No
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Yes
24,000					Yes
05	0		Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
6039	No		Double-Walled	Double Walled	No
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Yes
6,000					Yes
06	0		Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	
6040	No				No
Currently in Use				Pressurized	
Gasoline					Yes
15,000					Yes
07	0		Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
6041	No		Double-Walled	Double Walled	No
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible

Diesel		Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
6,000				Yes
08	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
6042	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
15,000				Yes
09	0	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
6043	No	Double-Walled	Double Walled	No
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel, Dyed		Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
6,000				Yes

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 3
2328 S Montana St
Butte, MT 59701 Silver Bow

Legacy ID:47-08682

Facility ID: 28453
Last Inspected On: 09/11/2020
Operating Permit Renewal Date: 02/09/2024

Owner Operator Contact: Don Edmisten;Town Pump Butte 3

4064976948

Operator Contact: Trent Biggers

Owner/Operator: Butte 3 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types

Product	Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery	
Capacity	Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act	
01	40	04/11/1981	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
2625	No		None	Yes	
Currently in Use		Electronic Line Leak Detector	Pressurized	Galvanic	
Diesel	11/03/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No	
12,000		Gilbarco-Veeder Root/TLS-350		No	
04	31	10/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2626	No		None	Yes	
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible	
Gasoline	05/05/2012	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No	
12,000		Gilbarco-Veeder Root/TLS-350		No	
05	31	10/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2627	No		None	Yes	
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible	
Gasoline	05/05/2012	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No	
12,000		Gilbarco-Veeder Root/TLS-350		No	
06	31	10/01/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
2628	No		None	Yes	
Currently in Use		Electronic Line Leak Detector	Pressurized	Non-corrodible	
Gasoline	05/05/2012	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No	
12,000		Gilbarco-Veeder Root/TLS-350		No	

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 4
3700 Harrison Ave
Butte, MT 59701 Silver Bow

Legacy ID:56-13911

Facility ID: 30581
Last Inspected On: 06/30/2021
Operating Permit Renewal Date: 10/14/2024

Owner Operator Contact:

Operator Contact: Trent Biggers

Owner/Operator: Butte 4 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4022	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No
02	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4023	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-350		No
03	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve

4024	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
15,000			Gilbarco-Veeder Root/TLS-350		No
04	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve
4025	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No
05	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4026	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
6,000			Gilbarco-Veeder Root/TLS-350		No
06	22	04/01/1999	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4294	No	06/19/2018	Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
6,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Butte

Location: TOWN PUMP INC BUTTE 8
 2001 Dewey Blvd
 Butte, MT 59701 Silver Bow

Legacy ID:47-08686

Facility ID: 28457
Last Inspected On: 09/11/2020
Operating Permit Renewal Date: 02/09/2024

Owner Operator Contact: Don Edmisten;U Pump Inc

4064976948;4064976923

Operator Contact: Trent Biggers

Owner/Operator: Butte 8 Town Pump LLC

Trent Biggers, UST Class A Operator
 Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	40	10/01/1981	Cathodically Protected Steel	Steel	Flapper Valve
2629	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
30,000			Gilbarco-Veeder Root/TLS-350		No
03	44	01/01/1977	Cathodically Protected Steel	Steel	Flapper Valve
2631	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
04	40	10/01/1981	Cathodically Protected Steel	Steel	Flapper Valve
2632	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current

Diesel		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
02	40	10/01/1981	Cathodically Protected Steel	Steel	Flapper Valve
4265	No			None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		11/02/2017	Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
30,000			Gilbarco-Veeder Root/TLS-350		No

Facility Summary in Silver Bow County in the City of Melrose

Location: MELROSE BAR
120 Main St
Melrose, MT 59743 Silver Bow

Legacy ID:47-07486

Facility ID: 28431
Last Inspected On: 02/03/2021
Operating Permit Renewal Date: 03/03/2024

Owner Operator Contact: Burr Lively;Lively Inc;Melrose License Holdings LLC **4067993577;4068352721;4068352711**

Operator Contact: Lee Lively;Rebecca Mergenthaler **4067993577**

Owner/Operator: Melrose License Holdings LLC

Owner/Operator: Rebecca Mergenthaler

Lee Lively, UST Class A Operator
Lee Lively, UST Class B Operator
Rebecca Mergenthaler, UST Class A Operator
Rebecca Mergenthaler, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	38	05/08/1983	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
4054	No		Lined Interior/Impressed Current	None	Yes
Currently in Use		08/16/2011	Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		09/19/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
10,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	38	05/08/1983	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve
4055	No		Lined Interior/Impressed Current	None	Yes
Currently in Use		08/16/2011	Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		09/19/2017	Automatic Tank Gauging 0.2	Continuous Interstitial Monitoring;ELLD 0.1;ELLD 0.2	No
6,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Silver Bow County in the City of Rocker

Location: ROCKER FLYING J
 122000 N Browns Gulch Rd
 Rocker, MT 59701 Silver Bow

Legacy ID:47-09893

Facility ID: 28472
Last Inspected On: 11/02/2020
Operating Permit Renewal Date: 02/09/2024

Owner Operator Contact: Barbara Wilhelm;EnviroCap LLC;Joey Cupp;Pilot Flying J

8133413655

Operator Contact: Trent Biggers

Owner/Operator: Rocker 3 Town Pump LLC

Trent Biggers, UST Class A Operator
 Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
15	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5302	No		Double-Walled	Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
30,000		09/06/2014	Gilbarco-Veeder Root/TLS-350		Yes
16	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5303	No		Double-Walled	Double Walled	Yes
Currently in Use		08/26/2014	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
30,000		09/06/2014	Gilbarco-Veeder Root/TLS-350		Yes
17	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5304	No		Double-Walled	Double Walled	Yes

Currently in Use		08/26/2014	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
30,000		09/06/2014	Gilbarco-Veeder Root/TLS-350		Yes
18	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
5305	No		Double-Walled	Double Walled	Yes
Currently in Use		08/26/2014	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Yes
30,000			Gilbarco-Veeder Root/TLS-350		Yes
19	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5306	No		Double-Walled	Double Walled	Yes
Currently in Use		07/25/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		Yes
20	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve
5307	No		Double-Walled	Double Walled	Yes
Currently in Use		07/25/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Yes
15,000			Gilbarco-Veeder Root/TLS-350		Yes
21	9	04/12/2012	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve;Flapper Valve
5308	No		Double-Walled	Double Walled	Yes

Currently in Use	07/25/2011	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel		Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000		Gilbarco-Veeder Root/TLS-350		Yes

Facility Summary in Silver Bow County in the City of Rocker

Location: TOWN PUMP INC ROCKER
1000 Grizzly Trl
Rocker, MT 59701-9646 Silver Bow

Legacy ID:47-13173

Facility ID: 28501
Last Inspected On: 12/21/2020
Operating Permit Renewal Date: 05/31/2024

Owner Operator Contact: Don Edmisten;Town Pump of Rocker Inc

4064976948;4064976700

Operator Contact: Trent Biggers

Owner/Operator: Rocker 1 Town Pump LLC

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2635	No			Double Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
02	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2636	No			Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible

Gasoline			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
03	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2637	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Gasoline			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
04	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2638	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
05	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2639	No			None	Yes
Currently in Use		09/14/2006	Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
06	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2640	No			None	Yes
Currently in Use		09/14/2006	Mechanical Line Leak Detector	Pressurized	Non-corrodible

Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
12,000			Gilbarco-Veeder Root/TLS-350		No
07	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2641	No			None	Yes
Currently in Use		09/14/2006	Electronic Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-350		No
08	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2642	No			None	Yes
Currently in Use		09/14/2006	Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-450		No
09	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2643	No			None	Yes
Currently in Use		09/14/2006	Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-350		No
10	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2644	No			None	Yes
Currently in Use		09/14/2006	Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No

10,000			Gilbarco-Veeder Root/TLS-350		No
11	28	06/01/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2645	No			None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Statistical Inventory Reconciliation	No
10,000			Gilbarco-Veeder Root/TLS-350		No
12	22	06/01/1999	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
4103	No		Double-Walled	Double Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Non-corrodible
Diesel			Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	Approved Remote Monitoring;Continuous Interstitial Monitoring;Statistical Inventory Reconciliation	No
8,000			Gilbarco-Veeder Root/TLS-350		No