

Facility Summary in Wibaux County in the City of Wibaux

Location: FIRST and LAST CHANCE 406, LLC
107 2nd Ave NE
Wibaux, MT 59353 Wibaux

System Facility ID:55-13559

Facility Code: 29677
Last Inspected On: 01/16/2023
Operating Permit Renewal Date: 05/22/2026

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: First & Last Chance 406, LLC (406) 939-2547 clairesangha@gmail.com

Operator Contact: Tsering Sangha;First & Last Chance 406, LLC (406) 939-2547 clairesangha@gmail.com;clairesangha@gmail.com

Owner/Operator: First & Last Chance 406, LLC (406) 939-2547 clairesangha@gmail.com
Tsering Sangha, UST Class A Operator clairesangha@gmail.com
Tsering Sangha, UST Class B Operator clairesangha@gmail.com

| | | | | | | | | | | | |
|--------------------|------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|------------------------------|---------------------------------|------------------|-----------------------|---------------|
| Tank Code | 01 | Tank Age | 31 | Tank Installed Date | 11/01/1994 | Tank Material | Cathodically Protected Steel | Piping Material | Flexible Plastic | Overfill Types | Flapper Valve |
| Tag Number | 3258 | Spill Test Date | 12/06/2022 | Piping Installed Date | | Tank Construction | | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 12/06/2022 | Primary Tank Leak Detection | Automatic Tank Gauging 0.2 | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 6000 | ATG Test Date | 12/06/2022 | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 12/06/2022 | | | ATG Type | Gilbarco-Veeder Root/TLS-300 | | | | |
| Tank Code | 02 | Tank Age | 31 | Tank Installed Date | 01/01/1994 | Tank Material | Cathodically Protected Steel | Piping Material | Flexible Plastic | Overfill Types | Flapper Valve |
| Tag Number | 3259 | Spill Test Date | 12/06/2022 | Piping Installed Date | | Tank Construction | | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Diesel | PLLD Test Date | | Tank/Piping CP Test Date | 12/06/2022 | Primary Tank Leak Detection | Automatic Tank Gauging 0.2 | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | 12/06/2022 | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 12/06/2022 | | | ATG Type | Gilbarco-Veeder Root/TLS-300 | | | | |
| Tank Code | 03 | Tank Age | 31 | Tank Installed Date | 01/01/1994 | Tank Material | Cathodically Protected Steel | Piping Material | Flexible Plastic | Overfill Types | Flapper Valve |
| Tag Number | 3260 | Spill Test Date | 12/06/2022 | Piping Installed Date | | Tank Construction | | Piping Construction | None | AST | No |

| | | | | | | | | | | | |
|--------------------|------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|------------------------------|---------------------------------|------------------|-----------------------|---------------|
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 12/06/2022 | Primary Tank Leak Detection | Automatic Tank Gauging 0.2 | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 6000 | ATG Test Date | 12/06/2022 | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 12/06/2022 | | | ATG Type | Gilbarco-Veeder Root/TLS-300 | | | | |
| Tank Code | 04 | Tank Age | 31 | Tank Installed Date | 01/01/1994 | Tank Material | Cathodically Protected Steel | Piping Material | Flexible Plastic | Overfill Types | Flapper Valve |
| Tag Number | 3261 | Spill Test Date | 12/06/2022 | Piping Installed Date | | Tank Construction | | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Diesel, Dyed | PLLD Test Date | | Tank/Piping CP Test Date | 12/06/2022 | Primary Tank Leak Detection | Automatic Tank Gauging 0.2 | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | 12/06/2022 | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 12/06/2022 | | | ATG Type | Gilbarco-Veeder Root/TLS-300 | | | | |

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COOP OIL CO
203 2nd Ave NW
Wibaux, MT 59353 Wibaux

System Facility ID:55-03348

Facility Code: 29656
Last Inspected On: 07/19/2022
Operating Permit Renewal Date: 10/23/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Wibaux Coop Oil Co (406) 795-2219

Operator Contact: Donald Lauf (406) 795-2219 wibauxcoop@midrivers.com

Owner/Operator: Wibaux Coop Oil Co (406) 795-2219

Donald Lauf, UST Class A Operator
Donald Lauf, UST Class A Operator
Donald Lauf, UST Class B Operator
Donald Lauf, UST Class B Operator

wibauxcoop@midrivers.com
wibauxcoop@midrivers.com
wibauxcoop@midrivers.com
wibauxcoop@midrivers.com

| | | | | | | | | | | | |
|--------------------|------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|--------------------------------|---------------------------------|-------------------------------|-----------------------|---------------|
| Tank Code | 07 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Fiberglass Reinforced Plastic | Overfill Types | Flapper Valve |
| Tag Number | 2267 | Spill Test Date | 07/19/2022 | Piping Installed Date | 11/09/2013 | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 06/11/2013 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 5000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 08 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Fiberglass Reinforced Plastic | Overfill Types | Flapper Valve |
| Tag Number | 2268 | Spill Test Date | 07/19/2022 | Piping Installed Date | 11/09/2013 | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 06/11/2013 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 09 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Fiberglass Reinforced Plastic | Overfill Types | Flapper Valve |

| | | | | | | | | | | | |
|--------------------|------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|--------------------------------|---------------------------------|-------------------------------|-----------------------|---------------|
| Tag Number | 2269 | Spill Test Date | 07/19/2022 | Piping Installed Date | | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 06/11/2013 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 10 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Fiberglass Reinforced Plastic | Overfill Types | Flapper Valve |
| Tag Number | 2270 | Spill Test Date | 07/19/2022 | Piping Installed Date | 11/09/2013 | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Diesel | PLLD Test Date | | Tank/Piping CP Test Date | 06/11/2013 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 11 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Fiberglass Reinforced Plastic | Overfill Types | Flapper Valve |
| Tag Number | 2271 | Spill Test Date | 07/19/2022 | Piping Installed Date | 11/09/2013 | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Currently in Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Diesel, Dyed | PLLD Test Date | | Tank/Piping CP Test Date | 06/11/2013 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 4000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COUNTY UST
225 2nd Ave NW
Wibaux, MT 59353-0086 Wibaux

System Facility ID:55-02446

Facility Code: 29654
Last Inspected On: 07/19/2022
Operating Permit Renewal Date: 10/15/2025

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Wibaux County Shop

Operator Contact: Kim Bacon

(406) 796-2943

Kim Bacon, UST Class A Operator
Kim Bacon, UST Class A Operator
Kim Bacon, UST Class B Operator
Kim Bacon, UST Class B Operator

| | | | | | | | | | | | |
|--------------------|------------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|--------------------------------|---------------------------------|--------------|-----------------------|---------------|
| Tank Code | 04 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Steel | Overfill Types | Flapper Valve |
| Tag Number | 2272 | Spill Test Date | 07/19/2022 | Piping Installed Date | | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Permanently Out of Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | |
| Product | Diesel | PLLD Test Date | | Tank/Piping CP Test Date | 07/19/2022 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 8000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 05 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Steel | Overfill Types | Flapper Valve |
| Tag Number | 2273 | Spill Test Date | 07/19/2022 | Piping Installed Date | | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Permanently Out of Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | |
| Product | Gasoline | PLLD Test Date | | Tank/Piping CP Test Date | 07/19/2022 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 8000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | 07/19/2022 | | | ATG Type | | | | | |
| Tank Code | 06 | Tank Age | 30 | Tank Installed Date | 06/01/1995 | Tank Material | Steel Clad | Piping Material | Steel | Overfill Types | |

| | | | | | | | | | | | |
|--------------------|------------------------|---------------------------|------------|---------------------------------|------------|--------------------------------------|--------------------------------|---------------------------------|--------------|-----------------------|----------|
| Tag Number | 2274 | Spill Test Date | 07/19/2022 | Piping Installed Date | | Tank Construction | Double-Walled | Piping Construction | None | AST | No |
| Tank Status | Permanently Out of Use | MLLD Test Date | | Sump Tightness Test Date | | Catastrophic L.D Type 3.0 | Not Required | Piping Type | Safe Suction | CP Met Types | Galvanic |
| Product | Oil, Waste | PLLD Test Date | | Tank/Piping CP Test Date | 07/19/2022 | Primary Tank Leak Detection | Manual Interstitial Monitoring | Primary Pipe Detection | | Vapor Recovery | No |
| Capacity | 1000 | ATG Test Date | | Line Tightness Test Date | | Secondary Tank Leak Detection | | Secondary Pipe Detection | | Energy Act | No |
| | | Overfill Test Date | | | | ATG Type | | | | | |