



Service Line Locations, Septic Tank System and Test Pit Locations Approximate (not to scale)

Date: May 2, 1997

File: c:\95-101\rireport\fig_12ri.ds4

Issued with RI Report (5/2/97)



NICKLIN
EARTH & WATER, INC.

Zones of Contamination
Test Pit Locations
Buttrey Shopping Center

Figure 11