




DRAWN:	JCM	PROJECT NO.:	09208
ENGINEER:	TLS	SCALE:	AS SHOWN
CHECKED:	TLS	APPROVED:	
DATE:	12/16/09	DATE:	2/26/10




TerraGraphics
Environmental Engineering,
Inc.

**UPPER BLACKFOOT
MINING COMPLEX**

**Mike Horse Dam Toe
Test Pit Locations**

COORDINATE SYSTEM:	NAD 83 International feet
DATE:	3/2/2010
SHEET	1



DRAWN:	JCM	PROJECT NO.:	09208
ENGINEER:	TLS	SCALE:	AS SHOWN
CHECKED:	TLS	APPROVED:	
DATE:	12/16/09	DATE:	2/26/10





TerraGraphics
Environmental Engineering,
Inc.

**UPPER BLACKFOOT
MINING COMPLEX**

**Paymaster Test Pits and
Boring Locations**


COORDINATE SYSTEM:
NAD 83 International feet
DATE: 3/2/2010
SHEET 2



Drill pad roads in Shave Gulch testing area were reclaimed to DEQ's approval.

- CONTOUR
- EDGE OF DITCH
- EDGE OF NEW ROADS
- EDGE OF PAVED ROADS
- EDGE OF ROAD
- EDGE OF STREAM
- EXISTING BUILDING
- FAULTS
- HEAVY TREE COVER
- INDEX CONTOUR
- MONITORING WELL
- NEW BOREHOLE
- PROPERTY BOUNDARY
- PROPOSED REPOSITORY LOCATION
- ROCK OUTCROP
- SWAMP
- TANK
- TEST PIT
- VEINS
- WATER
- ABANDONED MINE WORKINGS

DRAWN:	JCM	PROJECT NO.:	09208		TerraGraphics Environmental Engineering, Inc.	UPPER BLACKFOOT MINING COMPLEX	Shave Gulch Test Pits and Boring Locations	COORDINATE SYSTEM:	
ENGINEER:	TLS	SCALE:	AS SHOWN					NAD 83 International feet	
CHECKED:	TLS	APPROVED:						DATE:	
DATE:	12/16/09	DATE:	2/26/10					3/2/2010	
								SHEET 3	



DRAWN:	JCM	PROJECT NO.:	09208
ENGINEER:	TLS	SCALE:	AS SHOWN
CHECKED:	TLS	APPROVED:	
DATE:	12/16/09	DATE:	2/26/10




TerraGraphics
Environmental Engineering,
Inc.

**UPPER BLACKFOOT
MINING COMPLEX**

**Mike Horse Creek Road
Test Pit Locations**

COORDINATE SYSTEM:	NAD 83 International feet
DATE:	11/23/09
SHEET	4



DRAWN:	JCM	PROJECT NO.:	09208
ENGINEER:	TLS	SCALE:	AS SHOWN
CHECKED:	TLS	APPROVED:	
DATE:	12/16/09	DATE:	2/26/10




TerraGraphics
Environmental Engineering,
Inc.


**UPPER BLACKFOOT
MINING COMPLEX**

**Hazard Site Map
(1 of 2)**

COORDINATE SYSTEM:	NAD 83 International feet
DATE:	11/23/09
SHEET	5



Drift under Blackfoot R. reported, by G. Kovic, to have collapsed during construction of the WTP



- CONTOUR
- EDGE OF DITCH
- EDGE OF NEW ROADS
- EDGE OF PAVED ROADS
- EDGE OF ROAD
- EDGE OF STREAM
- EXISTING BUILDING
- FAULTS
- HEAVY TREE COVER
- INDEX CONTOUR
- MONITORING WELL
- NEW BOREHOLE
- PHOTO NUMBER AND DIRECTION
- PROPERTY BOUNDARY
- PROPOSED REPOSITORY LOCATION
- ROCK OUTCROP
- SWAMP
- TANK
- TEST PIT
- VEINS
- WATER
- ABANDONED MINE WORKINGS

DRAWN:	JCM	PROJECT NO.:	09208
ENGINEER:	TLS	SCALE:	AS SHOWN
CHECKED:	TLS	APPROVED:	
DATE:	12/16/09	DATE:	2/26/10



TerraGraphics
Environmental Engineering,
Inc.

**UPPER BLACKFOOT
MINING COMPLEX**

**Hazards Site Map
(2 of 2)**

COORDINATE SYSTEM:	NAD 83 International feet
DATE:	11/23/09
SHEET 6	