

Facility Summary in Wibaux County in the City of Wibaux

Location: AMSLER C STORE
107 2nd Ave NE
Wibaux, MT 59353 Wibaux

Legacy ID:55-13559

Facility ID: 29677
Last Inspected On: 01/14/2020
Operating Permit Renewal Date: 05/22/2023

Owner Operator Contact: Amsler C Store

4067962338

Operator Contact: Ernest Amsler

4067962338

Owner/Operator: Amsler C Store

Ernest Amsler, UST Class A Operator

Ernest Amsler, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
01	27	11/01/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
3258	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		03/23/2017	Automatic Tank Gauging 0.2	Deferred	No
6,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
02	27	01/01/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
3259	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		03/23/2017	Automatic Tank Gauging 0.2	Deferred	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
03	27	01/01/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
3260	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic

Gasoline		03/23/2017	Automatic Tank Gauging 0.2	Deferred	No
6,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No
04	27	01/01/1994	Cathodically Protected Steel	Flexible Plastic	Flapper Valve
3261	No			None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Diesel		03/23/2017	Automatic Tank Gauging 0.2	Deferred	No
4,000			Gilbarco-Veeder Root/TLS-350/Gilbarco EMC		No

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COOP OIL CO
203 2nd Ave NW
Wibaux, MT 59353 Wibaux

Legacy ID:55-03348

Facility ID: 29656
Last Inspected On: 07/08/2019
Operating Permit Renewal Date: 10/23/2022

Owner Operator Contact: Donald Lauf;Wibaux Coop Oil Co;Wibaux Coop Oil Co **4067952219;4067952219;4067952219**

Operator Contact: Donald Lauf

4067952219

Owner/Operator: Wibaux Coop Oil Co

Donald Lauf, UST Class A Operator
Donald Lauf, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
07	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
2267	No		Double-Walled	None	Yes
Currently in Use		11/09/2013	Not Required	Safe Suction	Galvanic
Gasoline		06/11/2013	Manual Interstitial Monitoring	Deferred	No
5,000					No
08	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve

2268	No		Double-Walled	None	Yes
Currently in Use		11/09/2013	Not Required	Safe Suction	Galvanic
Gasoline		06/11/2013	Manual Interstitial Monitoring	Deferred	No
4,000					No
09	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
2269	No		Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		06/11/2013	Manual Interstitial Monitoring	Deferred	No
4,000					No
10	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
2270	No		Double-Walled	None	Yes
Currently in Use		11/09/2013	Not Required	Safe Suction	Galvanic
Diesel		06/11/2013	Manual Interstitial Monitoring	Deferred	No
4,000					No
11	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
2271	No		Double-Walled	None	Yes
Currently in Use		11/09/2013	Not Required	Safe Suction	Galvanic
Diesel		06/11/2013	Manual Interstitial Monitoring	Deferred	No
4,000					No

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COOP OIL CO BULK PLANT #3049
400 1st Ave SE
Wibaux, MT 59353 Wibaux

Legacy ID:

Facility ID: 31131
Last Inspected On:
Operating Permit Renewal Date:

Owner Operator Contact: Donald Lauf;Wibaux Coop Oil Co

4067952219;4067952219

Operator Contact:

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
10	26	06/01/1995	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve
2270	No		Double-Walled	None	Yes
Currently in Use		11/09/2013	Not Required	Safe Suction	Galvanic
Diesel		06/11/2013	Manual Interstitial Monitoring	Deferred	No
4,000					No

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COUNTY UST
225 2nd Ave NW
Wibaux, MT 59353-0086 Wibaux

Legacy ID:55-02446

Facility ID: 29654
Last Inspected On: 07/08/2019
Operating Permit Renewal Date: 10/15/2022

Owner Operator Contact: N/A ZZZ - TBL_OWN : 1130;Wibaux County Shop;Wibaux County Shop

Operator Contact: Kim Bacon

4067962943

Owner/Operator: Wibaux County Shop

Kim Bacon, UST Class A Operator
Kim Bacon, UST Class B Operator

Tank Code	Age	Installed	Tank Material Construction	Piping Material	Overfill Types
Tag #	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Piping Installed Date	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
04	26	06/01/1995	Steel Clad	Steel	Flapper Valve
2272	No		Double-Walled	None	Yes

Currently in Use			Not Required	Safe Suction	
Diesel		07/13/2016	Manual Interstitial Monitoring	Deferred	No
4,000					No
05	26	06/01/1995	Steel Clad	Steel	Flapper Valve
2273	No		Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	
Gasoline		07/13/2016	Manual Interstitial Monitoring	Deferred	No
4,000					No
06	26	06/01/1995	Steel Clad	Steel	
2274	No		Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Oil, Waste		07/13/2016	Manual Interstitial Monitoring	Deferred	No
500					No