

Facility Summary in Wibaux County in the City of Wibaux

Location: FIRST and LAST CHANCE 406 LLC
107 2nd Ave NE
Wibaux, MT 59353 Wibaux

System Facility ID:55-13559

Facility Code: 29677
Last Inspected On: 01/30/2026
Operating Permit Renewal Date: 05/22/2029

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: First and Last Chance 406 LLC (406) 939-2547 firstlastchance406@gmail.com

Operator Contact: Tsering Sangha;First and Last Chance 406 LLC (406) 939-2547 clairesangha@gmail.com;firstlastchance406@gmail.com

Owner/Operator: First and Last Chance 406 LLC (406) 939-2547 firstlastchance406@gmail.com
Tsering Sangha, UST Class A Operator firstlastchance406@gmail.com
Tsering Sangha, UST Class B Operator firstlastchance406@gmail.com

Tank Code	01	Tank Age	32	Tank Installed Date	11/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3258	Spill Test Date	01/30/2026	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	01/30/2026	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	6000	ATG Test Date	01/30/2026	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	01/30/2026			ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	02	Tank Age	32	Tank Installed Date	01/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3259	Spill Test Date	01/30/2026	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	01/30/2026	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date	01/30/2026	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	01/30/2026			ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	03	Tank Age	32	Tank Installed Date	01/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3260	Spill Test Date	01/30/2026	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No

Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	01/30/2026	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	6000	ATG Test Date	01/30/2026	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	01/30/2026			ATG Type	Gilbarco-Veeder Root/TLS-300				
Tank Code	04	Tank Age	32	Tank Installed Date	01/01/1994	Tank Material	Cathodically Protected Steel	Piping Material	Flexible Plastic	Overfill Types	Flapper Valve
Tag Number	3261	Spill Test Date	01/30/2026	Piping Installed Date		Tank Construction		Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date	01/30/2026	Primary Tank Leak Detection	Automatic Tank Gauging 0.2	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date	01/30/2026	Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	01/30/2026			ATG Type	Gilbarco-Veeder Root/TLS-300				

Facility Summary in Wibaux County in the City of Wibaux

Location: WIBAUX COOP OIL CO
203 2nd Ave NW
Wibaux, MT 59353 Wibaux

System Facility ID:55-03348

Facility Code: 29656
Last Inspected On: 07/24/2025
Operating Permit Renewal Date: 10/23/2028

Note: Inspection is due 90 days before the Operating Permit Renewal Date.

Owner Operator Contact: Wibaux Coop Oil Co (406) 795-2219

Operator Contact: David Birnel;Wibaux Coop Oil Co;Donald Lauf (406) 795-2219 wibauxcoop@midrivers.com

Owner/Operator: Wibaux Coop Oil Co (406) 795-2219

David Birnel, UST Class A Operator
David Birnel, UST Class B Operator
Donald Lauf, UST Class A Operator
Donald Lauf, UST Class B Operator

wibauxcoop@midrivers.com
wibauxcoop@midrivers.com

Tank Code	07	Tank Age	31	Tank Installed Date	06/01/1995	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2267	Spill Test Date	07/24/2025	Piping Installed Date	11/09/2013	Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/11/2013	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	5000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/24/2025			ATG Type					
Tank Code	08	Tank Age	31	Tank Installed Date	06/01/1995	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2268	Spill Test Date	07/24/2025	Piping Installed Date	11/09/2013	Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/11/2013	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/24/2025			ATG Type					
Tank Code	09	Tank Age	31	Tank Installed Date	06/01/1995	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve

Tag Number	2269	Spill Test Date	07/24/2025	Piping Installed Date		Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Gasoline	PLLD Test Date		Tank/Piping CP Test Date	06/11/2013	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/24/2025			ATG Type					
Tank Code	10	Tank Age	31	Tank Installed Date	06/01/1995	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2270	Spill Test Date	07/24/2025	Piping Installed Date	11/09/2013	Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel	PLLD Test Date		Tank/Piping CP Test Date	06/11/2013	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/24/2025			ATG Type					
Tank Code	11	Tank Age	31	Tank Installed Date	06/01/1995	Tank Material	Steel Clad	Piping Material	Fiberglass Reinforced Plastic	Overfill Types	Flapper Valve
Tag Number	2271	Spill Test Date	07/24/2025	Piping Installed Date	11/09/2013	Tank Construction	Double-Walled	Piping Construction	None	AST	No
Tank Status	Currently in Use	MLLD Test Date		Sump Tightness Test Date		Catastrophic L.D Type 3.0	Not Required	Piping Type	Safe Suction	CP Met Types	Galvanic
Product	Diesel, Dyed	PLLD Test Date		Tank/Piping CP Test Date	06/11/2013	Primary Tank Leak Detection	Manual Interstitial Monitoring	Primary Pipe Detection		Vapor Recovery	No
Capacity	4000	ATG Test Date		Line Tightness Test Date		Secondary Tank Leak Detection		Secondary Pipe Detection		Energy Act	No
		Overfill Test Date	07/24/2025			ATG Type					